

MINERS BAY DOCK FACILITY

CONDITION ASSESSMENT REPORT

Prepared for:

Capital Regional District

479 Island Highway

Victoria, BC V9B 1H7

FINAL

Prepared by:



moffatt & nichol

777 W. Broadway, Suite 301

Vancouver, BC V5Z 4J7

December 11, 2015

MINERS BAY DOCK FACILITY

CONDITION ASSESSMENT REPORT

FINAL

December 11, 2015

M&N Project No. 8985 VC15

Prepared by:

MOFFATT & NICHOL

James Traber, EIT

Staff Engineer

Reviewed by:

MOFFATT & NICHOL

Paul Hoo, P.Eng

Senior Project Manager

Revision	Purpose of Issue	Date	Author	Reviewed	Approved
C	Final Report	December 11, 2015	JT	PH	PH
B	Final Draft Report	November 06, 2015	JT	PH	PH
A	Draft Report	September 20, 2015	JT	PH	PH

TABLE OF CONTENTS

1	INTRODUCTION	1
1.1	PURPOSE OF INSPECTION	1
2	SCOPE OF WORK.....	1
2.1	REFERENCE MATERIALS	2
2.1.1	Reports.....	2
3	FACILITY DESCRIPTION.....	4
3.1	APPROACH/WHARFHEAD	4
3.2	FLOATS.....	4
3.3	GANGWAYS.....	4
3.4	SERVICES	4
4	INSPECTION RESULTS.....	6
4.1	APPROACH/WHARFHEAD	6
4.1.1	Topsides	6
4.1.2	Abutment	6
4.1.3	Pile Caps.....	6
4.1.4	Stringers.....	6
4.1.5	Bearing Piles	7
4.2	FLOATS.....	8
4.2.1	Float A.....	8
4.2.2	Float B	9
4.2.3	Float C.....	10
4.2.4	Float D.....	11
4.3	GANGWAY	12
4.3.1	Gangway A to Float A	12
4.3.2	Gangway B to Float B and C	12
4.4	SERVICES	13
4.5	REVIEW OF OPERATIONAL, STRUCTURAL, AND MAINTENANCE ISSUES.....	13
5	RESIDUAL LIFE ESTIMATES	14
5.1	APPROACH/WHARFHEAD	14
5.2	FLOAT A	14
5.3	FLOAT B	14
5.4	FLOAT C	15
5.5	FLOAT D.....	15
5.6	GANGWAY	15
5.7	SERVICES	15
6	COST ESTIMATES OF REPAIRS	15
7	RISK, STRATEGIES, AND POLICY ADAPTATION.....	17
8	CONCLUSIONS AND RECOMMENDATIONS.....	17

APPENDIX A: PHOTOGRAPHS.....	A
APPENDIX B: OPINION OF PROBABLE REPAIR/REPLACEMENT COSTS	B
APPENDIX C: UNDERWATER INSPECTION REPORT	C

TABLE OF FIGURES

Figure 1: Site Plan	5
---------------------------	---

TABLE OF TABLES

Table 1: Topside Defects.....	6
Table 2: Abutment Defects	6
Table 3: Pile Caps Defects	6
Table 4: Stringer Defects	7
Table 5: Bearing Pile Defects	7
Table 6: Float A Defects	8
Table 7: Float B Defects	9
Table 8: Float C Defects	11
Table 9: Float D Defects	12
Table 10: Gangway A Defects	12
Table 11: Gangway B Defects	13
Table 12: Services Defects	13
Table 13: Cost Estimate	16

TABLE OF PHOTOGRAPHS

Photograph 1: General Layout.....	1
Photograph 2: Topside	1
Photograph 3: General Condition of Approach	2
Photograph 4: General Condition of Wharfhead.....	2
Photograph 5: Deck Rot at Bent 17	3
Photograph 6: Deck Rot at Bent 22	3
Photograph 7: Deck at Bent 23.....	4

Photograph 8: Deck at Bent 25.....	4
Photograph 9: Deck Rot between Bent 29 to 30	5
Photograph 10: Deck Rot at Bent 31	6
Photograph 11: Deck Rot between Bent 31 to 32	7
Photograph 12: Deck Rot at Bent 32	8
Photograph 13: Deck Rot at Bent 33	9
Photograph 14: Deck Rot at Bent 37	10
Photograph 15: Deck Rot at Bent 37	11
Photograph 16: Deck Rot at Bent 37	12
Photograph 17: Deck Rot at Bent 39	13
Photograph 18: Deck Rot at Bent 40	13
Photograph 19: Deck Rot and Hole Patch at Bent 40 and Cleat	14
Photograph 20: Deck Rot at Patches	14
Photograph 21: Warped Handrail at Bent 19	15
Photograph 22: Abutment.....	16
Photograph 23: Abutment.....	17
Photograph 24: Abutment.....	17
Photograph 25: Pile Caps	18
Photograph 26: Pile Cap Split at Bent 25	18
Photograph 27: Burnt Stingers between Bent 24 to 29	19
Photograph 28: Burnt Stingers between Bent 24 to 29	19
Photograph 29: Typical Approach Bent	20
Photograph 30: Concrete Spall at Pile 5C	21
Photograph 31: Gouge in Pile 8A.....	22
Photograph 32: Pile 18B Hole and Severe Marine Borer Damage	23
Photograph 33: Pile 21B Hole	23
Photograph 34: Cracking in Pile 24B.....	24
Photograph 35: Broken Bracing Bent 25	25
Photograph 36: Cracking in Pile 28B1.....	26
Photograph 37: Typical Wharfhead Pile Layout	27
Photograph 38: Typical Wharfhead Pile Layout	27
Photograph 39: Typical Wharfhead Pile Layout	28
Photograph 40: Pile 38H Batter Severe Marine Borer Damage.....	28
Photograph 41: Fender Piles	29
Photograph 42: Fender Piles	29
Photograph 43: Fender Face	30
Photograph 44: Pile 40A Batter Severe Marine Borer Damage.....	30
Photograph 45: Pile 39A Severe Marine Borer Damage.....	31
Photograph 46: Pile 38A Batter Severe Marine Borer Damage.....	32
Photograph 47: Float A General Condition.....	33
Photograph 48: Float A General Condition.....	34
Photograph 49: Float A Decking	34
Photograph 50: Float A Bull Rail and Rub Rail	35
Photograph 51: Float A Bull Rail	36
Photograph 52: Typical Pile Well Condition	37

Photograph 53: Guide Pile Abrasion.....	38
Photograph 54: Float B Condition	39
Photograph 55: Float B Deck Condition.....	40
Photograph 56: Float B Bull Rail and Rub Rail	41
Photograph 57: Float B Deck Worn out due to transition plate.....	41
Photograph 58: Float B Alignment Line	42
Photograph 59: Float B missing Bull Rail and Deck Board	43
Photograph 60: Connection between Float B and C	44
Photograph 61: Connection between Float B and C	44
Photograph 62: Float C.....	45
Photograph 63: Float C	45
Photograph 64: Float C Deck	46
Photograph 65: Float C Deck	46
Photograph 66: Float C Rub Board	47
Photograph 67: Connection between Float C and D	47
Photograph 68: Connection between Float C and D	48
Photograph 69: Float D.....	49
Photograph 70: Float D.....	50
Photograph 71: Float D Rub Rail.....	51
Photograph 72: Float D Rub Rail and Bull Rail	52
Photograph 73: Gangway A	53
Photograph 74: Gangway A	54
Photograph 75: Float A.....	55
Photograph 76: Gangway A	56
Photograph 77: Gangway A Guide Rails and Roller	57
Photograph 78: Gangway A Roller	57
Photograph 79: Gangway A Roller	58
Photograph 80: Gangway B	58
Photograph 81: Gangway B Hanger Support.....	59
Photograph 82: Gangway B	60
Photograph 83: Gangway B Broken Support	60
Photograph 84: Gangway B Broken Brace.....	61
Photograph 85: Gangway B	61
Photograph 86: Gangway B	62
Photograph 87: Gangway B Roller	63
Photograph 88: Electrical Services.....	64
Photograph 89: Lamp Standard at Bent 3	65
Photograph 90: Lamp Standard at Bent 3	66
Photograph 91: Broken Electrical Wire at Bent 16	67
Photograph 92: Lamp Standard at Bent 16	68
Photograph 93: Lamp Standard at Bent 16	69
Photograph 94: Lamp Standard at Bent 16	70
Photograph 95: Lamp Standard at Bent 28	71
Photograph 96: Lamp Standard at Bent 28	71
Photograph 97: Lamp Standard at Bent 28	72

Photograph 98: Lamp Standard at Bent 37 Pile F	73
Photograph 99: Electrical Services to Float A	74
Photograph 100: Lamp Standard on Float A.....	75
Photograph 101: Electrical Services to Float B	76
Photograph 102: Electrical Services to Float C	77
Photograph 103: Lamp Standard on Float C.....	78
Photograph 104: Lamp Standard on Float C.....	79
Photograph 105: Decommissioned Fuel Lines.....	80
Photograph 106: Decommissioned Fuel Lines.....	81

1 INTRODUCTION

Facility: Miners Bay Dock

Inspected by:

Moffatt & Nichol

James Traber, E.I.T

Engineer-Diver

All-Sea Underwater Solutions

Lance Hiney

Dive Supervisor

Inspection Date: August 13, 2015

1.1 PURPOSE OF INSPECTION

The purpose of the inspection is to assess the current condition of Capital Regional District's Miners Bay facility and determine the structural defects and improvements required for the facility to continue to be used safely.

2 SCOPE OF WORK

Moffatt & Nichol (M&N) was retained by Capital Regional District (CRD) to provide a condition assessment for their Miners Bay facility located on the North side of Mayne Island. The condition assessment follows the requirement delineated in the ASCE Manual and Reports on Engineering Practice No. 101, Underwater Investigations Standard Practice Manual (ASCE, 2001) and Procedures for Inspecting and Assessment of Fixed Timber Docks (Sexsmith, 1994).

ASCE 101 describes the types of inspections and specific structure considerations depending on objective, frequency of inspection and the level of damage. Three basic levels of inspection are used for inspecting marine facilities. The type and extent of damage/deterioration that can be detected depends on the level of inspection performed. The following general descriptions for Levels I through III comply with the ASCE 101. Refer to Appendix B for the inspection level descriptions. A level I inspection was performed on this facility.

Individual components are categorized into six condition ratings: not inspected, no damage, minor, moderate, major, and severe. Each component condition rating is defined in Appendix B.

Work by M&N include, but not be limited to the following:



1. Project initiation meeting with CRD and M&N
2. Review of existing facility documentation provided to M&N by CRD
3. Conduct a visual above water (M&N) and underwater inspection (All-Sea) of the facility reviewing the following structural components:
 - Abutment, access trestle, wharf, gangways, and floats;
 - Piles, pile caps, braces, stringers, decking, bull rails, handrails, rub boards, and anchorage systems;
 - Attenuation components and breakwaters;
 - Ancillary equipment including electrical systems, fuel dispensing equipment, and lifting devices; and,
 - Decommissioned works including fuel.
4. Produce an engineering condition assessment report, identifying any structural defects
5. Identify all repair work required at the facility
6. Provide a Class C budget estimate for required repair work
7. Estimation of remaining service life of dock and components

2.1 REFERENCE MATERIALS

CRD provided M&N with the following documents.

2.1.1 Reports

The following documents were provided as reference materials prior to the inspection:

- “Miners Bay Wharf, Mayne Island Inspection Report” dated May 27, 2008 by Hugh Tuttle Engineering.
- “SGIHC - Miners Bay Bracing and Decking Jobsite Inspection Notes” dated May 25, 2009 by Hugh Tuttle Engineering.
- “Miners Bay Dock Inspection” dated May 8, 2009 by Mainroad South Island Contracting.
- “Miners Bay - Float Anchoring Assessment” dated July 17, 2007 by ___?
- “Site Visit Inspection Report” dated January 8, 2007 by Mainroad South Island Contracting Ltd.



- “Miners Bay Wharf, Mayne Island Site Inspection Report” dated August 1, 2007 by Hugh Tuttle Engineering.
- “SGIHA_Letter and Inspection Reports”, dated September 12, 2005, by North Island Engineering.
- Pile Diving Record, August 11-12, 2005, from North Island Engineering.
- “SGIHC - Miners Bay Wharf Inspection” 1st Edition, dated September 3, 2003, by North Island Engineering.
- Outer Gulf Island Harbours Commission “Miners Bay Dock Inspection”, dated August 20, 2001 by Pacific Marine Construction.
- Outer Gulf Islands Harbours Commission “Miners Bay Dock - Risk Assessment”, dated March 2001 by EmergPro.
- Transport Canada “Phase 1 Environmental Site Assessment, Miners Bay, Mayne Island, BC” dated August 1996 by Castor Consultants.
- Transport Canada “Underwater Inspection of Fixed Timber Wharfs, Miners Bay, Mayne Island, BC” Final Report, dated May 19, 1998 by SNC♦LAVALIN
- Transport Canada “Miners Bay (Mayne Island) Wharf and Float Inspection” 1st Edition dated August 9, 1996 by North Island Engineering Ltd.



3 FACILITY DESCRIPTION

The facility is comprised of an approach and four floats connected via two gangways. The approach is timber piles supporting timber pile caps and deck. The floats are of typical timber construction and is anchored in place by timber piles and chain anchors.

3.1 APPROACH/WHARFHEAD

The approach and wharfhead consists of timber piles supporting timber pile caps, stringers and decking. Both sides on the approach have timber handrails and bull rails.

Handrails	2" x 6" top rails with 2" x 4" mid rail and 4" x 4" posts every 8ft
Bull Rails	8" x 10" with 1.5" riser
Decking	4" x 12" spanning 20"
Pile Caps	12" x 14"
Braces	6" x 8"

3.2 FLOATS

There are four timber floats at the terminal. Float A is located on the south side of the wharfhead and Floats B, C, and D is located on the east side of the wharfhead.

Bull Rails	4" x 6" with 4" Riser
Decking	2" x 12"
Rub-Boards	2" x 12"

3.3 GANGWAYS

The gangways are painted steel with a wooden deck.

3.4 SERVICES

There are six LED lamp standards at the facility servicing the approach, wharfhead, and floats.






Figure 1: Site Plan

4 INSPECTION RESULTS

The general condition from the above and underwater inspection are reported below.

4.1 APPROACH/WHARFHEAD

4.1.1 Topsides

The timber topsides are in poor condition. The approach and wharfhead have multiple boards that are weathered and starting to rot.

Table 1: Topside Defects

Location	Damage/Condition	Comments	Recommendations
Handrails and bull rails	Weathered, need to be cleaned and painted		Monitor
Decking	Weathered and starting to rot		Monitor
Wharfhead	Severe rot in decking boards and holes near berth face	Photographs 5 to 20	Repair
Wharfhead	Cleat supports at end of wharfhead are deteriorating	Photograph 18 to 19	Repair

4.1.2 Abutment

The abutment is in good condition with no notable defects.

Table 2: Abutment Defects

Location	Damage/Condition	Comments	Recommendations
Abutment		Photographs 22 to 24	

4.1.3 Pile Caps

The pile caps are in good condition.

Table 3: Pile Caps Defects

Location	Damage/Condition	Comments	Recommendations
Bent 25	Split Pile Cap	Photograph 26	Monitor

4.1.4 Stringers

The stringers are in good condition.

Table 4: Stringer Defects

Location	Damage/Condition	Comments	Recommendations
Bent 24 to 29	Burnt stringers	Photographs 27 to 28	Monitor

4.1.5 Bearing Piles

The bearing piles are in fair condition with a couple area of localized deterioration as noted below.

Table 5: Bearing Pile Defects

Location	Damage/Condition	Comments	Recommendations
Piles			
Bent 2 Pile B	Crack		Monitor
Bent 3 Pile A	Crack		Monitor
Bent 5 Pile A	Concrete foundation spall		Monitor
Bent 5 Pile C	Concrete foundation spall	Photograph 30	Monitor
Bent 6 Pile C	Concrete foundation spall		Monitor
Bent 8 Pile A	Gouge	Photograph 31	Monitor
Bent 18 Pile B	Hole with severe marine borer damage	Photograph 32	Replace
Bent 21 Pile B	Hole	Photograph 33	Monitor
Bent 24 Pile B	Cracking with severe marine borer damage	Photograph 34	Replace
Bent 25 Pile C	Hole 1" in diameter		Monitor
Bent 28 Pile B1	Cracking	Photograph 36	Monitor
Bent 32 Pile C	Cracking with severe marine borer damage		Replace
Bent 38 Pile H	Batter Pile severe marine borer damage	Photograph 40	Replace
Bent 38 Pile B	Marine borer damage 30% section loss		Replace
Bent 40 Pile A	Severe marine borer damage		Replace
Bent 40 Pile A	Batter pile severe marine borer damage	Photograph 44	Replace
Bent 39 Pile A	Severe marine borer damage	Photograph 45	Replace
Bent 38 Pile A	Batter pile severe marine borer damage	Photograph 46	Replace
Bracing			
Bent 25	Broken	Photograph 35	Repair



4.2 FLOATS

4.2.1 Float A

The float A is in good condition overall with no notable defects. The individual components are as follows:

Bull rails	Fair Condition
Decking	Fair Condition
Rub Boards	Fair Condition
Frame	Fair Condition
Floats	Fair Condition
Guide Piles	Fair Condition
Pile Well	Fair Condition

The freeboard on float A was as follows:

NW	-	NE	405mm
SW	-	SE	430mm

Freeboard is measured from waterline to underside of deck

The floats are in fair conditional overall. The individual components are in the following condition:

Table 6: Float A Defects

Location	Damage/Condition	Comments	Recommendations
Typical condition of floats photographs 47 to 48			
Bull Rails			
South East Side	Worn bull rails		Monitor
Decking			
Typical	10+ boards are loose, split, or warped		Repair
Rub Boards			
South and West Side	Worn rub rails		Monitor
Floats			
All	Foam billets are exposed foam with scattered areas of 20% section loss		Replace
All	Fasteners are corroded with 10% section loss		Replace
Guide Piles			

Piles 1A, 1B, 1C, 1D, 2A, 2B, 2C, 3A, 3C, 4A, 4C, 5A, 5C, 6C	Abrasion from the floats	Photograph 52	Monitor
Piles 4D and 6A	Severe abrasion from floats	Photograph 53	Replace
Pile 2D	Cavity approximately 100mm penetration x 75mm high x 25mm wide		Monitor
Pile Well			
All	Poor condition and requires UHMW on multiple sides of the pile well	Photograph 52	Replace worn rub boards and add UHMW pads

4.2.2 Float B

The float B is in good condition overall with no notable defects. The individual components are as follows:

Bull rails	Fair Condition
Decking	Fair Condition
Rub Boards	Fair Condition
Frame	Fair Condition
Anchor chains	Fair Condition
Floats	Fair Condition

The freeboard on float B was as follows:

NW	265mm	NE	340mm
SW	390mm	SE	355mm

Freeboard is measured from waterline to underside of deck

The floats are in fair conditional overall. The individual components are in the following condition:

Table 7: Float B Defects

Location	Damage/Condition	Comments	Recommendations
Typical condition of floats photograph 54 to 55			
Bull Rails			
Typical	Fair condition	Photograph 56	Monitor
South Side	Missing bull rail	Photograph 59	Repair
Decking			

Typical	Grating on deck is disconnecting from the timber boards.	Photograph 55	Remove grating and install a lower gauge of grating
South Side	Missing board	Photograph 59	Replace
Middle	Heavy abrasion from gangway landing	Photograph 57	Repair gangway landing to prevent abrasion
Rub Boards			
Typical	Worn boards		Monitor
Anchor Chains			
Typical	Chains have 15% loss, Fair Condition		Monitor
Floats			
Typical	Foam billets are encapsulated, good condition		Monitor
Connection			
Between Float B and C	Poor Condition	Photographs 60 and 61	Repair
Transition Plate	Rusted		Replace
Decking and rub rails	Significant abrasion		Replace

4.2.3 Float C

The float C is in good condition overall with no notable defects. The individual components are as follows:

Bull rails	Good Condition
Decking	Good Condition
Rub Boards	Good Condition
Frame	Good Condition
Anchor chains	Good Condition
Floats	Good Condition

The freeboard on float C was as follows:

NW	380mm	NE	510mm
SW	460mm	SE	405mm

Freeboard is measured from waterline to underside of deck

The floats are in fair conditional overall. The individual components are in the following condition:



Table 8: Float C Defects

Location	Damage/Condition	Comments	Recommendations
Typical condition of floats photograph 62 to 63			
Bull Rails			
Typical	Fair condition		Monitor
Decking			
Near North End	Cracked boards	Photographs 64 to 65	Monitor
Rub Boards			
Typical	Fair condition		Monitor
Anchor Chains			
Typical	East anchor chain have 80% loss, West anchor chain has 50% loss Poor condition		Replace
Floats			
Typical	Foam billets are encapsulated, good condition		Monitor
Typical	Fasteners corroding		Replace
Connection			
Between Float C and D	Fair Condition	Photographs 66 and 67	Monitor
Transition Plate	No transition plate	Photograph 67	Add
West side	Missing tire	Photograph 68	Replace

4.2.4 Float D

The float D is in good condition overall with no notable defects. The individual components are as follows:

Bull rails	Fair Condition
Decking	Fair Condition
Rub Boards	Fair Condition
Frame	Fair Condition
Anchor chains	Fair Condition
Floats	Fair Condition

The freeboard on float D was as follows:

NW	390mm	NE	380mm
SW	380mm	SE	470mm

Freeboard is measured from waterline to underside of deck



The floats are in fair conditional overall. The individual components are in the following condition:

Table 9: Float D Defects

Location	Damage/Condition	Comments	Recommendations
Typical condition of floats photograph 69 to 70			
Decking			
Typical	Fair condition, boards are starting to warp		Monitor
Anchor Chains			
Typical	Chains have 15% loss, Fair Condition		Monitor
Floats			
Typical	Foam billets are encapsulated, good condition		Monitor

4.3 GANGWAY

4.3.1 Gangway A

Gangway A is in fair condition overall. The individual component condition are as follows:

Frame	Fair Condition
Wood Deck	Fair Condition
Roller	Poor Condition
Guide Rails	Poor Condition
Hinges	Fair Condition

Table 10: Gangway A Defects

Location	Damage/Condition	Comments	Recommendations
Frame	Some loss of paint and rust	Photographs 73 to 76	Clean and repaint
Roller	Clearance between pile wells is too small for the gangway roller	Photograph 77	Repair
Roller	Broken roller	Photograph 78	Replace
Guide Rail	Out of alignment and worn out	Photograph 79	Replace

4.3.2 Gangway B

Gangway B is in fair condition overall. The individual component condition are as follows:

Frame	Poor Condition
-------	----------------

Wood Deck	Fair Condition
Roller	Poor Condition
Guide Rails	Poor Condition
Hinges	Fair Condition

Table 11: Gangway B Defects

Location	Damage/Condition	Comments	Recommendations
Overall		Photograph 25	
Frame	Some loss of paint and rust	Photograph 86	Clean and repaint
Frame	Broken brace on both sides	Photographs 83 and 84	Repair
Frame	Rusted beams and braces	Photograph 86	Repair
Guide Rails	Rusted	Photograph 87	Repair
Roller	Rusted	Photograph 87	Replace
Landing platform	Poor condition	Photograph 82	Replace

4.4 SERVICES

There are six LED lamp standards at the facility servicing the approach, wharfhead, and floats. In general the lighting is in good condition. The ground to shore is broken and will need to be replaced.

Table 12: Services Defects

Location	Damage/Condition	Comments	Recommendations
Bent 1	Broken ground		Repair

The facility in the past provided a fuel filling service for boat traffic. The float and fuel pumps have since been removed and the system decommissioned, however the pipe lines still run along the southern side of the approach. These lines are starting to rust but are in Fair Condition and do not, at this time, need to be removed. Close monitoring of these pipes is recommended to prevent damage.

4.5 REVIEW OF OPERATIONAL, STRUCTURAL, AND MAINTENANCE ISSUES

Based on discussions with the wharfinger when the site inspection was conducted the facility is used by seaplanes, recreational boaters, Canadian Postal service, and emergency personal. The wharfinger expressed that there are discussions to reduce the loading zone area on Float B and transition loading services to Float D. Since there are no transition plates between Float C and Float D, the Ambulance service could have issues with getting patients to Float D. It is recommended to install a transition plate between Float C and Float D before reducing the 15



minute loading zone on Float B. A few times a year a vessel berths along the end of the wharfhead. Based on the current condition of the cleat supports it is recommended to repair these supports before vessels are allowed to berth along the wharfhead.

5 RESIDUAL LIFE ESTIMATES

The residual life estimates are based on section 2.5 in Procedures for Inspection and Assessment of Fixed Timber Docks. The residual life estimates are rough estimated values based on subjective judgment of the current deterioration and observed damages in the structural elements and in no way provides a guarantee on actual life span. It is important to note that components could last shorter or longer depending on the surrounding environment and level of use. Rot and marine bores can spread very quickly greatly reducing the estimated values.

Assuming that the facilities will be routinely inspected and scheduled maintenance repairs done, review of the residual life estimates can be updated resulting in the service life of the structures extended beyond their design life of the structures.

5.1 APPROACH/WHARFHEAD

Handrails	3 to 6 years
Bull Rails	3 to 6 years
Decking	3 to 6 years
Pile Caps	8 to 10 years
Stringers	8 to 10 years
Bearing Piles	5 to 10 years

5.2 FLOAT A

Bull Rails	3 to 6 years
Decking	3 to 6 years
Rub Boards	3 to 6 years
Floatation	3 to 6 years
Guide Piles	3 to 6 years
Pile Wells	3 to 6 years

5.3 FLOAT B

Bull Rails	3 to 6 years
Decking	3 to 6 years

Rub Boards	3 to 6 years
Floatation	8 to 10 years
Chain Anchors	3 to 6 years

5.4 FLOAT C

Bull Rails	3 to 6 years
Decking	3 to 6 years
Rub Boards	3 to 6 years
Floatation	8 to 10 years
Chain Anchors	3 to 6 years

5.5 FLOAT D

Bull Rails	3 to 6 years
Decking	3 to 6 years
Rub Boards	3 to 6 years
Floatation	8 to 10 years
Chain Anchors	3 to 6 years

5.6 GANGWAY

Gangway A	8 to 10 years
Gangway B	3 to 6 years

5.7 SERVICES

Lighting	8 to 10 years
----------	---------------

6 COST ESTIMATES OF REPAIRS

An order of magnitude cost estimate is provided in this report for the purpose of assisting CRD with an approximate cost to repair or replacement of various structural elements.

This cost estimate is an opinion of cost made by M&N. In providing the cost estimate, it is recognized that neither CRD nor M&N has control over the costs of labor, equipment, materials, or contractors' methods of determining prices or bidding. This cost estimate is based

on the consultant's reasonable professional judgment and experience and does not constitute a warranty, express or implied, that contractors' bids or negotiated prices of the work will not vary from CRD budget or from any costs prepared by M&N.

The costs shown in this report are based on a combination of current material and labour prices obtained from various material suppliers and contractors as well as parametric unit rates from historical data and updated to reflect the location of site and current date.

In addition to the general limitations discussed above, our cost estimate is based on the following assumptions:

- All costs are given as Canadian Dollars (1 USD = 1.35 CAN);
- Due to lack of maintenance and the limitations of a visual inspection of the facility, further deterioration may be present in components and may increase repair or replacement costs.
- Construction assumed to be performed by a local contractor to reduce mobilization and demobilization costs, which are included in the final cost;
- 12% tax, and 20% for contractors overhead and profit is included in estimate,
- Contingency of 25% is included in final costs; and,
- The funding plan can prioritize repair work to accommodate per annum budgets while allowing the facility to continue to operate.

Table 13: Cost Estimate

Component	Mobilization Type	Year	Cost
Utilities Repair Cost:	Minor	Immediate	\$3,400
Mobilization/Demobilization	Minor	Immediate	\$3,500
Sub Total		Immediate	\$6,900
Approach Repair Cost:	Minor	1 Year	\$22,800
Gangway Repair Cost:	Minor	1 Year	\$13,800
Mobilization/Demobilization	Minor	1 Year	\$10,600
Escalation @ 2% per annum			\$700
Sub Total		1 Year	\$47,900
Float Repair Cost:	Major	5 Years	\$119,200
Approach Pile Cost	Major	5 Years	\$82,700
Utilities Upgrades	Minor	5 Years	\$11,800
Mobilization/Demobilization	Minor	5 Years	\$19,900
Escalation @ 2% per annum			\$2,300
Sub Total		5 Year	\$255,800
Grand TOTAL			\$310,600

7 RISK, STRATEGIES, AND POLICY ADAPTATION

Typical operations at the facility are able to continue as normal due to the current state of the facility. It is recommended to prevent any vessels berthing at the wharfhead until the cleats are repaired. A transition plate is recommended to be installed between Float C and Float D before the loading zone size is decreased on Float B.

8 CONCLUSIONS AND RECOMMENDATIONS

The facility at Miners Bay is in overall fair condition. This facility is one of the two that provide accesses to Mayne Island. The critical repairs include fixing the broken ground wire to the abutment, repairing the bearing piles on the approach and wharfhead, repairing the broken braces on gangway B, repairing the four cleat supports on the wharfhead. All other repairs are recommended to be done in a timely manner to ensure the dock remains operational.

APPENDIX A: PHOTOGRAPHS




Photograph 1: General Layout



Photograph 2: Topside




Photograph 3: General Condition of Approach



Photograph 4: General Condition of Wharfhead



Photograph 5: Deck Rot at Bent 17



Photograph 6: Deck Rot at Bent 22



Photograph 7: Deck at Bent 23



Photograph 8: Deck at Bent 25




Photograph 9: Deck Rot between Bent 29 to 30



Photograph 10: Deck Rot at Bent 31




Photograph 11: Deck Rot between Bent 31 to 32



Photograph 12: Deck Rot at Bent 32




Photograph 13: Deck Rot at Bent 33




Photograph 14: Deck Rot at Bent 37




Photograph 15: Deck Rot at Bent 37




Photograph 16: Deck Rot at Bent 37




Photograph 17: Deck Rot at Bent 39



Photograph 18: Deck Rot at Bent 40




Photograph 19: Deck Rot and Hole Patch at Bent 40 and Cleat



Photograph 20: Deck Rot at Patches



Photograph 21: Warped Handrail at Bent 19



Photograph 22: Abutment



Photograph 23: Abutment



Photograph 24: Abutment



Photograph 25: Pile Caps



Photograph 26: Pile Cap Split at Bent 25



Photograph 27: Burnt Stingers between Bent 24 to 29



Photograph 28: Burnt Stingers between Bent 24 to 29



Photograph 29: Typical Approach Bent




Photograph 30: Concrete Spall at Pile 5C



Photograph 31: Gouge in Pile 8A




Photograph 32: Pile 18B Hole and Severe Marine Borer Damage



Photograph 33: Pile 21B Hole



Photograph 34: Cracking in Pile 24B




Photograph 35: Broken Bracing Bent 25



Photograph 36: Cracking in Pile 28B1



Photograph 37: Typical Wharfhead Pile Layout



Photograph 38: Typical Wharfhead Pile Layout



Photograph 39: Typical Wharfhead Pile Layout



Photograph 40: Pile 38H Batter Severe Marine Borer Damage



Photograph 41: Fender Piles



Photograph 42: Fender Piles



Photograph 43: Fender Face



Photograph 44: Pile 40A Batter Severe Marine Borer Damage



Photograph 45: Pile 39A Severe Marine Borer Damage




Photograph 46: Pile 38A Batter Severe Marine Borer Damage



Photograph 47: Float A General Condition




Photograph 48: Float A General Condition



Photograph 49: Float A Decking



Photograph 50: Float A Bull Rail and Rub Rail



Photograph 51: Float A Bull Rail



Photograph 52: Typical Pile Well Condition





Photograph 53: Guide Pile Abrasion



Photograph 54: Float B Condition



Photograph 55: Float B Deck Condition



Photograph 56: Float B Bull Rail and Rub Rail



Photograph 57: Float B Deck Worn out due to transition plate



Photograph 58: Float B Alignment Line



Photograph 59: Float B missing Bull Rail and Deck Board



Photograph 60: Connection between Float B and C



Photograph 61: Connection between Float B and C



Photograph 62: Float C



Photograph 63: Float C




Photograph 64: Float C Deck



Photograph 65: Float C Deck



Photograph 66: Float C Rub Board



Photograph 67: Connection between Float C and D



Photograph 68: Connection between Float C and D




Photograph 69: Float D




Photograph 70: Float D



Photograph 71: Float D Rub Rail



Photograph 72: Float D Rub Rail and Bull Rail



Photograph 73: Gangway A



Photograph 74: Gangway A



Photograph 75: Float A



Photograph 76: Gangway A




Photograph 77: Gangway A Guide Rails and Roller



Photograph 78: Gangway A Roller



Photograph 79: Gangway A Roller




Photograph 80: Gangway B



Photograph 81: Gangway B Hanger Support




Photograph 82: Gangway B



Photograph 83: Gangway B Broken Support



Photograph 84: Gangway B Broken Brace



Photograph 85: Gangway B



Photograph 86: Gangway B



Photograph 87: Gangway B Roller



Photograph 88: Electrical Services




Photograph 89: Lamp Standard at Bent 3



Photograph 90: Lamp Standard at Bent 3



Photograph 91: Broken Electrical Wire at Bent 16



Photograph 92: Lamp Standard at Bent 16




Photograph 93: Lamp Standard at Bent 16



Photograph 94: Lamp Standard at Bent 16



Photograph 95: Lamp Standard at Bent 28



Photograph 96: Lamp Standard at Bent 28




Photograph 97: Lamp Standard at Bent 28




Photograph 98: Lamp Standard at Bent 37 Pile F



Photograph 99: Electrical Services to Float A



Photograph 100: Lamp Standard on Float A



Photograph 101: Electrical Services to Float B




Photograph 102: Electrical Services to Float C



Photograph 103: Lamp Standard on Float C



Photograph 104: Lamp Standard on Float C




Photograph 105: Decommissioned Fuel Lines



Photograph 106: Decommissioned Fuel Lines


APPENDIX B: OPINION OF PROBABLE REPAIR/REPLACEMENT COSTS

OPINION OF PROBABLE COST					DATE PREPARED 13-Sep-15		SHEET		OF		
OWNER AND LOCATION Capital Regional District Vancouver Island, British Columbia				CONSTRUCTION CONTRACT NO.				 moffatt & nichol			
PROJECT TITLE Miners Bay				ESTIMATED BY Moffatt & Nichol							
				STATUS OF DESIGN Draft							
				MATERIAL & EQUIPMENT COST		LABOUR COST		MAN JOB ORDER NUMBER 8985			
ITEM DESCRIPTION		QUANTITY		UNIT COST		TOTAL		UNIT COST		TOTAL	
		NUMBER	UNIT								
Sales Tax (British Columbia)		12.0%									
Overhead and Profit		20.0%									
Contingency		25.0%									
General											
Major Mobilization/Demobilization											
Mobilization/Demobilization	1	Lump Sum		\$5,000	\$5,000	\$1,680.00	\$1,680	\$6,680.00	\$6,680.00		
Insurance/Bonds	1	Lump Sum		\$4,000	\$4,000	\$0.00	\$0	\$4,000.00	\$4,000.00		
Total					\$9,000		\$1,680		\$10,680		
Sale Tax, Overhead and Profit, and Contingency					\$6,120		\$1,142		\$7,262		
Total Estimated Construction Cost					\$15,120		\$2,822		\$17,942		
Total Opinion of Probable Cost				Major Mobilization/Demobilization Cost:				\$18,000			
Minor Mobilization/Demobilization											
Mobilization/Demobilization	1	Lump Sum		\$2,500	\$2,500	\$1,680.00	\$1,680	\$4,180.00	\$4,180.00		
Insurance/Bonds	1	Lump Sum		\$2,000	\$2,000	\$0.00	\$0	\$2,000.00	\$2,000.00		
Total					\$4,500		\$1,680		\$6,180		
Sale Tax, Overhead and Profit, and Contingency					\$3,060		\$1,142		\$4,202		
Total Estimated Construction Cost					\$7,560		\$2,822		\$10,382		
Total Opinion of Probable Cost				Minor Mobilization/Demobilization Cost:				\$10,400			
Miners Bay											
Approach Repair											
Timber Handrail 2"x6" - Bent 19	16	ft		\$1.58	\$25	\$52.50	\$840	\$54.08	\$865		
Timber Decking 4"x12" Bents 22-40	408	ft		\$12.65	\$5,156	\$13.74	\$5,600	\$26.39	\$10,756		
Repair cleat supports	4	ea.		\$200.00	\$800	\$280.00	\$1,120	\$480.00	\$1,920		
Paint handrails & bullrails (option not incl. in rpt)	2135	sq ft		\$0.83	\$1,772	\$1.57	\$3,360	\$2.40	\$5,132		
Total					\$5,981		\$7,560		\$13,541		
Sale Tax, Overhead and Profit, and Contingency					\$4,067		\$5,141		\$9,208		
Total Estimated Construction Cost					\$10,049		\$12,701		\$22,750		
Total Opinion of Probable Cost				Approach Repair Cost:				\$22,800			
Approach Piles											
Remove damaged piles	1	No.		\$1,500.00	\$1,500	\$560.00	\$560	\$2,060.00	\$2,060.00		
Bent 18 Pile B - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 24 Pile B - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 32 Pile C - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 38 Pile A - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 38 Pile B - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 38 Pile H - replace batter pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 39 Pile A - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 40 Pile A - replace pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Bent 40 Pile A - replace batter pile	45	ft		\$16.15	\$727	\$53.33	\$2,400	\$69.49	\$3,127		
Disposal of damage piles	5.5	tons		\$450.00	\$2,473	\$1,800.00	\$9,894	\$2,250.00	\$12,367		
Approach Brace Repair											
Barge for transport brace to underside of deck	1	No.		\$1,500.00	\$1,500	\$560.00	\$560	\$2,060.00	\$2,060.00		
One X-brace at Pile Bent 25 (6"x 8")	20	ft		\$172.04	\$3,441	\$56.00	\$1,120	\$228.04	\$4,561		
Disposal of damage bracing	0.0	tons		\$450.00	\$0	\$2,650.00	\$0	\$3,100.00	\$0		
Total					\$15,456		\$33,734		\$49,190		
Sale Tax, Overhead and Profit, and Contingency					\$10,510		\$22,939		\$33,449		
Total Estimated Construction Cost					\$25,967		\$56,672		\$82,639		
Total Opinion of Probable Cost				Approach Piles Cost:				\$82,700			
Float Repair											
Float A Repair											
Repair decking 2" x 12"	168	sq. ft		\$0.43	\$73	\$8.00	\$1,344	\$8.43	\$1,417		
Remove old piles - 40ft	2	No.		\$0.00	\$0	\$1,000.00	\$2,000	\$1,000.00	\$2,000		
Replace piles - 40 ft	2	No.		\$810.00	\$1,620	\$2,400.00	\$4,800	\$3,210.00	\$6,420		
Repair pile well rub rail 2" x 12"	80	ft.		\$0.43	\$35	\$8.00	\$640	\$8.43	\$675		
Install UHMW wearing pads pile wells	4	No.		\$500.00	\$2,000	\$280.00	\$1,120	\$780.00	\$3,120		
Repair rub rails 2" x 12"	40	ft.		\$0.43	\$17	\$8.00	\$320	\$8.43	\$337		
Replace bull rails 4" x 6"	40	ft.		\$3.35	\$134	\$140.00	\$5,600	\$143.35	\$5,734		
Remove old floatation - 10 (1220x1220x2440)	14	No.		\$0.00	\$0	\$357.14	\$5,000	\$357.14	\$5,000		
Replace floatation - 10	14	No.		\$700.00	\$9,800	\$714.29	\$10,000	\$1,414.29	\$19,800		
Replace foam billet fasteners	1	No.		\$100.00	\$100	\$5,600.00	\$5,600	\$5,700.00	\$5,700		
Float B Repair											
Replace bull rails 4" x 6"	44	ft.		\$3.35	\$148	\$140.00	\$6,201	\$143.35	\$6,350		
Replace decking 2" x 12" at gangway & grating	140	sq.ft.		\$0.43	\$211	\$8.00	\$1,120	\$8.43	\$1,181		
Repair connection between floats B&C incl transit	1	No.		\$500.00	\$500	\$280.00	\$280	\$780.00	\$780		
Repair rub rails 2" x 12"	40	ft.		\$0.43	\$17	\$8.00	\$320	\$8.43	\$337		
Float C Repair											
Replace anchor chains Float C	100	ft		\$24.20	\$2,420	\$33.00	\$3,300	\$57.20	\$5,720		
Replace decking 2" x 12"	20	sq.ft.		\$0.43	\$9	\$8.00	\$160	\$8.43	\$169		
Repair connection between floats C&D incl transit	1	No.		\$500.00	\$500	\$280.00	\$280	\$780.00	\$780		
Replace foam billet fasteners	1	No.		\$100.00	\$100	\$2,240.00	\$2,240	\$2,340.00	\$2,340		
Float D Repair											
Repair decking 2" x 12"	360	sq. ft		\$0.43	\$157	\$8.00	\$2,880	\$8.43	\$3,037		
Total					\$17,841		\$53,205		\$70,896		
Sale Tax, Overhead and Profit, and Contingency					\$12,132		\$36,179		\$48,210		
Total Estimated Construction Cost					\$29,973		\$89,385		\$119,106		
Total Opinion of Probable Cost				Float Repair Cost:				\$119,200			
Gangway Repair											
Gangway A Repair											
Sandblast and re-paint rusted areas	1	No.		\$500.00	\$500	\$560.00	\$560	\$1,060.00	\$1,060		
Remove and replace roller, and roller bearings	1	No.		\$200.00	\$200	\$280.00	\$280	\$480.00	\$480		
Replace rusted L-guide rails	2	No.		\$100.00	\$200	\$280.00	\$560	\$380.00	\$760		
Add Transition plate on top and bottom	2	No.		\$100.00	\$200	\$280.00	\$560	\$380.00	\$760		
Gangway B Repair											
Install UHMW wearing pads to transition plates	2	No.		\$500.00	\$1,000	\$280.00	\$560	\$780.00	\$1,560		
Sandblast and re-paint rusted areas	1	No.		\$500.00	\$500	\$560.00	\$560	\$1,060.00	\$1,060		
Replace broken and rusted L-Braces - 3x 3x6lbs/ft	2	No.		\$100.00	\$200	\$280.00	\$560	\$380.00	\$760		
Replace rusted angles and I beams assume 3"x3"	2	No.		\$150.59	\$301	\$280.00	\$560	\$430.59	\$861		
Add Transition plate on top	1	No.		\$100.00	\$100	\$280.00	\$280	\$380.00	\$380		
Remove and replace roller, and roller bearings	1	No.		\$200.00	\$200	\$280.00	\$280	\$480.00	\$480		
Total					\$3,401		\$4,760		\$8,161		
Sale Tax, Overhead and Profit, and Contingency					\$2,313		\$3,237		\$5,550		
Total Estimated Construction Cost					\$5,714		\$7,997		\$13,711		
Total Opinion of Probable Cost				Gangway Repair Cost:				\$13,800			
Utilities Repair											
Repair ground	1	No.		\$1,000.00	\$1,000	\$1,000.00	\$1,000	\$2,000.00	\$2,000		
Total					\$1,000		\$1,000		\$2,000		
Sale Tax, Overhead and Profit, and Contingency					\$680		\$680		\$1,360		
Total Estimated Construction Cost					\$1,680		\$1,680		\$3,360		
Total Opinion of Probable Cost				Utilities Repair Cost:				\$3,400			
Utilities Upgrades											
Replace with LED fixtures	1	LS		\$4,000.00	\$4,000	\$3,000.00	\$12,000,000	\$7,000.00	\$7,000		
Total					\$4,000		\$12,000,000		\$7,000		
Sale Tax, Overhead and Profit, and Contingency					\$2,720		\$8,160,000		\$4,760		
Total Estimated Construction Cost					\$6,720		\$20,160,000		\$11,760		
Total Opinion of Probable Cost				Utilities Upgrades Cost:				\$11,800			

APPENDIX C: UNDERWATER INSPECTION REPORT

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

UNDERWATER INSPECTION REPORT CRD Docking Facilities

Southern Gulf Islands
August 10- 14th, 2015

Ref# 35332

BACKGROUND

Over the week of August 10-14th, 2015, All-Sea Underwater Solutions diving personnel performed underwater inspections of 12 CRD docking facilities located among the Southern Gulf Islands. The observations include the floats, pilings, anchor chains and anchor points. This inspection was directed by the onsite representative from Moffet and Nichol.

DIVING OPERATIONS

The diving was carried out using a three man dive team with surface supplied diving equipment, two way diver to topside communication and u/w video recording capability and conducted from a dive support vessel.

FACILITIES INSPECTED

Twelve docking facilities were underwater inspected at the following locations;

August 10, 2015


1. Piers Island Harbour, Piers Island.
2. Swartz Bay, Vancouver Island

August 11, 2015

1. Port Browning, N Pender Island
2. Lyall Harbour, Saturna Island
3. Hope Bay, N Pender Island

August 12, 2015

1. Retreat Cove, Galiano Island
2. Fernwood Dock, Salt Spring Island
3. Montague Harbour, Galiano Island



August 13, 2015

1. Sturdies Bay, Galiano Island
2. Minors Bay, Mayne Island

August 14, 2015

1. Horton Bay, Mayne Island
2. Port Washington, N Pender Island


FINDINGS

The data recorded is itemized from the site plan and general arrangement that was provided by the onsite representative from Moffet and Nichol. Each facility inspection was recorded via u/w cc video. The following is a list of abnormalities sighted; all other points inspected shall be considered free of significant damage.

Each photo has is marked with Chapter number and time in minutes from the video.

Piers Island Harbour, August 10, 2015. Time: 800am. Max depth 15 feet


- A) Foam billets were not encapsulated, exposed foam deteriorated approx 10-15% and were covered in marine growth.



04:29

ALL-SEA


UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

B) Southwest 4 pile cluster, piling on the NE corner; two cavities sighted approx 50mm deep x 130mmL x 30mmW near mud line.



12:33



12:40

C) Anchor chains from N end of triangular float, 3 connections, up to 50% wastage on links in the tidal zone. Anchor connections secure approx 20% wastage on shackle



22:59



29:26

D) Gangway pilings inspected; Row 8, three piles, 2' water depth, no abnormalities sighted.



Swartz Bay August 10, 2015. Time: 1115am, Max depth 18 feet

A) Anchor chain in tidal zones from dock connection has approx 10-20% wastage at the links. Chain along bottom up to 10% wastage.



B) Float A, East anchor chain at block connection, chain link has up to 30% wastage.




C) Anodes fitted to the anchor chains were found to average approx 80% depleted.

D) Foam billets were encapsulated; no signs of deterioration were sighted.

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

E) Concrete pilings #5 and #6: vertical fractures sighted up from mud line approx 400mmL.




Port Browning, August 11th, 2015, Time: 830am, Max depth 22 feet

A) Anchor chain connections at North float running east, chain wastage up to 15%



ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

B) Gangway pilings exhibit few small cavities to 20mm depth, very scattered.




C) Foam billets are encapsulated and remain intact.

D) No sign of significant damage to the u/w portion of the floats.

Lyall Harbour, August 11th, 2015, Time: 1210. Max depth 26 feet

A) Approach steel pilings exhibiting surface corrosion and pitting in way of scattered areas void of coatings. Second row from shoreline pilings are pitted to 2mm depths. Remaining steels piles to the North reveal pitting to 1mm depths. No anodes were fitted to the piling.




35:53



45:38



B) Non encapsulated foam billets under floats are deteriorated 10-20%



51:45



52:02

C) Float contact on wooden pile, wear approx 12mm. Steel pile wear from float approx 2mm, weld seam flush with pile surface. Scattered areas on steel pile, exposed corrosion to 1mm depths.



108:52 Wood pile



Ch.2: 2:25 Steel pile

D) Floats and remaining wooden piles in fair condition.

E) Float fasteners exhibit moderate corrosion.



Ch.2; 17:56

Hope Bay, August 11th, 2015, Time: 1515pm

- A) Pile row #6 angle cross timber, hollowed out at end in way of piling C
- B) Crack lines evident in pile 6B at concrete pile foot



00:26

Cross timber




01:57

Split line at pile foot

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

C) Scattered areas of small hole amongst the Wharf head and approach pilings to depths of 90mm opening to inner cavities. Each pile exhibits a certain degree of holes.




04:08




19:14

D) Row 8 Pile C, concrete footing deteriorated to exposed pile bottom.




09:13



09:32

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

E) Row 8 Pile D, Cross timber hollowed out at low end. Pile bottom contact on rocks approx 20%.



12:43




11:48


F) Row 10 Pile C, lower end of cross timber eroded out to a depth of 200mm



25:39



G) Float A, south side, east of gangway horizontal board dropped due to timber fasteners failing



34:36



36:11

H) Float A & C timber fasteners, scattered areas of wasted nuts.



39:22




41:39

I) Foam billets are encapsulated, no abnormalities sighted.

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

Retreat Cove, August 12th, 2015; Time: 800am, Max depth 18 feet

A) 3 pile cluster fender piles at west end of the approach. Multiple holes and outermost pile hollowed out at the bottom.



02:22



03:06

B) 3 bands scraped bottom, mid way and below water line, no abnormalities found




13:04 Row 9, Pile C (bottom)



24:53 Row 7 Pile B (mid way)

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

C) Row 8 Pile B has a large cavity approx 1.5M from bottom, measures 180mmDeep x 130mmw x 250mmH



20:08



21:10


D) Scattered areas of small holes in pilings from Rows 6, 5 and 4, lines A and B. Depths up to 100mm.



35:25



26:48



E) Scraped pile located at west cluster of three on pontoon float near gangway, north most pile. No abnormalities sighted.

F) Very scattered shallow cavities found on the float piles, max depth 20mm.



43:28 Scraped pile



46:40 Cavities

G) Side boards on pontoon float show signs of erosion at scattered areas, timber bolts are at varying degrees of metal wastage, still remains secure, bolts at max are 70% wasted




49:28



52:24

H) Foam billets are encapsulated, no abnormalities



Fernwood Dock, August 12th, 2105 Time: 1015am. Max depth 17 feet

A) Piling condition generally good with very few scattered small cavities to depths of 40mm max and widths of 40mm. Diver u/w inspected the approach piles to row 22



02:37



07:04

B) Older exposed foam billets show deterioration to approx 10%. Newer billets fiberglass coated are in good shape.



22:07

Exposed foam



31:18


Encapsulated foam



C) Scattered timber bolts found to be corroded, many remaining in fair condition, floats appear secure and solid. Side horizontal timbers are deteriorated and loose, mainly at the west end of the float.



39:33 Corroded nut



40:55 Deteriorated timber

Montague Harbour, August 12, 2015. Time 1230pm, Max depth 26 feet


A) Anchor chain condition wear average approx 1mm with exception to the connection at float A anchor block extending from the north corner to offshore block. The shackle connection is approx 70% worn through. Anchor chain anodes sighted are 30% depleted.



02:30 Typical anchor chain wear



08:52 Severe shackle link wear



A) Steel pilings total of 4 exhibited corrosion spots to 2mm depths. Fitted anode brackets were 100% depleted of anodes.



17:45 Pitting to 2mm depths




18:38 Anode brackets

B) Float fasteners found to be corroded, scattered areas up to 80% of bolt wasted.



31:58




31:51

C) Foam blocks encapsulated and in good condition.

D) Float structure appears in fair condition with scattered area of moderate wood deterioration on the side planks.

E) Wooden pilings are overall in good condition.



Sturdies Bay, August 13, 2015, Time 810am, Max depth 21 feet

A) Inspection of Float and pile clusters found no significant defects.

B) Break water piles are numbered 1 -93 beginning from north end. Piles 15, 40, 60 and 80 were scraped below water line, mid way and mud line, no defects sighted on those piles.



32:06 Pile 15 scraped band (Mid)



43:50 Pile 40 scraped band (lower)




52:32 Pile 60 scraped (lower)



1:10:19 Pile 80 scraped (upper)

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

B) Piling 63, west face of break water, crack running up from mud line for approx 1.2M then a second crack alongside starting and running approx 2M up the pile.



57:45



57:36



58:28



57:49

C) Pile 93 west face, approx 1.5M from bottom; cavity 75mmD x 400mmH x 25mmW

D) Pile 52 east face, small hole 25mm deep x 20mmW



1:19:39


Cavity



Ch.2; 10:46 Small Hole

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

E) Row 14 pile F cross timber hollowed out at lower end approx 100mm deep



Ch.3; 00:35



Ch.3; 00:45

F) Scattered holes found on approx 7 of the 23 piles on the main approach. Max depths 60mm x 25mm wide.



Ch.3; 2:10




Ch.3; 4:23



Ch.3; 5:22



Ch.3; 8:39



G) Row 9 Pile H, east pile of the pair; 1 meter crack from mud line up and approx 12mm wide at max.



Ch.3; 49:11



Ch.3; 49:18

Minors Bay, Aug 13th, 2015. Time; 1200 Max depth 26 feet


A) Float C east anchor chain, wear near connection 40%. Run of chain to anchor approx 80% wastage.



Ch.1; 01:58



Ch.1; 02:34



B) Float C west anchor chain, wear near connection 30%. Run of chain to anchor approx 50% wastage.



Ch. 1; 10: 55




Ch. 1; 11:45

C) Anchor chains on floats D and B have link wastage to 15% and are in fair condition. All anchor points on shore and concrete blocks are secure with wastage 15-25%.

D) Float timber fasteners have varying degrees of corrosion. No loose boards were sighted.



Ch1: 39:04




Ch1; 39:15

E) Foam billets are encapsulated, no abnormalities sighted.

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

Main Approach pilings were inspected u/w from Row 14 to row 40. The following photos show defects, the remaining are in fair condition;

A) Row 18 Piles A and B small cavities and cracks



Ch2: 51:55 Cavity 40mm deep x 25mmW



Ch2; 53:14, 2 cracks 50mm deep x 150mmH




Ch2; 42:35 Row 21, pile B cavity 50mmD



Ch2; 47:01 Row 21, pile C cavity 30mmD

ALL-SEA

UNDERWATER SOLUTIONS




All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

B) Row 26 Pile C scraped, 3 bands; Mud line ,mid way and below water line



Ch2; 14:45 Mid way



Ch2; below water line (cavity)

C) Row 30, pile B cavity approx 25mmD mid way up pile.


D) Row 32 Pile C cavity split at mud line approx 200mmD x 600mmH x 150mmW



Ch2 108:08 Row 30 pile B (cavity)



Ch3; 06:57 Row 32 Pile C Large cavity split



E) Row 33 Pile B 3 bands scraped at waterline, mid way and mud line, No abnormalities sighted.

F) Row 34, batter pile, 75mmDeep x 25mmW cavity approx 1M from mud line.



Ch3; 09:47 Row 33 Pile B Scraped



Ch3; 17:53 Row 34 Batter Pile cavity

G) Fender pile clusters at North face of the wharf, to sets in way of Rows 39 and 37, piles exhibit large cavities, splits and small holes. Outer piles are cladded with a steel plate half sleeve. Piles are deteriorating, but appear to be moderately sound. They are not part of the wharf structure.




Ch3 29:58 large cavity approx 200mmD



Ch3; 29:24 fender cluster

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

H) Row 38 Pile B line, At mud line eroded approx 80mm deep x 200mmW approx 30% around pile.




Ch3;47:17

G) Row 39 Pile A below water line pile is rotted out almost completely.



Ch4: 00:29



H) Row 40 Pile A, Vertical support pile, hollow section approx 2m up from mud line.
Approx 25% absent x 400mmH



Ch4: 11:15



Ch4: 12:10

I) Rub marks on outer piles on row 40.


J) Majority of the pilings from Row D toward row H are fitted with pile wrap, no significant defects were sighted.




Ch4:1:03:07



Ch4: 23:31



K) Float A, NW 6 pile cluster center N pile; cavity approx 100mm deep x 75mmH 25mmW.



Ch4: 110:49 Cavity

L) Float A foam billets are exposed foam with scattered areas of loss to 20% in sections. The float appears in good condition with fasteners moderately corroded to 10 % depletion.

Horton Bay, August 14th, 2015; Time: 805am Max depth 22 feet


Note: Horton Bay facility lay out differs from the provided plan, fingers A to D are not present. Fingers E and F remain.

A) Float timber fasteners on fingers E and F approx 5-10% corroded.


B) Finger floats E and F have exposed foam billets with deterioration to 10-15%



03.:36



01:03



C) Billets from the connection section of float A toward the shore are encapsulated and are in good condition.

D) Float A North section, timber fasteners exhibiting corrosion.

E) Section of float horizontal timber, located at north end of float A on west side in way of the 3 piles at corner. Rotted section from outside running inward about half way.



20:01



23:21


F) Row 6 pile diagonal cross member on main approach has a crack from propagating from both ends in way of the vertical pile fastening bolt. Each runs for approx 1 meter.



31:03



31:10



G) Pile row 2, first row where piles are set in concrete, a hole found in the east and west piles near the concrete setting. The holes run completely through and are bored out in the inside approx 75mm diameter.



41:55 East pile



44:37 West Pile

Port Washington, August 14th, 2015; Time: 11:00am


A) All Anchor chain connections and chains are in good condition.



11:54



16:57



B) Row 12 Pile B, two cavities sighted approx 50mm depths.

C) Row F Pile D, Pile was scraped in 3 locations, mud line section; small cavity sighted, less than 20mm depth.



24:57 Pile B cavity



40:43 Scraped pile D

D) Row 11 Pile D, opening in the wood approx 300mm H x 20mmW

E) Batter pile running from Row 8 Line A toward Row 10. Near mud line a hollow area approx 75mmDiameter x 80mm deep.



46:24 Pile D




59:02 Batter pile



F) Row 10 batter pile at C line, two cavities approx 70mm deep x 100mmL approx half way down pile.

G) Row 9 Pile F, split in pile 1.5m from water line down and continues up and out of the water for approx 2m.




1:07:33 Cavity



Ch 2; 01:04 Split pile

H) Row 8 pile D, split in the pile approx 300mmL x 50mm deep.




Ch2; 5:12



Ch2: 5:20

ALL-SEA

UNDERWATER SOLUTIONS



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

I) Row 6 pile D (adjacent to second pile). Two cavities approx 80mm deep



Ch2: 23:52




Ch2: 23:37

J) Row 4 West pile, cavity just above concrete, 80mm depth x 30mm wide.



Ch2: 31:26



K) Float B under gangway at west end has dropped due to the washer and bolts wasted away.

L) General condition of timber fasteners on float B and C



Ch2: 39:06



Ch2: 41:26

M) Billets on floats B and C encapsulated and in good condition.

N) Pile cluster eastern set on float B, outboard center in rubbing area. Cavity approx 50mm deep.



Ch2: 40:40 Billets



Ch2: 44:38



All-Sea Enterprises Ltd.

1458 Rupert Street
North Vancouver, B.C., Canada V7J 1E9
T: +1 (604) 980-9613
F: +1 (604) 980-9223
www.all-sea.com
office@all-sea.com

Photos are included with this report taken from the video provided of each facility.

For any additional information please contact the writer at the numbers provided.

Report Submitted By:
ALL-SEA ENTERPRISES LTD.

Lance Hiney