

**APPENDIX C**

**FECAL COLIFORM AND FLOW DATA**

**2006–2010**

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
0407	5	1000	AHWL	sand	SA,SU Rd. east corner of Saanichton Bay	Central Saanich/Tsawout						
							Apr 19, 2006	200610843	20	151	wet	no odour, discharge amber
							Sep 15, 2006	200612133	40	1600	dry	slight sewage odour, discharge clear
							Mar 20, 2007	200710617	100	17	wet	no odour, discharge reddish brown
							Aug 27, 2007	200711573	35	60	dry	no odour, discharge slight amber colour
							Mar 11, 2008	200811593	300	6	wet	no odour, discharge clear
							Jul 30, 2008	200812348	400	80	dry	musty odour, amber discharge
							Mar 05, 2009	200911298	400	8	wet	no odour, discharge clear, tidally influenced
							Jul 24, 2009	200912198	25	6	dry	no odour, discharge amber
							Mar 31, 2010	201011844	250	48	wet	no odour, slight amber discharge
Aug 26, 2010	201013017	30	128	dry	no odour, discharge clear							
0409A	6	200	I	sand beach	below and north of 2801 SA,SU Rd. in bank	Central Saanich/Tsawout						
							Feb 01, 2007	200710270	10	0	wet	no odour, discharge clear
							Aug 27, 2007	200712071	0		dry	dry, not sampled
0409C	6	200	AHWL	rock and gravel	2788 SA,SU Rd. at corner of gravel driveway	Central Saanich/Tsawout						
							Feb 27, 2008	200812960	0		wet	dry, not sampled
							Sep 17, 2008	200812961	0		dry	dry, not sampled
0409D	6	400	AHWL	rock and gravel	east side of 2764 SA,SU Rd.	Central Saanich/Tsawout						
							Mar 13, 2009	200911504			wet	wet only, not sampled
							Jul 24, 2009	200912200	8	2400	dry	no odour, discharge clear
							Feb 18, 2010	201011293	6	200	wet	no odour, discharge clear
							Aug 26, 2010	201013030	0		dry	dry, not sampled
0410	6	600	AHWL	sand beach	20 m north of 2764 SA,SU Rd.	Central Saanich/Tsawout						
							Apr 19, 2006	200610846	35	12	wet	no odour, discharge clear
							Sep 15, 2006	200612135	25	28	dry	no odour, discharge clear
							Feb 01, 2007	200710271	50	6	wet	no odour, discharge clear
							Aug 27, 2007	200711574	10	1400	dry	no odour, discharge clear
							Feb 27, 2008	200811144	20	6	wet	no odour, discharge clear
							Sep 17, 2008	200812978			dry	wet only, not sampled
							Feb 18, 2010	201011294	24	1	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Aug 26, 2010	201013014	2	210	dry	no odour, discharge clear
0410A	6	250	AHWL	sand beach	2859 SA,SU Rd.	Central Saanich/Tsawout						
							Feb 18, 2010	201011295	1	2	wet	no odour, discharge clear
							Aug 26, 2010	201013031	0		dry	dry, not sampled
0411	6	300	AHWL	beach	near SA,SU Rd. and Mt. Newton X Rd. intersection	Central Saanich/Tsawout						
							Feb 01, 2007	200710278	0		wet	dry, not sampled
							Aug 22, 2007	200711544	0		dry	dry, not sampled
0411AA	6		AHWL	beach	Between church and 2769 Mt Newton Rd	Central Saanich/Tsawout						
							Apr 19, 2006	200610847	15	297	wet	no odour, discharge brown
							Sep 15, 2006	200612137	0		dry	dry, not sampled
							Feb 01, 2007	200710272	30	8400	wet	no odour, discharge clear
							Apr 25, 2007	200710885	15	1600	wet	no odour, discharge very murky
							Aug 22, 2007	200711546	0		dry	dry, not sampled
							Feb 27, 2008	200812962			wet	standing water, not sampled
							Sep 16, 2008	200812793	0		dry	dry, not sampled
							Mar 13, 2009	200911484	5	41	wet	no odour, discharge clear
							Jul 24, 2009	200912174			dry	wet only, not sampled
							Feb 18, 2010	201011296	4	1	wet	no odour, discharge clear
							Aug 26, 2010	201013032			dry	wet only, not sampled
0412W	7	1700	AHWL	creek	Tetayut Creek	Central Saanich/Tsawout						
							Apr 25, 2006	200610923	100	363	wet	no odour, discharge brown
							Sep 13, 2006	200612106	150	76	dry	no odour, discharge slightly brown
							Mar 28, 2007	200710745	150	18	wet	no odour, discharge clear
							Sep 25, 2007	200711945	150	3000	dry	no odour, discharge slightly brown colour
							Feb 18, 2008	200811309	280	24	wet	no odour, discharge clear
							Jul 30, 2008	200812342	120	436	dry	no odour, discharge clear
							Mar 05, 2009	200911296	300	70	wet	no odour, discharge slight amber
							Jul 24, 2009	200912201	25	600	dry	no odour, discharge clear
							Feb 17, 2010	201011282	300	85	wet	no odour, discharge clear
							Aug 20, 2010	201012944	100	400	dry	no odour, discharge clear
0413	7	200	AHWL	estuary	beach access on Mt. Newton X Rd. east of Lochside Drv	Central Saanich						

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Apr 19, 2006	200610848	1	200	wet	no odour, discharge black
							Sep 14, 2006	200612109	0		dry	dry, not sampled
							Apr 02, 2007	200710768			wet	wet only, not sampled
							Aug 21, 2007	200712072			dry	wet only, not sampled
							Feb 27, 2008	200812963	0		wet	dry, not sampled
							Sep 16, 2008	200812974	0		dry	dry, not sampled
							Mar 13, 2009	200911505			wet	wet only, not sampled
							Jul 24, 2009	200912175			dry	wet only, not sampled
							Feb 18, 2010	201011306			wet	wet only, not sampled
							Aug 26, 2010	201013033	0		dry	dry, not sampled
0414	7	300	AHWL	estuary	Mt. Newton X Rd. beach access east of Lochside Dr.	Central Saanich						
							Apr 19, 2006	200610853	40	0	wet	no odour, discharge clear
							Sep 14, 2006	200612108	5	52	dry	no odour, discharge clear
0416	7	800	AHWL	sand/gravel beach	Ferguson Rd. beach access	Central Saanich						
							Mar 09, 2006	200610581	180	110	wet	no odour, discharge light brown
							May 17, 2006	200611027	15	161	wet	no odour, discharge clear
							Aug 16, 2006	200611732	80	132	dry	no odour, discharge clear
							Jan 23, 2007	200710073	100	22	wet	no odour, discharge light brown
							Aug 21, 2007	200711498	60	2800	dry	no odour, discharge clear
							Feb 27, 2008	200811146	15	< 1	wet	no odour, discharge clear
							Sep 17, 2008	200812620	35	1000	dry	no odour, discharge clear
							Mar 13, 2009	200911485	20	30	wet	no odour, discharge clear, dead salmon just below eop
							May 21, 2009	200911889	16	200	wet	no odour, discharge slight amber, dead halibut below eop
							Sep 24, 2009	200912750	20	600	dry	no odour, discharge clear
							Feb 18, 2010	201011297	20	4	wet	no odour, discharge clear
							Aug 18, 2010	201012925	10	1000	dry	no odour, discharge clear
							Sep 02, 2010	201013068	8	160	dry	no odour, discharge clear
							Oct 08, 2010	201013374	24	1000	dry	no odour, discharge clear
0419	7	400	AHWL	rocky beach	2654 Lancelot Dr., Turgoose Pt. Estates, near #14	Central Saanich						
							Mar 09, 2006	200610584	65	266	wet	no odour, discharge light brown
							Aug 16, 2006	200611734	50	24000	dry	no odour, discharge clear
							Sep 14, 2006	200612110	5	2	dry	no odour, discharge clear
							Jan 23, 2007	200710074	60	80	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Aug 21, 2007	200711499	25	140	dry	no odour, foam in discharge
							Feb 27, 2008	200811147	12	< 1	wet	no odour, discharge clear
							Sep 26, 2008	200812673	15	4400	dry	no odour, discharge clear with some brown foam
							Mar 13, 2009	200911487	15	0	wet	no odour, discharge clear
							Sep 24, 2009	200912752	6	12	dry	no odour, discharge clear
							Feb 18, 2010	201011299	6	1	wet	no odour, discharge clear
							Aug 26, 2010	201013015	3	52	dry	no odour, discharge clear
0420	7	600	AHWL	rocky beach	in rock wall south of concrete encasement below Arthur Rd. beach access	Central Saanich						
							Mar 09, 2006	200610583	10	274	wet	no odour, discharge clear
							Aug 16, 2006	200611733	0		dry	dry, not sampled
							Jan 23, 2007	200710075	65	133	wet	no odour, discharge clear
							Aug 21, 2007	200711500	20	160	dry	no odour, discharge clear
0421	7	200	AHWL	rocky beach	concrete encasement below manhole below Arthur Rd. beach access	Central Saanich						
							Mar 09, 2006	200610586	0		wet	dry, not sampled
							Aug 16, 2006	200611737			dry	dry, not sampled
0421A	8			rocky	north of 8055 Arthur Drive, access through field at foot of Arthur Drive							
							Sep 24, 2009	200912754	0		dry	dry, not sampled
							Feb 18, 2010	201011360			wet	wet only, not sampled
							Aug 26, 2010	201013039	0		dry	dry, not sampled
0422A	8	200	AHWL	rocky beach	foot of Newman Rd., 3 m north of boat house	Central Saanich						
							Mar 09, 2006	200610587	25	138	wet	no odour, discharge clear
							Aug 16, 2006	200611738			dry	wet, not sampled
0423	8	1100	AHWL	rocky beach	foot of Newman Rd., 8 m north of boat house	Central Saanich						
							Mar 09, 2006	200610588	100	1800	wet	no odour, discharge clear
							Aug 16, 2006	200611735	10	4	dry	no odour, discharge clear
							Jan 23, 2007	200710076	100	> 140	wet	no odour, discharge clear
							Aug 21, 2007	200711501	35	1600	dry	no odour, discharge clear
							Feb 27, 2008	200811148	50	13	wet	no odour, discharge clear
							Sep 19, 2008	200812979	10		dry	pipe broken causing flow to be too dispersed to sample
							Mar 13, 2009	200911488	25	8	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
0424	8	700	AHWL	sand/gravel	between 8475 and 8443-Lochside Dr.	North Saanich	Sep 24, 2009	200912755	1	16	dry	no odour, discharge clear
							Feb 18, 2010	201011300	20	8	wet	no odour, discharge clear
							Aug 26, 2010	201013034	0		dry	dry, not sampled
0426	9	1000	AHWL	rocky beach	Wardle Rd. beach access	North Saanich	Mar 09, 2006	200610585	90	16	wet	no odour, discharge light brown
							Aug 16, 2006	200611736			dry	dry, not sampled
0426	9	1000	AHWL	rocky beach	Wardle Rd. beach access	North Saanich	Mar 09, 2006	200610589	80	30000	wet	no odour, discharge clear
							May 17, 2006	200611028	15	33	wet	no odour, discharge clear
							Aug 16, 2006	200611739	25	200	dry	no odour, discharge clear
							Jan 05, 2007	200710028	100	98	wet	no odour, discharge clear
							May 24, 2007	200711000	40	6	wet	sweet odour, discharge clear
							Aug 21, 2007	200711502	25	1600	dry	no odour, discharge clear
							Jan 25, 2008	200811082	15	19	wet	no odour, discharge clear
							Sep 18, 2008	200812639	20	1000	dry	no odour, discharge clear
							Jan 15, 2009	200911009	100	180	wet	no odour, discharge clear
							Mar 13, 2009	200911489	30	12	wet	no odour, discharge clear
							Aug 17, 2009	200912401	6	11200	dry	no odour, discharge clear
							Oct 15, 2009	200912820	20	1400	wet	no odour, discharge clear
							Nov 26, 2009	200913057	100	128	wet	no odour, discharge clear
							Feb 18, 2010	201011301	20	6400	wet	no odour, discharge clear
							Apr 09, 2010	201011890	16	12400	wet	no odour, discharge clear
Aug 18, 2010	201012930	4	2	dry	no odour, discharge clear							
Oct 29, 2010	201013432	4	896	dry	no odour, discharge clear							
0428	9	900	AHWL	rocky beach	3 m north of beach access steps at foot of Amity Dr.	North Saanich	Mar 09, 2006	200610590	85	220	wet	no odour, discharge clear
							Aug 16, 2006	200611740	20	33	dry	no odour, discharge clear
							Jan 23, 2007	200710077	100	3600	wet	no odour, discharge clear
							Apr 25, 2007	200710887	80	0	wet	no odour, discharge clear
							May 24, 2007	200711001	45	600	wet	no odour, discharge clear
							May 31, 2007	200711009	40	44	wet	no odour, discharge clear
							Aug 21, 2007	200711503	40	600	dry	no odour, discharge clear
							Jan 25, 2008	200811076	25	16	wet	no odour, discharge clear
							Jan 31, 2008	200811121	15	2600	wet	no odour, discharge clear
							Sep 18, 2008	200812640	15	4	dry	no odour, discharge clear
							Jan 15, 2009	200911003	40	14	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 13, 2009	200911490	40	26	wet	no odour, discharge clear, crab carcasses in pipe upstream of sample
							Aug 17, 2009	200912403	6	100	dry	no odour, discharge clear
							Jan 21, 2010	201011106	40	12	wet	no odour, discharge clear
							Aug 26, 2010	201013019	5	116	dry	no odour, discharge clear
0428A	9	300	AHWL	rock beach	4m north of top of stairs at foot of Amity Dr.	North Saanich						
							Mar 09, 2006	200610591	5	272	wet	no odour, discharge clear
							Aug 16, 2006	200611741	0		dry	dry, not sampled
							Jan 23, 2007	200710078	15	40	wet	no odour, discharge clear
							Aug 21, 2007	200712073			dry	wet only, not sampled
0430	9	ditch	AHWL	rocky beach	ditch at south end of Bazan Bay Park	North Saanich						
							Mar 09, 2006	200610593	150	445	wet	no odour, discharge clear
							Aug 16, 2006	200611742	35	15	dry	no odour, discharge clear
							Jan 23, 2007	200710079	150	458	wet	no odour, discharge clear
							Aug 27, 2007	200711575	25	90	dry	no odour, discharge clear
0430A	9		AHWL		10 m north of grass area at foot of beach access f	North Saanich						
							Mar 09, 2006	200610594	35	110	wet	
							Aug 16, 2006	200611744	0		dry	dry, not sampled
0430AA	9			rocky beach	Cy Hampton Park 10 m south of three picnic tables	North Saanich						
							Jan 23, 2007	200710081	20	13	wet	no odour, discharge clear
							Aug 27, 2007	200712074	0		dry	dry, not sampled
							Jan 29, 2008	200811113	10	19	wet	no odour, discharge clear
							Sep 18, 2008	200812980	0		dry	dry, not sampled
							Feb 18, 2010	201011302	8	1	wet	no odour, discharge clear
							Aug 26, 2010	201013035			dry	wet only, not sampled
0431	9	600	AHWL	beach	Bazan Bay Park 20 m north of dirt path	North Saanich						
							Mar 09, 2006	200610595	120	120	wet	no odour, discharge clear
							Aug 16, 2006	200611743	45	1000	dry	no odour, discharge dark brown
							Jan 23, 2007	200710080	200	10	wet	no odour, discharge clear
							Aug 27, 2007	200711576	40	90	dry	no odour, discharge clear
0432	10	600	AHWL	beach	foot of Bazan Bay Rd.	North Saanich						
							Mar 09, 2006	200610596	200	329	wet	no odour, discharge clear
							Aug 16, 2006	200611745	25	190	dry	no odour, discharge clear
							Jan 23, 2007	200710082	250	> 44	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Aug 27, 2007	200711577	45	60	dry	no odour, discharge clear
0435	10	1100	AHWL	sand/gravel flat	50 m south of 9211 Lochside Dr.	North Saanich						
							Mar 09, 2006	200610597	200	949	wet	no odour, discharge clear
							Aug 16, 2006	200611746	70	13	dry	no odour, discharge clear
							Jan 23, 2007	200710083	200	179	wet	no odour, discharge clear
							Aug 27, 2007	200711570	100	70	dry	no odour, discharge clear
							Aug 26, 2010	201013016	10	2	dry	no odour, discharge clear
0437	10	600	AHWL	sand/gravel flat	9211 Lochside Dr. right of way	North Saanich						
							Mar 09, 2006	200610598	5	130	wet	no odour, discharge clear
							Aug 16, 2006	200611748	0		dry	dry, not sampled
0441	10	stream	AHWL	estuary	Reay Creek, beach access across from 9265 Lochside	North Saanich						
							Apr 19, 2006	200610826	90	4	wet	no odour, discharge slightly amber
							Sep 13, 2006	200612104	30	16	dry	no odour, discharge clear
							Mar 28, 2007	200710743	200	19	wet	no odour, discharge clear
							Sep 20, 2007	200712197	40	70	dry	no odour, discharge clear
							Feb 18, 2008	200811308	200	775	wet	no odour, discharge clear
							Jun 20, 2008	200811933	60	89	dry	no odour, discharge clear
							Mar 05, 2009	200911294	80	20	wet	no odour, discharge clear
							Sep 23, 2009	200912704	20	58	dry	no odour, discharge clear
							Feb 11, 2010	201011205	100	96	wet	no odour, discharge clear
							Sep 02, 2010	201013080	40	110	dry	no odour, discharge clear
0442	10	600	AHWL	sand/gravel beach	9334 Lochside Dr. beach access	North Saanich						
							Mar 09, 2006	200610599	15	1038	wet	no odour, discharge clear
							Sep 14, 2006	200612111	0		dry	dry, not sampled
							Jan 23, 2007	200710084	20	205	wet	petroleum odour, discharge medium brown and oily
							Aug 27, 2007	200711759	0		dry	dry, not sampled
							Jan 31, 2008	200811128	20	42	wet	no odour, discharge clear
							Sep 18, 2008	200812981	0		dry	dry, not sampled
							Mar 11, 2009	200911309			wet	wet only, not sampled
							Aug 17, 2009	200912404	0		dry	dry, not sampled
							Feb 18, 2010	201011303	8	1	wet	no odour, discharge clear
							Aug 26, 2010	201013036	0		dry	dry, not sampled
0443	10		AHWL	sand/gravel flat	9348 Lochside Dr.	Sidney						

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jan 23, 2007	200710085	8	2800	wet	no odour, discharge light brown
							Apr 25, 2007	200712190	0		wet	dry, not sampled
							Aug 27, 2007	200711758	0		dry	dry, not sampled
							Jan 31, 2008	200811127	5	600	wet	no odour, discharge clear
							Sep 18, 2008	200812982	0		dry	dry, not sampled
							Mar 11, 2009	200911480	0		wet	dry, not sampled
							Aug 17, 2009	200912405	0		dry	dry, not sampled
							Mar 26, 2010	201011802	1	2	wet	no odour, discharge clear
							Aug 26, 2010	201013037			dry	wet only, not sampled
0444	11	450	AHWL	sand/gravel beach	across from 9360 Lochside Dr.	Sidney						
							Jan 23, 2007	200710086	20	4	wet	no odour, discharge clear
							Aug 27, 2007	200711756	0		dry	dry, not sampled
0444A	11	300	AHWL	sand/gravel beach	12m south of steps across from 9388 Lochside Dr.	Sidney						
							Jan 23, 2007	200710087	40	0	wet	no odour, discharge clear
							Aug 27, 2007	200711757	0		dry	dry, not sampled
0445	11	600	AHWL	sand/gravel beach	20m north of steps across from 9388 Lochside Dr.	Sidney						
							Mar 09, 2006	200610600	10	1800	wet	no odour, discharge clear
							May 16, 2006	200611026	5	0	wet	no odour, discharge clear
							Aug 16, 2006	200611749	0		dry	dry, not sampled
							Jan 23, 2007	200710088	10	51	wet	no odour, discharge clear
							Aug 27, 2007	200711579	1	600	dry	no odour, discharge clear
							Jan 30, 2008	200811114	15	4	wet	no odour, discharge clear
							Sep 18, 2008	200812983			dry	wet only, not sampled
							Mar 11, 2009	200911470	5	6	wet	no odour, discharge clear
							Aug 17, 2009	200912406	1	144	dry	no odour, discharge clear
							Feb 18, 2010	201011304	8	20	wet	no odour, discharge clear
							Aug 26, 2010	201013021	2	12	dry	no odour, discharge clear
0446	11	600	AHWL	sand/gravel beach	15m south of beach access below 9462 Lochside Dr.	Sidney						
							Mar 09, 2006	200610601	5	140	wet	no odour, discharge clear
							Aug 16, 2006	200611747	5	120	dry	no odour, discharge clear
							Jan 23, 2007	200710089	35	19	wet	no odour, discharge clear
							Aug 27, 2007	200711599	5	50	dry	no odour, discharge clear
0447A	11	200	AHWL	sand/gravel beach	beach access at 9498 Lochside Dr.	Sidney						
							Mar 17, 2008	200811743	1	845	wet	no odour, discharge clear
							Sep 18, 2008	200812984	0		dry	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 11, 2009	200911481	0		wet	dry, not sampled
							Sep 24, 2009	200912756	1	12	dry	no odour, discharge clear
							Feb 18, 2010	201011305	1	150	wet	no odour, some sediment in discharge
							Aug 26, 2010	201013022	1	100	dry	no odour, discharge clear
0448	11	600	AHWL	sand/gravel beach	foot of Weiller Rd., Tulista Park	Sidney						
							Mar 09, 2006	200610604		360	wet	
							Aug 16, 2006	200611751			dry	wet, not sampled
							Jan 29, 2007	200710128	20	0	wet	no odour, discharge clear
							Sep 12, 2007	200711702	8	800	dry	no odour, discharge clear
							Jan 30, 2008	200811115	8	4	wet	no odour, discharge clear
							Sep 18, 2008	200812623	1	8200	dry	no odour, discharge clear
							Oct 27, 2008	200812655	1	120	dry	no odour, discharge clear
							Nov 13, 2008	200812856	5	56	dry	no odour, foamy clear discharge
							Mar 11, 2009	200911471	2	1000	wet	no odour, discharge clear
							Mar 24, 2009	200911579	5	18	wet	no odour, discharge clear
							May 21, 2009	200911887	6	200	wet	no odour, discharge slight amber, sudsy on beach
							Aug 17, 2009	200912407	1	4	dry	no odour, discharge clear
							Mar 26, 2010	201011803	8	8	wet	no odour, discharge clear
							Aug 18, 2010	201012922	1	94	dry	no odour, discharge clear
0449	11	ditch	I	sand/gravel beach	ditch along west and south side of Tulista Park	Sidney						
							Mar 09, 2006	200610603	0	275	wet	
							Aug 16, 2006	200611750			dry	wet, not sampled
							Apr 02, 2007	200710769	75	50	wet	no odour, discharge clear
							May 31, 2007	200711025	30	240	wet	no odour, discharge clear
							Sep 12, 2007	200711703	20	1000	dry	no odour, discharge clear
							Mar 17, 2008	200811742	30	307	wet	sewage odour, discharge clear
							Aug 14, 2008	200812119	15	1000	dry	no odour, discharge clear
							Mar 11, 2009	200911472	15	22	wet	no odour, discharge clear, river otter entered culvert after sampling
							Apr 23, 2009	200911809	15	94	wet	no odour, discharge clear
							Sep 25, 2009	200912765	6	600	dry	no odour, discharge clear
							Nov 27, 2009	200913061	30	75	wet	no odour, discharge clear
							Feb 18, 2010	201011307	16	670	wet	no odour, discharge clear
							Aug 18, 2010	201012921	4	13200	dry	no odour, discharge clear
							Sep 02, 2010	201013066	4	1000	dry	no odour, discharge clear
							Oct 07, 2010	201013364	4	400	dry	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Nov 04, 2010	201013480	10	108	dry	no odour, discharge clear
0449A	11	1200	BLWL	sand/gravel beach	manhole located at corner of Oakville and Eighth S	Sidney						
							Mar 11, 2009	200911473	10	1000	wet	no odour, discharge clear
							Apr 23, 2009	200911808	10	600	wet	slight chemical odour, discharge murky brown
							Aug 17, 2009	200912408	2	44800	dry	no odour, discharge clear
							Oct 15, 2009	200912822	10	288	wet	no odour, discharge clear, sampled from pooled water
							Feb 18, 2010	201011308	4	350	wet	no odour, discharge clear
							Aug 18, 2010	201012920	4	200	dry	no odour, discharge clear
							Oct 07, 2010	201013366	4	60	dry	slight perfume odour, discharge clear
0450	11	900	I	gravel beach	below Ocean Ave. and Second St. intersection	Sidney						
							Mar 09, 2006	200610605		2200	wet	
							Aug 16, 2006	200611752	5	245	dry	no odour, discharge clear
							Apr 02, 2007	200710770	35	100	wet	no odour, discharge clear
							Sep 12, 2007	200711705	15	30	dry	no odour, slightly murky
							Jan 30, 2008	200811116	15	39	wet	no odour, discharge clear
							Aug 14, 2008	200812256	15	1600	dry	no odour, discharge clear
							Mar 11, 2009	200911426	15	34	wet	no odour, discharge clear
							Aug 17, 2009	200912409	18	86	dry	no odour, discharge clear
							Feb 18, 2010	201011309	20	130	wet	no odour, discharge clear
							Aug 26, 2010	201013023	20	800	dry	no odour, discharge clear
0451	11	400	I	gravel beach	north of 450 below Ocean Ave. and Second St. intersection	Sidney						
							Apr 02, 2007	200710771	30	10	wet	no odour, discharge clear
							Sep 12, 2007	200711704	5	2600	dry	no odour, discharge murky
							Jan 30, 2008	200811117	8	< 1	wet	no odour, discharge clear
							Aug 14, 2008	200812257	10	24	dry	no odour, discharge clear
							Mar 11, 2009	200911427	10	0	wet	no odour, discharge clear
							Aug 17, 2009	200912118	10	84	dry	no odour, discharge clear
							Feb 18, 2010	201011310	10	1	wet	no odour, discharge clear
							Aug 26, 2010	201013024	4	20	dry	no odour, discharge clear
0456	12	200	AHWL	grass/shrub bank	Eastview Dr., 10 m north of concrete sea wall	Sidney						
							Mar 09, 2006	200610609	0		wet	dry, not sampled
							Aug 16, 2006	200611753	0		dry	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
0456A	12	200			at beginning of concrete wall, 20 m north of condos near Eastview Park		Mar 09, 2006	200610608	0		wet	dry, not sampled
							Aug 16, 2006	200612306	0		dry	dry, not sampled
							Jan 30, 2008	200812964	0		wet	dry, not sampled
							Sep 18, 2008	200812985	0		dry	dry, not sampled
0457	12	200	AHWL	grassy bank	north end of Eastview Park, south of government d	Sidney	Jan 31, 2008	200811129	8	35	wet	no odour, discharge clear
							Aug 14, 2008	200812258	0		dry	dry, not sampled
0458	12	400	I	riprap	foot of Beacon Ave. below Sidney Museum	Sidney	Feb 18, 2010	201011311	30	10	wet	no odour, discharge clear
							Aug 26, 2010	201013025	12	< 1	dry	no odour, discharge clear
0458A	12	200	I	riprap	end of Seaport Rd., west side of Rumrunner Pub	Sidney	Feb 22, 2006	200610338	1	40	wet	no odour, discharge reddish-brown
							Aug 17, 2006	200611776	10	172800	dry	no odour, discharge clear
							Sep 15, 2006	200612138	5	553600	dry	foul odour, discharge clear
							Sep 19, 2006	200612083	15	36000	dry	no odour, discharge clear
							Jan 23, 2007	200710096	15	203200	wet	no odour, discharge clear
							Sep 12, 2007	200711713	1	2000	dry	slight sewage odour, discharge clear
							May 15, 2008	200811812	3	9600	wet	strong cresote odour, discharge clear
							Aug 14, 2008	200812259	1	337600	dry	sewage odour, discharge clear
							Nov 12, 2008	200812850	2	12000	dry	no odour, discharge clear
							Mar 11, 2009	200911474	1	168000	wet	no odour, discharge clear
							May 21, 2009	200911885	1	600	wet	sulphur odour, discharge clear
							Aug 17, 2009	200912119	6	1800	dry	no odour, discharge clear
							Nov 17, 2009	200912999	4	1000	wet	no odour, discharge clear
							Nov 26, 2009	200912517	6	262400	wet	no odour, discharge clear
Dec 16, 2009	200913100	12	650	wet	no odour, discharge clear							
Jan 21, 2010	201011136	1	18800	wet	no odour, discharge clear							
Aug 26, 2010	201013026	1	28	dry	no odour, discharge clear							
0458B	12	450	I	riprap	foot of Seaport Pt., 10 m north of dock access of	Sidney						

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Feb 27, 2008	200812966	0		wet	dry, not sampled
							Aug 14, 2008	200812975			dry	wet only, not sampled
0458C	12	200	I	riprap	west of Seaport, west end of wood posts near rock	Sidney						
							Feb 27, 2008	200812967	0		wet	dry, not sampled
							Aug 14, 2008	200812976			dry	wet only, not sampled
0459	12	200	I	rock/sand/gravel beach	behind 9901-3rd St. parking lot, 20 m south of beach access	Sidney						
							Mar 13, 2006	200610606	15	32	wet	no odour, discharge clear
							Aug 16, 2006	200611755	0		dry	dry, not sampled
0464	12	250	BLWL	gravel beach	foot of Rothesay Rd. beach access	Sidney						
							Jan 16, 2006	200610016		50	wet	no odour, discharge clear
							Aug 16, 2006	200611756			dry	wet, not sampled
0465	12	300	AHWL	rock/gravel beach	access foot of Rothesay beach	Sidney						
							Jan 29, 2007	200710131			wet	wet, not sampled
							Sep 12, 2007	200711751	0		dry	dry, not sampled
0466	12	350	AHWL	gravel/rocky beach	Memory Lane beach access at end of Shoreacres Rd.	Sidney						
							Jan 29, 2007	200710129	25	2	wet	no odour, discharge clear
							Sep 12, 2007	200711712	20	53	dry	no odour, discharge clear
0467	12	250	AHWL	rock/gravel beach	beach access at foot of Shoreacres Rd. and Memory	Sidney						
							Mar 13, 2006	200610613			wet	wet, not sampled
							Aug 16, 2006	200611758	0		dry	dry, not sampled
0468	13	250	AHWL	rock/sand/gravel beach	beach access at Amherst	Sidney						
							Mar 11, 2009	200911482			wet	wet only, not sampled
							Sep 23, 2009	200912710			dry	wet only, not sampled
							Feb 18, 2010	201011312	2	1	wet	no odour, discharge clear
							Aug 26, 2010	201013029	2	84	dry	no odour, discharge clear
0469	13	300	AHWL	rock/sand/gravel beach	beach access at Amherst, 8 m south of steps	Sidney						
							Jan 29, 2007	200710132	10	0	wet	no odour, discharge clear
							Sep 12, 2007	200711714	3	8	dry	no odour, discharge clear
0471	13	150	I	rock/sand/gravel beach	south of beach access at Surfside Place	Sidney						
							Jan 29, 2007	200710135			wet	wet only, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 12, 2007	200711752	0		dry	dry, not sampled
0472	13	150	I	beach	beach access at Surfside Place, at bottom of steps	Sidney						
							Mar 13, 2006	200610620	0		wet	dry, not sampled
							Aug 16, 2006	200611759	0		dry	dry, not sampled
							Jan 29, 2007	200710133	5	0	wet	no odour, discharge clear
							Sep 12, 2007	200711666	2	4	dry	no odour, discharge clear
							Feb 28, 2008	200811421	1	8	wet	no odour, discharge clear
							Sep 18, 2008	200812986	0		dry	dry, not sampled
							Mar 11, 2009	200911475	1	2	wet	no odour, discharge clear
							Sep 23, 2009	200912706	1	10	dry	no odour, discharge clear, otter feces near eop
							Feb 18, 2010	201011313	2	10	wet	no odour, discharge clear
							Aug 26, 2010	201013028	1	50	dry	no odour, slightly dirty discharge
3001	13	200	AHWL	rock & gravel beach	access at 10232 Sommerset Place, 5 m west of boat	Sidney						
							Feb 19, 2010	201011316	1	98	wet	no odour, discharge clear
							Sep 09, 2010	201013102	1	14	dry	no odour, discharge clear
3002	13	200	AHWL	sand & cobble beach	Robert's Bay beach access at Third St., beside bir	Sidney						
							Feb 27, 2008	200812968	0		wet	dry, not sampled
							Sep 18, 2008	200812987	0		dry	dry, not sampled
3003	13	300	AHWL	sand & cobble beach	Roberts Bay beach access at Third St., 2.5 m west	Sidney						
							Mar 13, 2006	200610612	20	10	wet	no odour, discharge clear
							Aug 16, 2006	200611775			dry	wet, not sampled
3004	13	250	AHWL	sand & cobble beach	beach access at Fifth St. below Roberts Bay bird s	Sidney						
							Jan 29, 2007	200710134			wet	dry, not sampled
							Sep 17, 2007	200712000	0		dry	dry, not sampled
							Feb 28, 2008	200812969	0		wet	dry, not sampled
							Sep 18, 2008	200812988	0		dry	dry, not sampled
							Apr 23, 2009	200911813	0		wet	dry, not sampled
3005	13	stream	AHWL	sand/cobble beach	foot of Fifth St., Mermaid Canal	Sidney						
							Mar 13, 2006	200610615		18	wet	no odour, discharge clear
							Aug 17, 2006	200611777		1200	dry	no odour, discharge clear
							Jan 29, 2007	200710136		36	wet	no odour, discharge clear, flow too large to estimate

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 12, 2007	200711715		280	dry	no odour, discharge clear, pooled water therefore flow not estimated
							Feb 27, 2008	200811149	5	6	wet	no odour, discharge clear
							Sep 18, 2008	200812989			dry	stagnant water therefore not sampled
							Mar 13, 2009	200911492		1400	wet	no odour, discharge clear
							Sep 25, 2009	200912781			dry	stagnant water, no flows downstream
							Feb 19, 2010	201011317	6	92	wet	no odour, discharge clear
							Sep 09, 2010	201013158			dry	wet only, not sampled
3006	13	700	AHWL	rock & gravel beach	foot of Ardwell Ave.	Sidney						
							Mar 13, 2006	200610616	25	63	wet	no odour, discharge clear
							Aug 17, 2006	200611778	3	120	dry	no odour, discharge clear
							Jan 29, 2007	200710137	30	73	wet	no odour, discharge clear
							Sep 12, 2007	200711711	3	2	dry	no odour, discharge clear
							Feb 28, 2008	200811420	8	20	wet	no odour, discharge clear
							Sep 18, 2008	200812638	5	2600	dry	no odour, discharge clear
							Mar 13, 2009	200911493	25	1000	wet	no odour, discharge clear
							Sep 23, 2009	200912707	2	216	dry	no odour, discharge clear
							Feb 19, 2010	201011318	16	124	wet	no odour, discharge clear
							Sep 09, 2010	201013103	4	4400	dry	no odour, discharge clear
							Sep 15, 2010	201013176	4	400	dry	no odour, discharge clear
3006A	14	100	AHWL		foot of Bowden, 10 m west of beach access stairs	Sidney						
							Mar 13, 2006	200610622	0		wet	dry, not sampled
							Aug 17, 2006	200611780	0		dry	dry, not sampled
3007	14	250	AHWL	rock & gravel beach	foot of Bowden, 9 m west of beach access	Sidney						
							Jan 29, 2007	200710138	10	0	wet	no odour, discharge clear
							Sep 12, 2007	200711716	1	8	dry	no odour, discharge clear
3008A	14	150	AHWL	rock	south side of 10465 Allbay Rd.	Sidney						
							Mar 27, 2009	200911677	8	0	wet	no odour, discharge clear
							Sep 23, 2009	200912711	0		dry	dry, not sampled
							Feb 19, 2010	201011319	4	1	wet	no odour, discharge clear
							Sep 09, 2010	201013104	2	< 1	dry	no odour, discharge clear
3008B	14	150	AHWL	rock	south side of 10471 Allbay Rd.	Sidney						
							Mar 27, 2009	200911678	0		wet	dry, not sampled
							Sep 23, 2009	200912712	0		dry	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Feb 19, 2010	201011361	0		wet	dry, not sampled
							Sep 09, 2010	201013159	0		dry	dry, not sampled
3008BA	14	150		rock	In front of 10471 Allbay Road	Sidney						
							Mar 27, 2009	200911679	0		wet	dry, not sampled
							Sep 23, 2009	200912713	0		dry	discharge buried, no flows seen in area of discharge
							Feb 19, 2010	201011362	0		wet	dry, not sampled
							Sep 09, 2010	201013160	0		dry	dry, not sampled
3008C	14	150	AHWL	rock	north side of 10471 Allbay Rd.	Sidney						
							Mar 27, 2009	200911680	0		wet	dry, not sampled
							Sep 23, 2009	200912714	0		dry	dry, not sampled
							Feb 19, 2010	201011363	0		wet	dry, not sampled
							Sep 09, 2010	201013161			dry	wet only, not sampled
3009	14	150	AHWL	rock beach	foot of Allbay Rd., 5 m west from bedrock outcrop	Sidney						
							Mar 13, 2006	200610618	8	83	wet	no odour, discharge clear
							Aug 17, 2006	200611781	0		dry	dry, not sampled
							Jan 23, 2007	200710090	20	0	wet	no odour, discharge clear
							Sep 12, 2007	200711754	0		dry	dry, not sampled
							Feb 28, 2008	200811426	1	< 1	wet	no odour, discharge clear
							Sep 18, 2008	200812990	0		dry	dry, not sampled
							Mar 13, 2009	200911495	1	0	wet	no odour, discharge clear
							Sep 23, 2009	200912715	0		dry	dry, not sampled
							Feb 19, 2010	201011320	1	1	wet	no odour, discharge clear
							Sep 09, 2010	201013105	1	4	dry	no odour, discharge clear
3011	14	150	AHWL	riprap	foot of Bowden Rd., 3 m from wharf access in ripra	Sidney						
							Mar 11, 2009	200911479	12	0	wet	no odour, discharge clear
							Sep 24, 2009	200912757	6	0	dry	no odour, discharge clear
							Feb 19, 2010	201011321	1	1	wet	no odour, discharge clear
							Sep 09, 2010	201013106	2	< 1	dry	no odour, discharge clear
3013	14	200	AHWL	riprap	foot of Griffith near Blue Peter Pub, 3 m east of	Sidney						
							Mar 11, 2009	200911483			wet	wet only, not sampled
							Sep 24, 2009	200912758			dry	wet only, not sampled
							Feb 19, 2010	201011364			wet	wt only, not sampled
							Sep 09, 2010	201013162	0		dry	dry, not sampled

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3013AA		200			in rock wall at foot of Tsehum Rd							
							Sep 15, 2006	200612139	0		dry	dry, not sampled
							Jan 29, 2007	200710140	0		wet	dry, not sampled
							Sep 12, 2007	200711755	0		dry	dry, not sampled
3014	14	500	I	sand flat	eastern pipe, east side of wharf at DFO Small Craft Harbour Branch	Sidney						
							Jan 29, 2007	200710141	30	372	wet	no odour, discharge clear
							Sep 12, 2007	200711708	1	179200	dry	no odour, discharge clear
							Sep 20, 2007	200711843	10	26400	dry	no odour, discharge clear
							Feb 28, 2008	200811428	1	483	wet	no odour, discharge clear
							Aug 14, 2008	200812260	5	19200	dry	onion odour, discharge clear
							Nov 12, 2008	200812852	8	800	dry	no odour, discharge clear
							Mar 11, 2009	200911476	5	14400	wet	no odour, discharge clear
							Apr 24, 2009	200911818	1	16	wet	no odour, discharge clear
							Sep 25, 2009	200912767	2	310	dry	no odour, discharge clear
							Feb 18, 2010	201011314	2	16000	wet	no odour, discharge clear
							Apr 13, 2010	201011896	3	4000	wet	no odour, discharge clear
							Aug 18, 2010	201012736	1	2200	dry	no odour, discharge clear
							Sep 02, 2010	201013063	2	200	dry	no odour, discharge clear
							Sep 17, 2010	201013208	6	1000	dry	no odour, discharge clear
							Oct 08, 2010	201013326	4	645	dry	perfume odour, discharge clear
3015	14	450	I	sand flat	western pipe, east of wharf at DFO Small Craft Harbour Branch	Sidney						
							Mar 23, 2006	200610660	10	8	wet	no odour, discharge clear
							Aug 17, 2006	200611779	5	1600	dry	no odour, discharge clear
							Jan 29, 2007	200710142	20	0	wet	no odour, discharge clear
							Sep 12, 2007	200711707	1	16800	dry	no odour, discharge clear, lots of algae along spillway flow
							Sep 20, 2007	200711844	5	7400	dry	no odour, discharge clear, otter feces above discharge
							Feb 28, 2008	200811429		6	wet	no odour, discharge clear
							Aug 14, 2008	200812261	8	1200	dry	no odour, discharge clear
							Nov 12, 2008	200812854	8	800	dry	no odour, discharge clear
							Mar 11, 2009	200911478	10	2	wet	no odour, discharge clear
							May 15, 2009	200911879	6	267	wet	slight metallic odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3016	14	850	I	mud flat	behind 10462 Resthaven Rd.	Sidney	Sep 25, 2009	200912769		200	dry	no odour, discharge clear
							Feb 18, 2010	201011315	4	30	wet	no odour, discharge clear
							Aug 18, 2010	201012916	1	600	dry	no odour, discharge clear
3017A	14	200	I	sand and silt	Allbay Park, in front of first townhouse along wal	Sidney	Mar 23, 2006	200610658	80	155	wet	no odour, discharge clear
							Aug 17, 2006	200611783	10	117	dry	no odour, discharge clear
							Apr 02, 2007	200710772	30	4200	wet	no odour, discharge clear
							May 24, 2007	200711003	30	0	wet	no odour, discharge clear
							May 31, 2007	200711026	25	236	wet	no odour, discharge clear
							Sep 12, 2007	200711706	15	27200	dry	no odour, discharge clear
							Sep 20, 2007	200711845	10	35200	dry	no odour, discharge clear
							Feb 28, 2008	200811430	20	1876	wet	no odour, discharge clear
							Aug 14, 2008	200812262	5	90	dry	possible sewage odour, discharge clear
							Mar 13, 2009	200911496	15	6000	wet	no odour, discharge clear
							Sep 25, 2009	200912770	8	64	dry	no odour, discharge clear
Feb 11, 2010	201011216	20	800	wet	no odour, discharge clear							
Sep 09, 2010	201013101	8	20800	dry	no odour, discharge clear							
3017B	14	200	I	sand and silt	Allbay Park, halfway between ends of townhouses al	Sidney	Mar 13, 2006	200610619	1	0	wet	no odour, discharge clear
							Aug 17, 2006	200611785	0		dry	dry, not sampled
3017D	14	200	AHWL	rock	northern tip of Peninsula in Tseychum Harbour	Sidney	Apr 02, 2007	200710773	1	< 40	wet	no odour, discharge reddish-brown
							Sep 12, 2007	200711760			dry	wet only, not sampled
3017F	15	150	AHWL	sand and silt	east corner of large block condos at Marina Park M	Sidney	Mar 13, 2009	200911497	1	0	wet	no odour, discharge clear
							Sep 24, 2009	200912759	0	36	dry	no odour, discharge clear
							Feb 19, 2010	201011322	1	1	wet	no odour, discharge clear
							Sep 02, 2010	201013073	1	10	dry	no odour, discharge clear
3017F	15	150	AHWL	sand and silt	east corner of large block condos at Marina Park M	Sidney	Mar 13, 2009	200911498	1	0	wet	no odour, discharge clear
							Sep 25, 2009	200912760			dry	wet only, not sampled
							Feb 19, 2010	201011332	1	1	wet	no odour, discharge clear
							Sep 09, 2010	201013099	1	14	dry	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3018	15	450	I	rocky beach	behind 2056 White Birch, across from north end of	Sidney						
							Apr 02, 2007	200710775	6	9	wet	no odour, discharge clear
							Sep 12, 2007	200711718	1	551	dry	
							Feb 28, 2008	200811432	3	2	wet	no odour, discharge clear
							Aug 14, 2008	200812991			dry	wet only, not sampled
							Mar 24, 2009	200911585	5	200	wet	no odour, discharge clear
							Sep 25, 2009	200912761	2	34	dry	no odour, discharge clear
							Feb 19, 2010	201011333	2	2	wet	no odour, discharge clear
Sep 09, 2010	201013100	2	94	dry	no odour, discharge clear							
3020	15	1000	AHWL	mud flat	east of Capital City Yacht Club below Blue Heron Rd	North Saanich						
							Mar 23, 2006	200610657	25	195	wet	no odour, discharge clear
							Aug 17, 2006	200611784	15	574	dry	no odour, discharge clear
							Apr 02, 2007	200710776	60	400	wet	no odour, discharge clear
							Sep 12, 2007	200711709	15	44	dry	no odour, discharge clear
							Jan 25, 2008	200811101	20	96	wet	sweet odour, discharge clear
							Aug 14, 2008	200812263	8	28	dry	no odour, discharge clear
							Feb 19, 2010	201011323	4	8	wet	no odour, discharge clear
Sep 09, 2010	201013107	2	200	dry	no odour, discharge clear							
3021	15	600	AHWL	mud flat	near corner of McDonald Park Rd., Bayfield Rd.	North Saanich						
							Mar 22, 2006	200610703	35	63	wet	no odour, discharge clear
							Aug 17, 2006	200611786	20	465	dry	no odour, discharge clear
							Jan 30, 2007	200710143	30	6	wet	no odour, discharge clear
							Sep 12, 2007	200711710	20	56	dry	no odour, discharge clear
							Mar 17, 2008	200811740	60	< 1	wet	no odour, discharge clear
							Aug 14, 2008	200812264	25	26	dry	no odour, discharge clear
3021A	16		AHWL	mud and clay	1835 Marina Drv, southwest corner of North Saanich Marina	North Saanich						
							Jan 18, 2006	200610048	15	1800	wet	no odour, discharge clear
							Aug 31, 2006	200611882	5	3240	dry	no odour, discharge clear
							Jan 05, 2007	200710034	45	600	wet	no odour, discharge clear
							May 31, 2007	200711027	5	3200	wet	no odour, discharge slightly murky
							Sep 12, 2007	200711719	1	3800	dry	no odour, discharge murky
							Jan 25, 2008	200811095	5	42	wet	no odour, discharge slightly turbid

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Aug 14, 2008	200812266	5	4	dry	no odour, slightly turbid discharge
							Jan 15, 2009	200911015	15	66	wet	no odour, discharge clear
							Jan 22, 2009	200911078	15	178	wet	no odour, discharge clear
							Mar 11, 2009	200911420	15	600	wet	no odour, discharge clear
							Mar 11, 2009	200911428	15	1000	wet	no odour, discharge clear
							Sep 24, 2009	200912762	2	2200	dry	no odour, discharge clear
							Nov 18, 2009	200913012	8	122	wet	no odour, discharge clear
							Jan 21, 2010	201011124	12	1800	wet	no odour, discharge clear
							Sep 09, 2010	201013108	3	3200	dry	no odour, discharge clear
3022	16	300	I	mud flat	North Saanich Marina, 6 m west from parking area	North Saanich						
							Mar 31, 2010	201011846	10	36	wet	strong sulphur odour, discharge clear
							Sep 09, 2010	201013163			dry	wet only, not sampled
3028	16	900	AHWL	mud flat	McDonald Park Rd. & Highway	North Saanich						
							Mar 03, 2008	200811433	25	125	wet	no odour, discharge clear
							Aug 14, 2008	200812992	0		dry	dry, not sampled
							Mar 24, 2009	200911586	12	4	wet	no odour, discharge clear
							Sep 24, 2009	200912763	10	16	dry	no odour, discharge clear
3030	16	550	AHWL	mud flat	200 m north of pedestrian overpass, past McDonald	North Saanich						
							Mar 31, 2010	201011848	16	96	wet	no odour, discharge clear
							Sep 09, 2010	201013164			dry	wet only, not sampled
3032	16	600	AHWL	mud flat	south of Lands End Road signage on Pat Bay Hwy.	North Saanich						
							Mar 03, 2008	200811434	3	43	wet	no odour, discharge clear
							Aug 14, 2008	200812993			dry	muddy stagnant water therefore not sampled
3034	16	200	AHWL	mud flat	foot of Swartz Bay Rd. near highway	North Saanich						
							Mar 03, 2008	200811435	7	76	wet	no odour, grey discharge and flow intermittent
							Aug 14, 2008	200812994	0		dry	dry, not sampled
3034D	16	500	AHWL	riprap	in riprap north of boat parking lot, north end of Westport Marina	North Saanich						
							Mar 22, 2006	200610705	15	42	wet	no odour, discharge clear
							Aug 31, 2006	200611883	0		dry	dry, not sampled
							Jan 30, 2007	200710144	45	76	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 12, 2007	200711761	0		dry	dry, not sampled
							Mar 03, 2008	200811436	30	1131	wet	no odour, grey discharge
							Aug 14, 2008	200812995	0		dry	dry, not sampled
							Mar 24, 2009	200911587	20	137	wet	no odour, discharge clear
							Sep 24, 2009	200912764	1	140	dry	no odour, discharge clear
							Feb 19, 2010	201011325	6	204	wet	no odour, discharge clear
							Sep 09, 2010	201013140	1	128	dry	no odour, discharge clear
3035A	16	250	AHWL	riprap	Westport Yacht Sales Office, north end of second c	North Saanich						
							Mar 17, 2008	200811739			wet	wet only, not sampled
							Aug 14, 2008	200812996			dry	wet only, not sampled
3035AA	16			rip rap	Below parking lot of West Port Marina Yacht Sales below 3035	North Saanich						
							Mar 17, 2008	200811738	5	< 1	wet	no odour, discharge clear
							Aug 14, 2008	200812997	0		dry	dry, not sampled
							Feb 19, 2010	201011326	3	< 1	wet	no odour, discharge clear
							Sep 09, 2010	201013141	3	< 1	dry	no odour, discharge clear
3035C	17	300	AHWL	rock & gravel beach	west side of foot of Tyron Road	North Saanich						
							Mar 22, 2006	200610706	3	3800	wet	no odour, discharge clear
							Aug 31, 2006	200611884	0		dry	dry, not sampled
							Sep 19, 2006	200612085	1	2600	dry	no odour, discharge clear
							Jan 05, 2007	200710043	35	861	wet	no odour, discharge clear
							Sep 12, 2007	200711762			dry	wet only, not sampled
							Mar 03, 2008	200811439	10	261	wet	no odour, discharge clear
							Aug 14, 2008	200812267	1	6	dry	no odour, discharge clear
							Mar 24, 2009	200911588	1	200	wet	no odour, discharge clear
							Sep 25, 2009	200912772	1	0	dry	no odour, discharge clear
							Jan 21, 2010	201011131	1	23	wet	no odour, discharge clear
							Jan 29, 2010	201011168	1	26	wet	no odour, discharge clear
							Sep 15, 2010	201013177	1	10	dry	no odour, discharge clear
3036	17	250	AHWL	riprap	Inwood Road near Anchor Rd., just south of wharf i	North Saanich						
							Mar 03, 2008	200811440	15	1239	wet	no odour, discharge clear
							Aug 14, 2008	200812998	0		dry	dry, not sampled
							Mar 24, 2009	200911589	10	77	wet	no odour, discharge clear
							Sep 25, 2009	200912773	2	178	dry	no odour, discharge clear
							Feb 19, 2010	201011327	10	158	wet	no odour, discharge clear
							Sep 15, 2010	201013178	6	1000	dry	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3037AA	18	150		rip rap	Canoe Cove Marino 7 m north of D dock in rip rap	North Saanich						
							Mar 03, 2008	200811441	5	465	wet	no odour, discharge clear
							Aug 14, 2008	200812999	0		dry	dry, not sampled
							Mar 24, 2009	200911630	1	4	wet	no odour, discharge clear
							Sep 25, 2009	200912774	0		dry	dry, not sampled
							Feb 19, 2010	201011328	2	4	wet	no odour, discharge clear
Sep 15, 2010	201013260			dry	wet only, not sampled							
3038	18	150	AHWL	riprap	near Yacht Sales shop, between docks D & E, Canoe Cove Marina	North Saanich						
							Mar 24, 2009	200911631	1	4	wet	no odour, discharge clear
							Sep 25, 2009	200912775	0		dry	dry, not sampled
							Feb 19, 2010	201011329	1	5400	wet	no odour, discharge clear
Sep 15, 2010	201013261			dry	wet only, not sampled							
3040	18	300	AHWL	riprap	10m east of B dock, Canoe Cove Marina	North Saanich						
							Mar 03, 2008	200811442	5	< 1	wet	no odour, discharge clear
Aug 14, 2008	200813000	0		dry	dry, not sampled							
3041	18	300	AHWL	riprap	6 m west of A dock, Canoe Cove Marina	North Saanich						
							Mar 24, 2009	200911632	6	0	wet	no odour, discharge clear
							Sep 25, 2009	200912776	0		dry	dry, not sampled
							Feb 19, 2010	201011330	8	2	wet	no odour, discharge clear
Sep 15, 2010	201013262			dry	wet only, not sampled							
3042	18	ditch	AHWL	rocky beach	foot of Barnacle Rd., 5 m east of government dock	North Saanich						
							Mar 24, 2009	200911633	1	2	wet	slight chemical odour, discharge amber
							Sep 25, 2009	200912777	0		dry	dry, not sampled
							Feb 19, 2010	201011331	2	< 1	wet	no odour, discharge clear
Sep 15, 2010	201013263			dry	wet only, not sampled							
3043	18	600	I	riprap	between CP ferry dock & slip 5, Swartz Bay Ferry Terminal	North Saanich						
							Apr 23, 2009	200911810	0		wet	dry, not sampled
							Sep 25, 2009	200912778	0		dry	dry, not sampled
							Mar 31, 2010	201011850			wet	wet only, not sampled
Sep 15, 2010	201013264			dry	wet only, not sampled							
3044	18	250	AHWL	riprap	under slip 4 at Swartz Bay Ferry Terminal	North Saanich						

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Apr 07, 2006	200610830	0		wet	dry, not sampled
							Sep 15, 2006	200612140	0		dry	dry, not sampled
							Jan 31, 2007	200710173	0		wet	dry, not sampled
							Sep 17, 2007	200712002			dry	wet only, not sampled
3045	18	250	AHWL	riprap	between slip 2 & 3 at Swartz Bay Ferry Terminal	North Saanich						
							Apr 07, 2006	200612740			wet	under construction, could not access
							Sep 15, 2006	200612141	0		dry	dry, not sampled
							Jan 31, 2007	200710174	1	0	wet	no odour, discharge clear
							Sep 17, 2007	200712001			dry	wet only, not sampled
3047	18	250	AHWL	riprap	1 m west of metal catwalk at Swartz Bay Ferry Terminal	North Saanich						
							Apr 23, 2009	200911812	0		wet	dry, not sampled
							Sep 25, 2009	200912779	0		dry	dry, not sampled
							Mar 31, 2010	201011849	1	20	wet	no odour, discharge clear
							Sep 15, 2010	201013265	0		dry	dry, not sampled
3048	18	250	AHWL	riprap	in front of concrete pillars at west end Swartz Bay Ferry Terminal	North Saanich						
							Apr 23, 2009	200911811	1	0	wet	no odour, discharge clear
							Sep 25, 2009	200912780	0		dry	dry, not sampled
							Mar 31, 2010	201011851			wet	pipe removed, no flow seen
							Sep 15, 2010	201013266			dry	pipe removed, no flow seen
3049	18	600	AHWL	riprap	below passenger terminal at Swartz Bay Ferry Terminal	North Saanich						
							Apr 07, 2006	200610827	10	8	wet	no odour, discharge clear
							Sep 15, 2006	200612142	0		dry	dry, not sampled
							Jan 31, 2007	200710175	20	0	wet	no odour, discharge clear
							Sep 17, 2007	200712003	0		dry	dry, not sampled
3050	19	600	AHWL	bedrock & rock	right of way from Ravenscroft Place	North Saanich						
							Mar 22, 2006	200610707	10	35	wet	no odour, discharge clear
							Aug 31, 2006	200611889	0		dry	dry, not sampled
							Jan 30, 2007	200710146	30	64	wet	no odour, discharge clear
							Sep 17, 2007	200711857	3	144	dry	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3051	19	stream	AHWL	sand/gravel beach	40m west of large dock at Shearwater Terrace beach access, Queen Mary Bay	North Saanich						
							Mar 24, 2009	200911634	15	0	wet	no odour, discharge clear
							Aug 14, 2009	200912378			dry	wet only, not sampled
							Mar 26, 2010	201011790	40	8	wet	no odour, discharge clear
							Sep 15, 2010	201013180	2	2200	dry	no odour, discharge clear
3052	19	ditch	AHWL	sand/gravel beach	50m west of dock at Shearwater Terrace beach access, Queen Mary Bay	North Saanich						
							Mar 24, 2009	200911636	8	0	wet	no odour, discharge clear
							Aug 14, 2009	200912379	10	56	dry	no odour, discharge clear
							Mar 26, 2010	201011791	8	10	wet	no odour, discharge clear
							Sep 15, 2010	201013181	4	6	dry	no odour, discharge clear
3053	19	250	AHWL	sand/gravel beach	west end of Queen Mary Bay, west of Shearwater Terrace beach access	North Saanich						
							Mar 24, 2009	200911637	6	34	wet	no odour, discharge clear
							Aug 14, 2009	200912380	6	6	dry	no odour, discharge clear
							Mar 26, 2010	201011792	4	< 1	wet	no odour, discharge clear
							Sep 15, 2010	201013183	3	6	dry	no odour, discharge clear
3054	19	stream	AHWL	rocky beach & cliff	foot of Dawson Way	North Saanich						
							Mar 24, 2009	200911638	40	4	wet	no odour, discharge clear
							Aug 14, 2009	200912381	10	148	dry	no odour, discharge clear
							Mar 26, 2010	201011793	40	4	wet	no odour, discharge clear
							Sep 15, 2010	201013184	20	22	dry	no odour, discharge clear
3055	20		AHWL	rock/sand beach	35m east of wharf, Lands End Road & Sylvan Place	North Saanich						
							Mar 03, 2008	200811443	20	4	wet	no odour, discharge clear
							Sep 26, 2008	200812627	15	14	dry	no odour, discharge clear
3057	20	100	AHWL	bank	top of bank at foot of Kew Road	North Saanich						
							Mar 24, 2009	200911639	12	10	wet	no odour, discharge clear
							Aug 14, 2009	200912382	1	6	dry	no odour, discharge clear
							Mar 26, 2010	201011794	6	< 1	wet	no odour, discharge clear
							Sep 15, 2010	201013185	2	8	dry	no odour, discharge clear
3058	20	600	AHWL	sand/gravel/rock beach	road off Lands End Road across from Howcrest Road,	North Saanich						
							Mar 24, 2009	200911640	30	2	wet	no odour, discharge clear
							Aug 14, 2009	200912383	0		dry	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 26, 2010	201011796	10	14	wet	no odour, discharge clear
							Sep 15, 2010	201013267	0		dry	dry, not sampled
3059	20	100	AHWL	sand/gravel beach	Lands End Road, seven lots east of Seabreeze Rd.,	North Saanich						
							Mar 24, 2009	200911641	12	0	wet	no odour, discharge clear
							Aug 14, 2009	200912384	2	18	dry	no odour, discharge clear
							Mar 26, 2010	201011797	2	35	wet	no odour, discharge clear
							Sep 15, 2010	201013186	1	18	dry	no odour, discharge clear
3059A	21	100		sand/gravel/rock beach	East of Jupata Way at base of concrete retaining wall	North Saanich						
							Mar 03, 2008	200812977			wet	dry, not sampled
							Sep 26, 2008	200812970			dry	wet only, not sampled
3059B	21	seepage		sand/gravel/rock beach	East of Jupata Way under log retaining wall	North Saanich						
							Mar 03, 2008	200811444	5	< 1	wet	no odour, discharge clear
							Sep 26, 2008	200812496	3	42	dry	no odour, discharge clear
3059C	21			sand/gravel/rock beach	East of Jupata Way west of first concrete retaining wall	North Saanich						
							Mar 03, 2008	200812971	0		wet	dry, not sampled
							Sep 26, 2008	200813001			dry	wet only, not sampled
3060	21	ditch	AHWL	sand/gravel/rock beach	Jupata Way, 5 m east of boat ramp	North Saanich						
							Mar 24, 2009	200911642	12	2	wet	no odour, discharge clear
							Aug 14, 2009	200912385	2	165	dry	no odour, discharge clear but flow pulsing
							Mar 26, 2010	201011799	8	2	wet	no odour, discharge clear
							Sep 15, 2010	201013187	4	188	dry	no odour, discharge clear
3062	21	ditch	AHWL	gravel/bedrock outcrop	foot of West Saanich Road, near boat house	North Saanich						
							Mar 25, 2009	200911643	8	10	wet	no odour, discharge clear
							Aug 14, 2009	200912386			dry	wet only, not sampled
							Mar 26, 2010	201011800	10	4	wet	no odour, discharge clear
							Sep 15, 2010	201013268	0		dry	dry, not sampled
3064	21	600	AHWL	bedrock outcrop and gravel beach	east of beach access steps at Kingfisher Road	North Saanich						
							Mar 25, 2009	200911644	8	44	wet	no odour, discharge clear
							Aug 14, 2009	200912387			dry	wet only, not sampled
							Mar 26, 2010	201011801	8	143	wet	no odour, discharge clear
							Sep 15, 2010	201013188	6	200	dry	no odour, discharge clear

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3076	23	350	AHWL	rocky beach	200 m west of beach access at foot of Tatlow Road	North Saanich						
							Mar 25, 2009	200911645	10	10	wet	no odour, discharge clear
							Jul 24, 2009	200912161	0		dry	dry, not sampled
							Feb 17, 2010	201011288	12	40	wet	no odour, discharge clear
							Sep 15, 2010	201013269	0		dry	dry, not sampled
3077	23	250	AHWL	rocky beach	50 m west of beach access at Tatlow Road	North Saanich						
							Jan 27, 2006	200610114	8	780	wet	no odour, discharge clear
							Aug 31, 2006	200611885	12	960	dry	no odour, discharge clear
							Apr 02, 2007	200710782	25	50	wet	no odour, discharge clear
							Sep 17, 2007	200711858	3	38	dry	no odour, discharge clear
							Mar 11, 2008	200811680	8	110	wet	no odour, discharge clear
							Sep 26, 2008	200812676	8	80	dry	no odour, discharge clear
							Jul 24, 2009	200912190	8	10400	dry	no odour, discharge clear
							Oct 15, 2009	200913824	2	243	wet	no odour, discharge clear
							Feb 17, 2010	201011289	12	3800	wet	no odour, discharge clear
							Apr 13, 2010	201011900	4	55	wet	no odour, discharge clear
							Aug 18, 2010	201012923	1	800	dry	no odour, discharge clear
							Aug 30, 2010	201013048	2	190	dry	no odour, discharge clear
							Oct 28, 2010	201013425	6	1000	dry	no odour, discharge clear
3077A		100			Foot of Tatlow beach access east of 3077 (incorrectly labelled 3076)	North Saanich						
							Mar 25, 2009	200911647	16	0	wet	
							Jul 24, 2009	200912191	10	88	dry	no odour, discharge clear
							Feb 17, 2010	201011290	4	< 1	wet	no odour, discharge clear
							Aug 30, 2010	201013047	3	1200	dry	no odour, discharge clear
3078	23	350	AHWL	rocky beach	beach access at foot of Tatlow Road	North Saanich						
							Mar 11, 2008	200811682	5	179	wet	no odour, discharge clear
							Sep 26, 2008	200812677	5	5600	dry	no odour, discharge clear
							Mar 25, 2009	200911646	4	0	wet	no odour, discharge clear
							Apr 24, 2009	200911821	30	0	wet	no odour, discharge clear
							Jul 24, 2009	200912194	8	185	dry	no odour, discharge clear
							Feb 17, 2010	201011291	8	26	wet	no odour, discharge clear
							Aug 30, 2010	201013130			dry	wet only, not sampled
							Nov 04, 2010	201013485	4	88	dry	no odour, discharge clear
							3078B		100			Foot of Tatlow, north of Tatlow creek in rock wall

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jul 24, 2009	200911557	10	23200	dry	no odour, discharge yellow with brown scum
							Aug 14, 2009	200912388	1	36800	dry	no odour, discharge clear
							Nov 18, 2009	200913010	2	57	wet	no odour, discharge clear
							Feb 17, 2010	201011281	12	27	wet	no odour, discharge clear
							Aug 18, 2010	201012918	0		dry	dry, not sampled
							Oct 07, 2010	201013380	0		dry	dry, not sampled
3079	23	stream	AHWL	rocky beach	beach access at foot of Tatlow Road, Tatlow Creek	North Saanich						
							Apr 19, 2006	200610829	50	44	wet	no odour, discharge light amber
							Aug 31, 2006	200611886	20	10	dry	no odour, discharge clear
							Feb 28, 2007	200710337	90	140	wet	no odour, discharge light brown
							Sep 05, 2007	200711641	35	2800	dry	no odour, discharge clear
							Feb 18, 2008	200811307	200	131	wet	no odour, discharge clear
							Jul 29, 2008	200812340	10	17	dry	sewage/swampy odour, discharge clear
							Mar 06, 2009	200911406	200	50	wet	no odour, discharge slightly murky
							Jul 24, 2009	200912192	18	2200	dry	no odour, discharge slight amber
							Oct 15, 2009	200912826	40	151	wet	no odour, discharge clear
							Feb 17, 2010	201011286	200	84	wet	no odour, discharge clear
							Sep 10, 2010	201013156	12	108	dry	no odour, discharge clear
							Oct 07, 2010	201013368	12	160	dry	no odour, discharge clear
							Oct 28, 2010	201013423	30	160	dry	no odour, discharge clear
3080	24	300			foot of Danton Road	North Saanich						
							Mar 22, 2006	200610708	20	82	wet	no odour, discharge clear
							Aug 31, 2006	200611900			dry	wet, not sampled
							Jan 30, 2007	200710147	35	37	wet	no odour, discharge clear
							Sep 17, 2007	200712004			dry	wet only, not sampled
3080A	24	creek	I		Bennes Creek, 10992 Kalitan Rd., under concrete stairs	North Saanich						
							Mar 22, 2006	200610709	100	214	wet	no odour, discharge clear
							Sep 22, 2006	200612204	40	6000	dry	no odour, discharge clear
							Jan 30, 2007	200710156	100	122	wet	no odour, discharge clear
							May 31, 2007	200711032	25	11200	dry	no odour, discharge clear
							Sep 05, 2007	200711639	20	1440	dry	no odour, discharge clear
							Mar 11, 2008	200811684	200	424	wet	no odour, discharge clear
							Sep 17, 2008	200812624	5	230	dry	no odour, discharge clear

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 26, 2010	201011781	50	800	wet	no odour, discharge clear
							Sep 10, 2010	201013155	3	84	dry	no odour, discharge clear
3080B	24	300	AHWL		568 Meldram Drv., pipe in ditch at right of way	North Saanich						
							Mar 22, 2006	200610710	5	13600	wet	no odour, discharge clear
							Aug 31, 2006	200611902	0		dry	dry, not sampled
							Jan 05, 2007	200710049	35	803	wet	no odour, discharge clear
							May 31, 2007	200711030	5	36	wet	no odour, discharge clear
							Sep 05, 2007	200711640	5	1000	dry	no odour, discharge clear
							Mar 11, 2008	200811683	15	10	wet	no odour, discharge clear
							Sep 17, 2008	200813002			dry	wet only, not sampled
							Mar 25, 2009	200911648	6	800	wet	no odour, discharge clear
							Aug 14, 2009	200912389	1	1200	dry	no odour, discharge clear
							Mar 26, 2010	201011780	2	200	wet	no odour, discharge clear
							Sep 10, 2010	201013154	1	336	dry	slight sewage odour, discharge clear
3080C	24	100		rock/gravel beach	west side of Deep Cove Marina parking lot							
							Jan 30, 2007	200710148	20	2	wet	no odour, discharge clear
							Sep 17, 2007	200712005			dry	wet only, not sampled
3082	24	600	AHWL	rock/gravel beach	west side of Deep Cove Marina at foot of Deep Cove Rd	North Saanich						
							Mar 22, 2006	200610711	20	834	wet	no odour, discharge clear
							Aug 31, 2006	200611888	20	18	dry	no odour, discharge clear
							Jan 30, 2007	200710149	50	148	wet	no odour, discharge clear
							Aug 28, 2007	200711560	15	2200	dry	no odour, discharge clear
							Mar 11, 2008	200811686	150	183	wet	no odour, discharge clear
							Sep 17, 2008	200812626	5	80800	dry	no odour, discharge clear
							Mar 25, 2009	200911649	30	0	wet	no odour, discharge clear
							Apr 24, 2009	200911825	12	0	wet	no odour, discharge clear
							May 21, 2009	200911891	12	0	wet	no odour, discharge clear
							Aug 14, 2009	200912390	4	98	dry	no odour, discharge clear
							Mar 26, 2010	201011777	30	24	wet	no odour, discharge clear
							Aug 18, 2010	201012924	1	74	dry	no odour, discharge clear
3082A	24	300	AHWL	rock/gravel beach	top of rock wall at foot of Deep Cove Rd	North Saanich						
							Mar 22, 2006	200610713	3	2400	wet	no odour, discharge clear
							Aug 31, 2006	200611903	0		dry	dry, not sampled
							Jan 30, 2007	200710150	3	0	wet	no odour, discharge clear
							Aug 28, 2007	200712076	0		dry	dry, not sampled
							Mar 14, 2008	200811615			wet	wet only, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 17, 2008	200813003	0		dry	dry, not sampled
3082AA	24	100			2 m east of concrete stairs at 10986 Madrona Drv							
							Mar 22, 2006	200610712	2	2000	wet	no odour, discharge clear
							Sep 22, 2006	200612203	5	482	dry	no odour, discharge clear
							Mar 27, 2010	201011778			wet	wet only, not sampled
							Sep 10, 2010	201013165			dry	wet only, not sampled
3082AB	24				west of boathouse on rock pilings at Deep Cove Marina							
							Sep 22, 2006	200612202	20	610	dry	no odour, discharge clear
							Jan 30, 2007	200710151			wet	wet only, not sampled
							Sep 28, 2007	200712075	0		dry	dry, not sampled
3083	24	stream	AHWL	bedrock outcrop and rock/gravel beach	2m west of stairs below Wain Road & Madrona Drive	North Saanich						
							Mar 22, 2006	200610715			wet	wet, not sampled
							Aug 31, 2006	200611904	0		dry	dry, not sampled
3084	24	250	AHWL	cobble beach	150 m north of Cromar Road	North Saanich						
							Jan 16, 2006	200610024	70	4400	wet	no odour, discharge brownish
							Mar 23, 2006	200610652	65	33	wet	sewage odour, discharge clear
							Aug 31, 2006	200611905	0		dry	dry, not sampled
							Jan 30, 2007	200710160	50	155	wet	no odour, discharge clear
							Aug 28, 2007	200712077	0		dry	dry, not sampled
							Mar 11, 2008	200811685	30	3010	wet	no odour, discharge clear
							Mar 14, 2008	200811617	15	310	wet	no odour, discharge clear
							Sep 17, 2008	200813004	0		dry	dry, not sampled
							Mar 25, 2009	200911650	8	10	wet	no odour, discharge clear
							Aug 14, 2009	200912391	0		dry	dry, not sampled
							Mar 26, 2010	201011784	12	211	wet	no odour, discharge clear
							Sep 10, 2010	201013166			dry	wet only, not sampled
3084A	24	200		cobble beach	10814 Madrona Road							
							Jan 30, 2007	200710153	3	45	wet	no odour, discharge clear
							Aug 28, 2007	200711562	5	4	dry	no odour, discharge clear
							Mar 14, 2008	200811616	5	200	wet	no odour, discharge clear
							Sep 17, 2008	200812625	1	< 1	dry	no odour, discharge clear
							Mar 25, 2009	200911651	6	8	wet	no odour, discharge clear
							Aug 14, 2009	200912392	2	400	dry	no odour, discharge clear
							Mar 26, 2010	201011785	2	6	wet	no odour, discharge clear

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 10, 2010	201013151	1	26	dry	no odour, discharge clear
3084B	24	100		cobble beach	NW of Cromar Rd beach access	North Saanich	Mar 14, 2008	200811618	1	< 1	wet	sewage odour, discharge clear
							Sep 17, 2008	200813005	0		dry	dry, not sampled
							Mar 25, 2009	200911652	1	0	wet	no odour, discharge clear
							Aug 14, 2009	200912393	0		dry	dry, not sampled
3085	24	450	AHWL	cobble beach	beach access at Cromar Road, 2 m north	North Saanich	Mar 25, 2009	200911653	16	0	wet	no odour, discharge clear
							Aug 14, 2009	200912394	2	0	dry	no odour, discharge clear
							Mar 26, 2010	201011786	16	14	wet	no odour, discharge clear
							Sep 10, 2010	201013152	2	6	dry	no odour, discharge clear
3086	25	500	AHWL	cobble beach with bedrock outcrops	2m south of beach access stairs at Norris Road	North Saanich	Mar 22, 2006	200610714	25	544	wet	no odour, discharge clear
							Aug 31, 2006	200611906	0		dry	dry, not sampled
							Jan 30, 2007	200710154	70	44	wet	no odour, discharge clear
							Aug 28, 2007	200712078	0		dry	dry, not sampled
							Mar 11, 2008	200811687	30	1025	wet	no odour, discharge clear
							Sep 17, 2008	200813006	0		dry	dry, not sampled
							Mar 25, 2009	200911654	20	4	wet	no odour, discharge clear
							Aug 14, 2009	200912395			dry	wet only, not sampled
							Mar 26, 2010	201011787	12	50	wet	no odour, discharge clear
							Sep 10, 2010	201013167	0		dry	dry, not sampled
3087	25	450	AHWL	pebble beach with mudflat	1 m south stairs at Towner Road beach access	North Saanich	Jan 18, 2006	200610041	80	1600	wet	no odour, discharge clear
							Sep 14, 2006	200612120	0		dry	dry, not sampled
							Jan 30, 2007	200710155	85	124	wet	no odour, discharge clear
							May 24, 2007	200711004	25	244	wet	no odour, discharge clear
							Aug 28, 2007	200711563	10	8	dry	no odour, discharge clear
							Mar 11, 2008	200811688	100	38	wet	no odour, discharge clear
							Sep 26, 2008	200812675	10	681	dry	no odour, discharge clear
							Mar 25, 2009	200911656	20	10	wet	no odour, discharge clear
							Aug 14, 2009	200912396	2	800	dry	no odour, discharge clear
							Mar 26, 2010	201011788	12	24	wet	no odour, discharge clear
							Sep 10, 2010	201013150	1	84	dry	no odour, discharge clear
							Nov 04, 2010	201013486	6	42	dry	no odour, discharge clear

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3088	25	450	AHWL	rock/gravel beach	10608 Towner Road, 4 m south of beach access steps	North Saanich						
							Mar 22, 2006	200610717	0	wet	dry, not sampled	
							Sep 14, 2006	200612121	0	dry	dry, not sampled	
3089AA	26			rocky beach	east side of stairs below 693 Finlayson	North Saanich						
							Mar 22, 2006	200610719	1	260	wet	musty odour, discharge clear
							Sep 14, 2006	200612112	0		dry	dry, not sampled
							Jan 30, 2007	200710157	1	183	wet	no odour, discharge clear
							Sep 17, 2007	200712006	0		dry	dry, not sampled
3089AB	26				between 785 and 771 Towner Park Rd	North Saanich						
							Mar 22, 2006	200610722	20	98	wet	no odour, discharge clear
							Sep 14, 2006	200612113	5	78	dry	no odour, discharge clear
							Jan 30, 2007	200710159	65	67	wet	no odour, discharge clear
							Sep 17, 2007	200712007	0		dry	dry, not sampled
3089AC	26	150			at edge of stairs in rock wall on west side of 825 Towner Park Rd							
							Mar 22, 2006	200610723	10	6	wet	no odour, discharge clear
							Sep 14, 2006	200612114	0		dry	dry, not sampled
							Jan 30, 2007	200710162	8	0	wet	no odour, discharge clear
							Sep 17, 2007	200712008	0		dry	dry, not sampled
3089BB	26	200			west side of 701 Towner Park Rd, 25 m east of 3089AA							
							Mar 22, 2006	200610720	2	16800	wet	sewage odour, discharge clear
							May 11, 2006	200611341	0		wet	dry, not sampled
							Sep 14, 2006	200612115	0		dry	dry, not sampled
							Jan 30, 2007	200710163	20	70	wet	no odour, discharge clear
							Sep 17, 2007	200712009	0		dry	dry, not sampled
							Mar 11, 2008	200811690	25	76	wet	no odour, discharge clear
							Sep 26, 2008	200813031	0		dry	dry, not sampled
3089CC	26	150			east side of 701 Towner Park Rd, at end of concrete wall							
							Mar 22, 2006	200610721	2	6	wet	no odour, discharge clear
							Sep 14, 2006	200612116	0		dry	dry, not sampled
							Jan 30, 2007	200710158	8	2	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 17, 2007	200712010			dry	wet only, not sampled
3090	26	stream	AHWL	rocky beach	100m north of 10429 West Saanich Road	North Saanich/Tseyicum	Mar 22, 2006	200610725	40	48	wet	no odour, discharge amber
							Sep 14, 2006	200612117	0		dry	dry, not sampled
3091	26	550	AHWL	rocky beach	25m north of 10425 West Saanich Road	North Saanich/Tseyicum	Mar 22, 2006	200610724	10	81	wet	no odour, discharge clear
							Sep 14, 2006	200612118	0		dry	dry, not sampled
							Feb 28, 2007	200710339	60	6	wet	no odour, discharge clear
							Sep 17, 2007	200712011	0		dry	dry, not sampled
							Mar 14, 2008	200811619	10	13	wet	no odour, discharge clear
							Sep 26, 2008	200813007	0		dry	dry, not sampled
3092	26	400	AHWL	rocky beach	100m south of 10429 West Saanich Road	North Saanich/Tseyicum	Mar 22, 2006	200610726			wet	wet, not sampled
							Sep 14, 2006	200612119	0		dry	dry, not sampled
							Feb 28, 2007	200710767	0		wet	dry, not sampled
							Sep 17, 2007	200712012	0		dry	dry, not sampled
3094	27	600	AHWL	sand/gravel beach	20m south of beach access, across from and south of Totem Lane	North Saanich/Tseyicum	Mar 26, 2010	201011789	6	< 1	wet	no odour, discharge clear
							Sep 02, 2010	201013131	0		dry	dry, not sampled
3095	27	2400	AHWL	sand/gravel beach	Tseyicum Creek 10m north of 1036 West Saanich Rd	North Saanich/Tseyicum	Apr 19, 2006	200610825	45	236	wet	no odour, discharge murky
							Sep 13, 2006	200612102	10	49	dry	no odour, discharge clear
							Mar 28, 2007	200710741	300	4800	wet	no odour, discharge clear
							Apr 02, 2007	200710778	90	800	wet	no odour, discharge murky
							Sep 05, 2007	200711643	80	61968	dry	no odour, discharge reddish colour
							Sep 27, 2007	200711927	40	20800	dry	no odour, discharge murky
							Jan 31, 2008	200811130		1200	wet	
							Mar 11, 2008	200811598	100	44	wet	no odour, discharge clear
							May 15, 2008	200811814	40	840	wet	no odour, light brown discharge

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jul 30, 2008	200812345	25	3640	dry	swampy odour, amber discharge
							Jan 15, 2009	200911021	600	110	wet	no odour, discharge clear
							Jan 22, 2009	200911084	300	800	wet	no odour, discharge clear
							Mar 06, 2009	200911404	200	228	wet	no odour, discharge clear
							Mar 11, 2009	200911414		5200	wet	no odour, discharge clear
							Jul 24, 2009	200912196	30	22400	dry	burnt sugar odour, discharge amber
							Nov 18, 2009	200913006	300	1000	wet	no odour, discharge clear
							Nov 26, 2009	200912519	350	392	wet	no odour, discharge clear
							Feb 11, 2010	201013630	85	400	wet	no odour, reddish brown discharge
							Aug 30, 2010	201013045	15	7000	dry	no odour, amber discharge
							Sep 10, 2010	201013144	20	330	dry	no odour, discharge clear
							Oct 29, 2010	201013433	60	600	wet	no odour, discharge clear
3097	27	600	AHWL	sand/gravel beach	foot of Munro Road	North Saanich						
							Mar 25, 2009	200911659	0		wet	dry, not sampled
							Sep 23, 2009	200912708	0		dry	dry, not sampled
							Feb 16, 2010	201011280	1	< 1	wet	no odour, discharge clear
							Sep 02, 2010	201013132	0		dry	dry, not sampled
3098	27	600	AHWL	sand/gravel beach	10m south of Munro Road beach access stairs	North Saanich						
							Mar 25, 2009	200911658	0		wet	dry, not sampled
							Sep 23, 2009	200912709	0		dry	dry, not sampled
							Mar 26, 2010	201011795			wet	wet only, not sampled
							Sep 02, 2010	201013133	0		dry	dry, not sampled
3099	27	600	AHWL	sand/gravel beach	20m south of Munro Road beach access stairs	North Saanich						
							Mar 25, 2009	200911657	2	0	wet	no odour, discharge clear
							Sep 23, 2009	200913163	0		dry	dry, not sampled
							Feb 16, 2010	201011279	10	400	wet	no odour, discharge clear
							Sep 02, 2010	201013134	0		dry	dry, not sampled
3100	27	400	AHWL	sand/gravel beach	below 10177 West Saanich Rd	North Saanich						
							Mar 22, 2006	200610716	15	445	wet	no odour, discharge clear
							Sep 14, 2006	200612122	0		dry	dry, not sampled
							Jan 31, 2007	200710139	15	11000	wet	no odour, discharge clear
							May 31, 2007	200712192	0		wet	dry, not sampled
							Aug 28, 2007	200712079	0		dry	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jan 25, 2008	200811092	5	26200	wet	sewage odour, discharge clear
							Sep 26, 2008	200813008	0		dry	dry, not sampled
							Jan 15, 2009	200911027	12	6	wet	no odour, discharge clear
							Jan 22, 2009	200911090	10	10	wet	no odour, discharge clear
							Mar 11, 2009	200911408	10	0	wet	no odour, discharge clear
							Mar 11, 2009	200911429	10	4	wet	no odour, discharge clear
							Apr 24, 2009	200911828	1	0	wet	no odour, discharge clear
							Sep 23, 2009	200912716	0		dry	dry, not sampled
							Nov 18, 2009	200913004			wet	no odour, discharge clear
							Jan 21, 2010	201011118	12	< 1	wet	no odour, discharge clear
							Sep 02, 2010	201013135	0		dry	dry, not sampled
3100A	27	400	AHWL	sand/gravel beach	south side of 10127 West Saanich Rd	North Saanich						
							Jan 27, 2006	200610104	40	2200	wet	no odour, discharge clear
							Sep 14, 2006	200612123	0		dry	dry, not sampled
							Jan 31, 2007	200710165	20	33	wet	no odour, discharge clear
							Aug 28, 2007	200712080	0		dry	dry, not sampled
							Jan 25, 2008	200811088	10	701	wet	no odour, discharge clear
							Sep 26, 2008	200813009			dry	wet only, not sampled
							Mar 25, 2009	200911660	1	0	wet	no odour, discharge clear
							Sep 23, 2009	200912717			dry	dry, not sampled
							Feb 11, 2010	201011201	5	600	wet	no odour, grey turbid discharge
							Sep 02, 2010	201013136	0		dry	dry, not sampled
3100B	27	300	AHWL	sand/gravel beach	5m south of 3100A on south side of 10127 West Saanich Rd	North Saanich						
							Jan 27, 2006	200610106	15	25	wet	no odour, discharge clear
							Sep 14, 2006	200612124	0		dry	dry, not sampled
3101	27	ditch	AHWL	sand/mud beach	north side of Mills X Rd	North Saanich						
							Mar 25, 2009	200911661	10	6	wet	no odour, discharge clear
							Sep 23, 2009	200912718			dry	dry, not sampled
							Feb 16, 2010	201011278	3	28	wet	no odour, discharge clear
							Sep 02, 2010	201013137			dry	wet only, not sampled
3102	27	600	AHWL	sand/gravel beach	middle of cemetery property, at convergence of two pathways	North Saanich						
							Mar 25, 2009	200911662	12	6	wet	no odour, discharge clear
							Sep 23, 2009	200912719			dry	dry, not sampled
							Feb 16, 2010	201011277	15	10400	wet	no odour, discharge clear
							Mar 26, 2010	201011779	10	30	wet	no odour, discharge clear

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 02, 2010	201013138	0		dry	dry, not sampled
3103	28	250	BLWL	sand/mud beach	north end of seaplane base off Widgeon D	North Saanich						
							Sep 17, 2010	201013209			dry	wet only, not sampled
3104	28	1400	AHWL	sand and mud	north end of seaplane base, TEN TEN Creek	North Saanich						
							Apr 19, 2006	200610841	90	56	wet	no odour, discharge clear
							Sep 13, 2006	200612100	10	577	dry	slight odour, discharge clear
							Mar 28, 2007	200710699	400	148	wet	no odour, discharge clear
							Sep 20, 2007	200710755	20	415	dry	no odour, discharge clear
							Mar 11, 2008	200811595	200	4	wet	no odour, discharge clear
							Jul 30, 2008	200812344	10	253	dry	swampy odour, discharge clear
							Mar 06, 2009	200911402	200	10	wet	no odour, discharge clear
							Sep 25, 2009	200912782	20	157	dry	no odour, discharge clear
							Mar 26, 2010	201011782	120	1000	wet	slight swamp odour, discharge clear
							Aug 20, 2010	201012940	40	1000	dry	no odour, discharge clear
							Sep 17, 2010	201013190	30	2600	dry	no odour, discharge clear
3104B	28	375	I	riprap	north side of riprap spit, InSTITUTE of Ocean Sciences	North Saanich						
							May 01, 2006	200610973	3	2	wet	no odour, discharge clear
							Aug 03, 2006	200611716	0		dry	dry, not sampled
3105	28		AHWL	riprap and mud	4m north of 1st set of wharfs at south side of Institute of Ocean Sciences	North Saanich						
							May 01, 2006	200610971			wet	wet, not sampled
							Aug 03, 2006	200611717	0		dry	dry, not sampled
							Apr 18, 2007	200710844			wet	wet only, not sampled
							Sep 27, 2007	200711960			dry	wet only, not sampled
							Mar 11, 2008	200811594			wet	wet only, not sampled
							Sep 26, 2008	200813010			dry	wet only, not sampled
							Mar 27, 2009	200911684	4	0	wet	no odour, discharge clear
							Mar 31, 2010	201011837	4	2	wet	no odour, discharge clear
							Sep 17, 2010	201013191	1	400	dry	no odour, discharge clear
3109	29	400	AHWL	rock/sand/gravel	beach access at Briarwood Place	North Saanich						
							Mar 25, 2009	200911663	10	2	wet	no odour, discharge clear
							Sep 23, 2009	200913037			dry	dry, not sampled
							Feb 16, 2010	201011276	25	286	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 15, 2010	201013270	0		dry	dry, not sampled
3110	29	150	AHWL	rock/sand/gravel	10 m west of beach access at Briarwood P	North Saanich	Mar 14, 2008	200811620	1	< 1	wet	no odour, discharge clear
							Sep 05, 2008	200813011			dry	dry, not sampled
3112	29	800	I	rock/sand/gravel	below road allowance at Glenelg and Ardm	North Saanich	Mar 14, 2008	200811622	40	14	wet	no odour, discharge clear
							Sep 05, 2008	200813012			dry	dry, not sampled
3114	29	450	AHWL	rock/sand/gravel	1.5m west of beach access across from 9655 Ardmore	North Saanich	May 01, 2006	200610974		64	wet	
							Sep 14, 2006	200612125	0		dry	dry, not sampled
3115	30	600	AHWL	rock/sand/gravel	beach access at Braemar Avenue	North Saanich	Mar 27, 2009	200911681	20	4	wet	no odour, discharge clear
							Sep 23, 2009	200913038			dry	dry, not sampled
							Feb 16, 2010	201011275	25	4400	wet	no odour, discharge clear
							Sep 15, 2010	201013271	0		dry	dry, not sampled
3116	31	250	AHWL	rock/gravel	Ardmore Drive	North Saanich	Mar 14, 2008	200811750			wet	wet only, not sampled
							Sep 05, 2008	200813013	0		dry	dry, not sampled
3117	31	200	AHWL	rock/gravel	Ardmore Drive	North Saanich	Mar 14, 2008	200811623	1	< 1	wet	no odour, discharge clear
							Sep 05, 2008	200813014			dry	dry, not sampled
3118	31	450	AHWL	sand	foot of Hartfell	North Saanich	Jan 18, 2006	200610030	40	74	wet	no odour, discharge clear
							Jan 24, 2006	200610054	70	40	wet	no odour, discharge clear
							Jan 31, 2006	200610152	85	120	wet	no odour, discharge clear
							Feb 22, 2006	200610340	80	140	wet	no odour, discharge clear
							Sep 14, 2006	200612126	0		dry	dry, not sampled
							Jan 31, 2007	200710166	75	600	wet	no odour, discharge clear
							Aug 28, 2007	200712081	0		dry	dry, not sampled
							Jan 30, 2008	200811118	60	66	wet	no odour, discharge clear
							Sep 05, 2008	200813015			dry	dry, not sampled
							Mar 18, 2009	200911395	40	340	wet	no odour, discharge clear
							Jul 16, 2009	200912035			dry	dry, not sampled
							Jan 21, 2010	201011142	40	200	wet	no odour, discharge clear
							Jul 20, 2010	201012467	1	3800	dry	no odour, discharge clear
							Oct 29, 2010	201013443	2	123	dry	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3118A	31	150	AHWL	sand	20m east of Hartfell beacg access	North Saanich						
							Feb 22, 2006	200610342	10	< 1	wet	
							Mar 07, 2006	200610574	10	< 1	wet	no odour, discharge clear
							Sep 14, 2006	200612127			dry	wet, not sampled.
3118AA	31	100	AHWL	sand	18m east of Hartfell beach access	North Saanich	Jan 24, 2006	200610060	5	3	wet	no odour, discharge clear
							Jan 31, 2006	200610149	10	70	wet	no odour, discharge clear
							Feb 22, 2006	200610341	5	70	wet	no odour, discharge clear
							Mar 07, 2006	200610568	5	< 1	wet	no odour, discharge clear
							Sep 14, 2006	200612128			dry	wet, not sampled
							Jan 31, 2007	200710167	10	2000	wet	no odour, discharge clear
							Apr 25, 2007	200710888	15	7000	wet	no odour, discharge clear
							May 31, 2007	200711029	5	35	wet	no odour, discharge clear
							Aug 28, 2007	200711558	5	400	dry	no odour, discharge clear
							Jan 31, 2008	200811136	5	4000	wet	no odour, discharge clear
							Sep 05, 2008	200812493	1	15200	dry	no odour, discharge clear
							Jan 15, 2009	200911033	8	12600	wet	no odour, discharge clear
							Jul 16, 2009	200912099	2	110	dry	no odour, discharge slight amber
							Nov 18, 2009	200913002	10	102	wet	no odour, discharge clear
							Jan 21, 2010	201011112	1	< 1	wet	no odour, discharge clear
							Jan 29, 2010	201011174	1	427	wet	no odour, discharge clear
Feb 16, 2010	201011209	2	131	wet	no odour, discharge clear							
Jul 20, 2010	201012468	2	560	dry	no odour, discharge clear							
3118B	31	100	AHWL	sand	30m east Hartfell beach access	North Saanich	Feb 22, 2006	200610345			wet	wet, not sampled
							Mar 07, 2006	200611340			wet	wet, not sampled
							Sep 14, 2006	200612129	0		dry	dry, not sampled
							Jan 31, 2007	200710279			wet	wet only, not sampled
							Aug 28, 2007	200712082	0		dry	dry, not sampled
3118C	31	100	AHWL	sand	45m east of Hartfell beach access	North Saanich	Feb 22, 2006	200610343	10	< 1	wet	no odour, discharge clear
							Mar 07, 2006	200610571	5	< 1	wet	no odour, discharge clear
							Sep 14, 2006	200612130	1	0	dry	no odour, discharge clear
							Jan 31, 2007	200710169	20	78	wet	no odour, discharge clear
							Aug 28, 2007	200712083	0		dry	dry, not sampled
							Jan 31, 2008	200812972	0		wet	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 05, 2008	200813016	0		dry	dry, not sampled
3118D	31	100			50m east of Hartfell beach access	North Saanich	Feb 22, 2006	200610344	10	< 1	wet	no odour, discharge clear
							Mar 07, 2006	200610573	5	< 1	wet	no odour, discharge clear
							Sep 14, 2006	200612131	1	2	dry	no odour, discharge clear
3119	31	stream	AHWL	sand	immediately east of Coles Bay Regional Park beach access	North Saanich	Jan 24, 2006	200610062	80	70	wet	no odour, discharge clear
							Jan 31, 2006	200610141	80	290	wet	no odour, discharge clear
							Feb 22, 2006	200610346	80	550	wet	no odour, discharge clear
							Mar 07, 2006	200610562	75	520	wet	no odour, discharge clear
							Sep 14, 2006	200612132			dry	dry, not sampled
							Jan 31, 2007	200710170	80	2	wet	no odour, discharge clear
							Aug 28, 2007	200711559	5	800	dry	no odour, discharge murky
							Jan 31, 2008	200811142	300	49	wet	no odour, discharge clear
							Sep 05, 2008	200813017			dry	wet only, not sampled
							Mar 18, 2009	200911394	60	50	wet	no odour, discharge clear
							Jul 16, 2009	200912100	1	80	dry	no odour, discharge clear
							Feb 16, 2010	201011273	75	20	wet	no odour, slight brown/turbid discharge
							Jul 20, 2010	201014199			dry	wet only, not sampled
3120	31	stream	AHWL	sand	5m south of wood steps at foot of McTavish Rd	North Saanich	Jan 24, 2006	200610061	80	600	wet	no odour, discharge clear
							Jan 31, 2006	200610140	100	3600	wet	no odour, discharge clear
							Feb 22, 2006	200610354	100	40	wet	no odour, discharge clear
							Mar 07, 2006	200610560	65	40	wet	no odour, discharge clear
							Sep 15, 2006	200612143	0		dry	dry, not sampled
							Jan 31, 2007	200710171	90	170	wet	no odour, discharge clear
							May 31, 2007	200711028	20	54	wet	no odour, discharge clear
							Aug 28, 2007	200712084			dry	wet only, not sampled
							Jan 31, 2008	200811143	150	1600	wet	no odour, discharge clear
							Sep 05, 2008	200813018			dry	wet only, not sampled
							Mar 18, 2009	200911393	60	310	wet	no odour, discharge clear
							Jul 16, 2009	200912101			dry	no odour, discharge clear, sampled from pooled water
							Feb 16, 2010	201011208	80	2600	wet	no odour, discharge clear
							Jul 20, 2010	201012706			dry	wet only, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3122	31	350	AHWL	sand	40m south of boat ramp on Pauquachin First Nation land	Pauquachin						
							Feb 22, 2006	200610332	150	10	wet	no odour, discharge clear
							Mar 07, 2006	200610580	60	30	wet	no odour, discharge clear
							Sep 15, 2006	200612144	0		dry	dry, not sampled
							Feb 01, 2007	200710273	100	15	wet	no odour, discharge clear
Sep 17, 2007	200712013	0		dry	dry, not sampled							
3123	31	300	AHWL	sand	50m south of boat ramp on Pauquachin First Nations land	Pauquachin						
							Feb 22, 2006	200610333	30	10	wet	no odour, discharge clear
							Mar 07, 2006	200610579	70	< 1	wet	no odour, discharge clear
Sep 15, 2006	200612145	0		dry	dry, not sampled							
3124	31	stream	AHWL	sand	200m south of boat ramp on Pauquachin First Nations land	Pauquachin						
							Feb 22, 2006	200610355	200	< 1	wet	no odour, discharge clear
							Mar 07, 2006	200610399	100	< 1	wet	no odour, discharge clear
Sep 15, 2006	200612146	0		dry	dry, not sampled							
3124A	31	stream	AHWL	rock	300m south of 3124, by large alder, Pauquachin First Nation land	Pauquachin						
							Mar 31, 2010	201011838	12	28	wet	no odour, discharge clear
Sep 15, 2010	201013272			dry	wet only, not sampled							
3124B	32	stream		rock/sand/gravel	Between 8660 & 8640 Kleewyck Rd, 30 m N of boathouse	North Saanich						
							Mar 14, 2008	200811751			wet	wet only, not sampled
Sep 26, 2008	200813019			dry	wet only, not sampled							
3125	32	stream	AHWL	rock/sand/gravel	Kleewyck Road	North Saanich						
							Mar 14, 2008	200811624	200	2	wet	no odour, discharge clear
Sep 26, 2008	200813020			dry	wet only, not sampled							
3125B	32	ditch		rock/sand/gravel	between 8560 and 8580 Mink Road	North Saanich						
							Jan 18, 2006	200610034	35	43	wet	no odour, discharge clear
Sep 15, 2006	200612147	0		dry	dry, not sampled							
3125C	32	ditch	AHWL	rock/sand/gravel	below 570 Seacliff Rd	North Saanich						
							Mar 14, 2008	200811625	5	1	wet	no odour, discharge clear
Oct 21, 2008	200813021	0		dry	dry, not sampled							

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3126	32	200	AHWL	rock/sand/gravel	under patio at 750 Seacliff Road	North Saanich						
							Mar 14, 2008	200811626	2	< 1	wet	no odour, discharge clear
							Oct 21, 2008	200813022	0		dry	dry, not sampled
3127	32	stream	AHWL	rock and gravel	Salmon Creek, 570 Lawrence Rd	Central Saanich						
							Mar 31, 2010	201011840	20	14	wet	no odour, discharge clear
							Sep 15, 2010	201013273	0		dry	dry, not sampled
3127A	33		AHWL	rock and gravel	30 m east of large grey boat house, nort	Central Saanich						
							Mar 31, 2010	201011839	40	14	wet	no odour, discharge clear
							Sep 15, 2010	201013274	0		dry	dry, not sampled
3128	33	stream	AHWL	rock and gravel	beach access at Nimmo Road	Central Saanich						
							Feb 01, 2007	200710274	70	0	wet	no odour, discharge clear
							Sep 17, 2007	200712015	0		dry	dry, not sampled
3129	34	stream	AHWL	rock and gravel	Thompson Cove	Central Saanich						
							Mar 18, 2009	200911392	60	1	wet	no odour, discharge clear
							Jul 16, 2009	200912102	1	730	dry	no odour, discharge clear
							Mar 11, 2010	201011632	30	40	wet	no odour, discharge clear
							Jul 20, 2010	201012466	8	500	dry	no odour, discharge clear
3131	34		AHWL	rock and gravel	20m east of concrete patio at 675 Senanus Drive	Central Saanich						
							Mar 23, 2006	200610728	75	30	wet	no odour, discharge clear
							Sep 15, 2006	200612148	0		dry	dry, not sampled
							Feb 01, 2007	200710275	80	75	wet	no odour, discharge clear
							Sep 19, 2007	200712024	0		dry	dry, not sampled
							Mar 14, 2008	200811627	50	110	wet	no odour, discharge clear
3132	34	stream	AHWL	rock and gravel	100m south of concrete pation at 675 Senanus Drv	Central Saanich						
							Mar 14, 2008	200811628	20	10	wet	no odour, discharge clear
							Sep 05, 2008	200813024	0		dry	dry, not sampled
3133	35	creek			south side of Woodwyn Farm, Hagan Creek	Central Saanich						
							Apr 25, 2006	200610887	300	223	wet	no odour, discharge clear
							Sep 13, 2006	200612038	150	66	dry	slight sewage odour, discharge clear
							Mar 20, 2007	200710623	400	66	wet	no odour, discharge reddish brown

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 05, 2007	200711645	400	27	dry	no odour, discharge clear
							Feb 18, 2008	200811306	1500	83	wet	no odour, discharge clear with some foam
							Jun 24, 2008	200811960	300	1000	dry	no odour, discharge clear
							Sep 05, 2008	200812427		28	dry	no odour, discharge clear, flow not estimated
							Mar 05, 2009	200911302	400	20	wet	no odour, discharge clear
							Jul 30, 2009	200912221	100	42	dry	no odour, discharge clear
							Feb 03, 2010	201011189	400	18	wet	no odour, discharge clear
							Aug 30, 2010	201013042	300	2	dry	no odour, discharge clear
3134	35		AHWL	rock/sand/gravel	30 m north of viewing platform on Tsartlip land	Central Saanich/Tsartlip						
							Mar 23, 2006	200610727	30	8	wet	no odour, discharge clear
							Sep 15, 2006	200612149	0		dry	dry, not sampled
							Feb 01, 2007	200710276	50	20	wet	no odour, discharge light brown
							Sep 19, 2007	200712023			dry	dry, not sampled
							Sep 19, 2007	200712033	0		dry	dry, not sampled
							Mar 17, 2008	200811497	30	24	wet	no odour, discharge clear
							Sep 05, 2008	200813026	0		dry	dry, not sampled
							Mar 18, 2009	200911396	30	60	wet	no odour, discharge clear, some refuse in channel
							Jul 16, 2009	200912066	0		dry	dry, not sampled
							Mar 11, 2010	201011633	20	910	wet	no odour, dirty brown discharge
							Jul 20, 2010	201012708	0		dry	dry, not sampled
3135	35	600	AHWL	rock/sand/gravel	above viewing platform on Tsartlip First	Central Saanich/Tsartlip						
							Mar 11, 2010	201011635	20	950	wet	no odour, discharge clear
							Jul 20, 2010	201012709	0		dry	dry, not sampled
3138	36	400	AHWL	rock/sand/gravel	south side of of Tsarlip boat launch parking lot	Central Saanich/Tsartlip						
							Mar 18, 2009	200911397	30	320	wet	foul odour, discharge murky brown, refuse and fish carcasses upstream
							Jul 16, 2009	200912078			dry	dry, not sampled
							Mar 11, 2010	201011636	60	1300	wet	no odour, dirty brown discharge
							Jul 20, 2010	201012710	0		dry	dry, not sampled
3143	36	800	AHWL	rock/gravel/sand	north end of Brentwood Inn property on Verdier Ave	Central Saanich						
							Mar 03, 2008	200811450	5	24	wet	no odour, discharge clear

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 05, 2008	200813027	0		dry	dry, not sampled
							Mar 11, 2010	201011631	10	130	wet	no odour, discharge clear
							Sep 15, 2010	201013189	1	34	dry	no odour, discharge clear
3143A	36	400	AHWL	sand/gravel	2m southeast of Willow Tree on south side of Verdier Ave.	Central Saanich						
							Mar 11, 2010	201011690	0		wet	site discontinued
3144	36	450	AHWL	rock/gravel/sand	15m north of Brentwood Inn wharf	Central Saanich						
							Mar 18, 2009	200911391	20	60	wet	slight fragrance, discharge clear
							Jul 16, 2009	200912097	4	670	dry	no odour, discharge clear
							Mar 11, 2010	201011630	24	490	wet	no odour, discharge clear
							Jul 20, 2010	201012465	8	430	dry	no odour, discharge clear
3145	36	760	AHWL	bedrock	foot of Clarke Road	Central Saanich						
							Mar 17, 2008	200811731	20	29	wet	no odour, discharge clear
							Sep 05, 2008	200812428	5	4	dry	no odour, discharge clear, flow surged from 1 L/min. to 10 L/min.
3145A	36				Devonshire beach access, south side of 7078 Brentwood Drive							
							Mar 23, 2006	200610729	25	27	wet	no odour, discharge clear
							Sep 22, 2006	200612206	20	2600	dry	no odour, discharge clear
							Feb 01, 2007	200710277	65	16	wet	no odour, discharge clear
							Sep 19, 2007	200711842	5	4600	dry	no odour, discharge clear
							Mar 14, 2008	200811629	100	1160	wet	no odour, discharge clear
							Sep 05, 2008	200813028	0		dry	dry, not sampled
							Mar 18, 2009	200911390	15	10	wet	no odour, discharge clear
							Jul 16, 2009	200912096	2	90	dry	no odour, discharge clear
							Mar 11, 2010	201011629	16	420	wet	no odour, discharge clear
							Jul 20, 2010	201012464	10	73	dry	no odour, discharge clear
3146	36	stream	AHWL	rock/gravel/sand	Brentwood Drive near Marchant Road	Central Saanich						
							Mar 23, 2006	200610644	75	36	wet	
							Sep 22, 2006	200612208	40	91	dry	no odour, discharge clear
							Feb 01, 2007	200710179	100	> 1200	wet	no odour, discharge light brown color
							Sep 19, 2007	200711841	30	600	dry	no odour, discharge clear
							Mar 17, 2008	200811732	300	620	wet	no odour, discharge clear
							Sep 05, 2008	200812492	20	113	dry	no odour, discharge clear

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 27, 2009	200911686	100	127	wet	no odour, discharge clear
							Oct 09, 2009	200912814	35	30	wet	no odour, discharge clear
							Mar 31, 2010	201011842	100	1400	wet	no odour, discharge clear
							Jul 20, 2010	201012463	15	340	dry	no odour, discharge clear
3147	36	200		rock/gravel/sand	foot of Marchant Road	Central Saanich						
							Mar 27, 2009	200911687	15	0	wet	no odour, discharge clear
							Jul 16, 2009	200912036			dry	dry, not sampled
							Mar 11, 2010	201011628	20	550	wet	no odour, discharge clear
							Jul 20, 2010	201012462	10	10	dry	no odour, discharge clear
3147A	36	150	AHWL	rock	end of Grilse Lane	Central Saanich						
							Mar 23, 2006	200610646	0		wet	dry, not sampled
							Sep 22, 2006	200612193	0		dry	dry, not sampled
							Sep 19, 2007	200712021			dry	dry, not sampled
							Mar 17, 2008	200811734			wet	wet only, not sampled
							Sep 05, 2008	200813029	0		dry	dry, not sampled
3147B	36	300	AHWL	rock and gravel	foot of Josephine Road, 6 m south from path access	Central Saanich						
							Mar 23, 2006	200610647	0		wet	dry, not sampled
							Sep 22, 2006	200612191	0		dry	dry, not sampled
3148	36	stream	AHWL	sand and gravel	east of Port Royale development under wooden bridge	Central Saanich						
							Mar 23, 2006	200610648	75	22	wet	
							Sep 22, 2006	200612210	40	68	dry	no odour, discharge clear
							Feb 01, 2007	200710177	70	9	wet	no odour, discharge clear
							Sep 19, 2007	200711840	10	150	dry	dry, not sampled
							Mar 17, 2008	200811735	80	51	wet	no odour, discharge clear
							Sep 05, 2008	200812394		26	dry	no odour, discharge clear
							Mar 11, 2010	201011627	100	250	wet	no odour, discharge clear
							Jul 20, 2010	201012408	30	55	dry	no odour, discharge clear
3148A	36	150	AHWL	riprap	10 m west of bridge along Angler's Anchorage walkway	Central Saanich						
							Mar 23, 2006	200610649	0		wet	dry, not sampled
							Sep 22, 2006	200612194	0		dry	dry, not sampled
3149	36	200	AHWL	riprap	east end of Port Royale at Anglers Lane	Central Saanich						
							Mar 23, 2006	200610650	0		wet	dry, not sampled
							Sep 22, 2006	200612195	0		dry	dry, not sampled

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
3149B	36	150	AHWL	riprap	in riprap halfway between park bench and log retaining wall	Central Saanich						
							Mar 14, 2008	200811736	0	wet	dry, not sampled	
							Sep 05, 2008	200813030	0	dry	dry, not sampled	
3150	36	450	I	riprap	below Port Royale Walkway, 40 m east of wharf	Central Saanich						
							Mar 14, 2008	200811499	30	1320	wet	no odour, discharge clear
							Sep 26, 2008	200812674		353	dry	no odour, discharge clear
							Mar 18, 2009	200911388	20	170	wet	no odour, discharge clear
							Jul 16, 2009	200912059			dry	wet only, not sampled
							Mar 11, 2010	201011626	40	280	wet	no odour, discharge clear
							Jul 20, 2010	201012409	1	3500	dry	no odour, discharge clear
Nov 04, 2010	201013487	20	546	dry	no odour, discharge clear							
3151	36	300	I	riprap	foot of Deamere, west end of Port Royale property	Central Saanich						
							Mar 14, 2008	200811730	15	1680	wet	no odour, discharge clear
							Sep 26, 2008	200812641		704	dry	no odour, discharge clear
							Mar 18, 2009	200911387	2	4000	wet	no odour, discharge sudsy
							May 21, 2009	200911776	0		wet	dry, not sampled
							Jul 16, 2009	200912072			dry	dry, not sampled
							Nov 26, 2009	200912518	20	28	wet	no odour, discharge clear
							Mar 11, 2010	201011624	20	160	wet	no odour, discharge clear
Jul 20, 2010	201012707	0		dry	dry, not sampled							
3152A	37	100	I	gravel	east side of Butchart Gardens dock	Central Saanich						
							May 11, 2006	200611004	0		wet	dry, not sampled
							Sep 27, 2006	200612273	0		dry	dry, not sampled
3153	37	450	I	sand and gravel	small bay at Butchart Gardens	Central Saanich						
							Mar 17, 2008	200811737	2	4400	wet	no odour, discharge clear
							Oct 21, 2008	200812656	15	< 1	dry	no odour, discharge clear
							Mar 27, 2009	200911688	10	26	wet	sampled from settling pond just upstream of eop
							Oct 09, 2009	200912815	1	600	wet	sampled in settling ponds
							Mar 31, 2010	201011843	6	200	wet	no odour, discharge clear
Jul 20, 2010	201012407	10	550	dry	no odour, discharge clear							
3154	37	stream	AHWL	estuary	south of Butchart Gardens in Tod inlet, Tod Creek	Central Saanich						

\* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

## Stormwater Quality Report

### Fecal Coliform and Flow Data (for the period of Jan 01, 2006 to Dec 31, 2010)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Apr 25, 2006	200610889	300	46	wet	no odour, discharge clear
							Sep 13, 2006	200612037	5	68	dry	no odour, discharge clear
							Mar 28, 2007	200710697		36	wet	no odour, discharge clear, flow too large to estimate
							Sep 05, 2007	200711647	200	98	dry	no odour, discharge clear
							Feb 18, 2008	200811305	2000	18	wet	no odour, foam in discharge
							Jun 20, 2008	200811928	150	66	dry	no odour, slight amber discharge
							Mar 06, 2009	200911400	1000	4	wet	no odour, discharge clear
							Sep 23, 2009	200912702	100	4	dry	no odour, discharge clear
							Feb 17, 2010	201011284	500	16	wet	no odour, discharge clear
							Aug 30, 2010	201013040	120	6	dry	no odour, discharge clear