

APPENDIX C

**FECAL COLIFORM AND FLOW DATA:
1998 - 2006**

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7001	P2		AHWL		outflow from Buck Lake, next to Buck Lake Water Treatment plant, North Pender Island	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913884	70	4	wet	no odour, discharge clear
							Jul 21, 1998	197913885	0		dry	dry, not sampled
							Apr 07, 2003	197917222		2	wet	no odour, discharge clear
							Jul 18, 2003	197917514		96	dry	no odour, discharge clear
							Apr 20, 2005	200510707	25	2	wet	
							Aug 18, 2005	200511438		9	dry	no odour, discharge clear
7001A	P2		AHWL	cobble/sand beach	north corner of Boat Nook, North Pender Island	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913882	120	120	wet	no odour, discharge clear
							Jul 21, 1998	197913883	80	1470	dry	no odour, discharge clear
							Feb 19, 1999	197914550	200	28	wet	no odour, discharge clear
							Jul 06, 1999	197914551	3	120	wet	no odour, discharge clear
							Mar 14, 2001	197915696	30	10	wet	no odour, discharge clear
							Aug 21, 2001	197915864	5	14400	dry	no odour, discharge clear
							Apr 18, 2002	197916898	30	3	wet	no odour, discharge clear
							Jul 31, 2002	197916899	5	223	dry	no odour, discharge clear
							Apr 07, 2003	197917223		2	wet	discharge clear, no odour, end of pipe is blocked with woody debris
							Mar 17, 2004	200412975	40	8	wet	no odour, discharge clear
							Jul 23, 2004	200414175			dry	wet, not sampled
							Apr 20, 2005	200510708	25	8	wet	no odour, discharge clear
							Aug 18, 2005	200511437	20	2200	dry	no odour, discharge clear
							Dec 15, 2005	200512091	25	24	wet	no odour, discharge clear
Mar 27, 2006	200610662	30	2	wet	no odour, discharge clear							
Jul 07, 2006	200611353	5	6000	dry	no odour, discharge black							
7002	P2		AHWL		inflow for Buck Lake at 36107 Galleon Way	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913886	80	58	wet	no odour, discharge clear
							Jul 21, 1998	197913887	0		dry	dry, not sampled
							Feb 19, 1999	197914552	50	54	wet	no odour, discharge clear
							Jul 06, 1999	197914553	35	41	dry	no odour, discharge clear
							Apr 13, 2000	197910963	30	48	wet	no odour, discharge clear
							Aug 10, 2000	197911049	6	155	dry	no odour, discharge clear
							Mar 14, 2001	197915697	50	5	wet	no odour, discharge clear
							Aug 21, 2001	197915865	10	198	dry	no odour, discharge clear
							Apr 18, 2002	197916900	30	6	wet	no odour, discharge clear
							Jul 31, 2002	197916901	0		dry	dry, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Apr 07, 2003	197917224	20	54	wet	no odour, discharge clear
							Jul 18, 2003	197917522	0		dry	dry, not sampled
							Mar 17, 2004	200412979	40	4	wet	no odour, discharge clear
							Jul 23, 2004	200414176	0		dry	dry, not sampled
							Apr 20, 2005	200510709	20	10	wet	no odour, discharge clear
							Aug 18, 2005	200511440			dry	wet, not sampled
							Mar 27, 2006	200610663	10	4	wet	no odour, discharge clear
							Jul 07, 2006	200611338	0		dry	dry, not sampled
7002A	P2		AHWL		36112 Galleon Rd., upstream of 7002 (flow into Buck Lake)	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913890	60	63	wet	no odour, discharge clear
							Jul 21, 1998	197913891	1	20	dry	no odour, discharge clear
							Feb 19, 1999	197914554	80	47	wet	no odour, discharge clear
							Jul 06, 1999	197914555	30	20	dry	no odour, discharge clear
							Apr 13, 2000	197910964	30	58	wet	no odour, discharge clear
							Aug 10, 2000	197912531	8	110	dry	no odour, discharge clear
							Mar 14, 2001	197915698	35	3	wet	no odour, discharge clear
							Aug 21, 2001	197915866	15	632	dry	no odour, discharge clear
							Apr 18, 2002	197916902	30	14	wet	no odour, discharge clear
							Apr 07, 2003	197917225	20	58	wet	no odour, discharge clear
							Jul 18, 2003	197917523	0		dry	dry, not sampled
							Mar 17, 2004	200412980	40	6	wet	no odour, discharge clear
							Jul 23, 2004	200414177	0		dry	dry, not sampled
							Apr 20, 2005	200510711	60	4	wet	no odour, discharge clear
							Aug 18, 2005	200511473	2	5600	dry	no odour, discharge clear
							Dec 15, 2005	200512164			wet	wet, not sampled
							Mar 27, 2006	200610732	30	8	wet	no odour, discharge clear
							Jul 07, 2006	200611352	5	6	dry	no odour, discharge murky
7003	P2		AHWL		3710 Tiller Crescent, inflow for Buck lake	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913888	45	4	wet	no odour, discharge clear
							Jul 21, 1998	197913889	1	323	dry	no odour, discharge clear
							Feb 19, 1999	197914556	30	45	wet	no odour, discharge clear
							Jul 06, 1999	197914557	5	100	dry	no odour, discharge clear
							Apr 13, 2000	197910965	6	0	wet	no odour, discharge clear
							Aug 10, 2000	197912532	1	245	dry	no odour, discharge clear
							Mar 14, 2001	197915699	12	6	wet	no odour, discharge clear
							Apr 18, 2002	197916904	10	4	wet	no odour, discharge clear
							Apr 07, 2003	197917226	5	6	wet	no odour, discharge clear
							Jul 18, 2003	197917524	0		dry	dry, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 17, 2004	200412978	10	0	wet	no odour, discharge clear
							Jul 23, 2004	200414178	0		dry	dry, not sampled
							Apr 20, 2005	200510712	16	15	wet	no odour, discharge clear
							Aug 18, 2005	200511477			dry	wet, not sampled
							Mar 27, 2006	200610666	10	2	wet	no odour, discharge clear
							Jul 07, 2006	200611339	0		dry	dry, not sampled
7003A	P2		AHWL		Galleon Way and Port Rd, upstream of 7003	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913892		40	wet	no odour, discharge clear
							Jul 21, 1998	197913893	0		dry	dry, not sampled
							Feb 19, 1999	197914558	30	11	wet	no odour, discharge clear
							Jul 06, 1999	197914559	0		dry	dry, not sampled
							Apr 13, 2000	197910966		2	wet	no odour, discharge murky brown, sediment in sample
							Aug 10, 2000	197912533	0		dry	dry, not sampled
							Mar 14, 2001	197915700	2	10	wet	no odour, discharge murky brown
							Aug 21, 2001	197915845			dry	wet, not sampled
							Apr 18, 2002	197916906		27	wet	no odour, discharge clear
							Jul 31, 2002	197916956	0		dry	dry, not sampled
							Apr 07, 2003	197917227		6	wet	slight odour, discharge clear
							Jul 18, 2003	197917525	0		dry	dry, not sampled
							Mar 17, 2004	200412976	1	22	wet	no odour, discharge clear
							Jul 23, 2004	200414179			dry	wet, not sampled
							Apr 20, 2005	200510714	16	14	wet	no odour, discharge clear
							Aug 18, 2005	200511478			dry	wet, not sampled
							Mar 27, 2006	200610730	1	2	wet	no odour, discharge clear
							Jul 07, 2006	200611354	0		dry	dry, not sampled
7004	P2		AHWL		Bucaneer Creek, 4705 Bucaneers Rd., Magic Lake inflow	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913898	20	10	wet	musty odour, discharge turbid
							Jul 21, 1998	197913899	1	20	dry	no odour, discharge clear
							Feb 19, 1999	197914560	30	22	wet	no odour, discharge clear
							Jul 06, 1999	197914561	50	20	dry	no odour, discharge clear
							Apr 13, 2000	197910967	16	5	wet	no odour, discharge clear
							Aug 10, 2000	197912534	0		dry	dry, not sampled
							Mar 14, 2001	197915701	40	11	wet	no odour, discharge clear
							Aug 21, 2001	197915846	0		dry	dry, not sampled
							Apr 18, 2002	197916907	20	4	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jul 31, 2002	197916908	2	305	dry	no odour, discharge clear
							Apr 07, 2003	197917228	30	6	wet	no odour, discharge clear
							Jul 18, 2003	197917526	0		dry	dry, not sampled
							Mar 17, 2004	200412974	30	2	wet	no odour, discharge clear
							Jul 23, 2004	200413519	2	128	dry	no odour, discharge clear
							Apr 20, 2005	200510716	120	0	wet	no odour, discharge clear
							Aug 18, 2005	200511479	5	134	dry	no odour, discharge clear
							Mar 27, 2006	200610668	20	2	wet	no odour, discharge clear
							Jul 07, 2006	200611355	0		dry	dry, not sampled
7004A	P2		AHWL		Ketch Rd. and Bedwell Harbour Rd., behind Magic Lake Water Treatment Plant	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913900		40	wet	no odour, discharge clear
							Feb 19, 1999	197914562	60	9	wet	no odour, discharge clear
							Jul 06, 1999	197914563	50	21	dry	no odour, discharge clear
							Apr 13, 2000	197910968	15	0	wet	no odour, discharge clear
							Aug 10, 2000	197912535	3	200	dry	no odour, discharge clear
							Mar 14, 2001	197915702	35	2	wet	no odour, discharge clear
							Aug 21, 2001	197915868		103	dry	no odour, discharge clear
							Apr 18, 2002	197916909	20	2	wet	no odour, discharge clear
							Jul 31, 2002	197916910	0		dry	dry, not sampled
							Apr 07, 2003	197917229	15	2	wet	no odour, discharge clear
							Jul 18, 2003	197917527	0		dry	dry, not sampled
							Mar 17, 2004	200412973	20	0	wet	no odour, discharge clear
							Jul 23, 2004	200414180	0		dry	dry, not sampled
							Apr 20, 2005	200510715	60	0	wet	no odour, discharge clear
							Aug 18, 2005	200511482	0		dry	dry, not sampled
							Mar 27, 2006	200610669	25	2	wet	no odour, discharge clear
							Jul 07, 2006	200611356			dry	standing water, not sampled
7005	P2		AHWL		Pirates Rd. near Cannon Crescent, Magic Lake outflow	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913896	80	4	wet	no odour, discharge clear
							Jul 21, 1998	197913897	0		dry	dry, not sampled
							Apr 18, 2002	197916911	30	19	wet	no odour, discharge clear
							Jul 31, 2002	197916912	0		dry	dry, not sampled
							Apr 20, 2005	200510718	100	8	wet	no odour, discharge clear
							Aug 18, 2005	200511436	0		dry	dry, not sampled
7005A	P2		AHWL	bedrock	50 m south of sewer outfall, Magic Lake outflow	N.Pender Island/ S.G.I.						
							Mar 18, 1998	197913894	220	4	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7006					36112 Galleon Way, culvert to the north		Jul 21, 1998	197913895	15	237	dry	no odour, discharge clear
							Jul 18, 2003	197917528	0		dry	dry, not sampled
							Mar 17, 2004	200414163			wet	wet, not sampled
							Jul 23, 2004	200414181	0		dry	dry, not sampled
7006A	creek				Shingle Bay Park at 2612 Spinaker Drv		Apr 20, 2005	200510710	100	0	wet	no odour, discharge clear
							Aug 18, 2005	200511474			dry	wet, not sampled
							Mar 27, 2006	200611342	0		wet	dry, not sampled
							Jul 07, 2006	200611358	0		dry	dry, not sampled
7007	P4	450	AHWL	bedrock	1704 Swanson View Rd.	N.Pender Island/ S.G.I.	Apr 20, 2005	200510713	200	10	wet	no odour, discharge clear
							Aug 18, 2005	200511439	0		dry	dry, not sampled
							Mar 27, 2006	200610664	20	4	wet	
							Jul 07, 2006	200611357	0		dry	dry, not sampled
7010	P4		AHWL	bedrock, some sand	near entrance of Bedwell Harbour beside large dock	N.Pender Island/ S.G.I.	Apr 13, 2000	197910969	10	2	wet	no odour, discharge clear
							Aug 10, 2000	197912536	1	180	dry	no odour, discharge clear
							Apr 20, 2005	200510720	25	2	wet	no odour, discharge clear
							Aug 18, 2005	200511435	0		dry	dry, not sampled
							Mar 27, 2006	200611343	0		wet	dry, not sampled
							Jul 07, 2006	200611359	0		dry	dry, not sampled
7015	P4		AHWL	sand/cobble beach	west end of Medicine Beach, Bedwell Harbour	N.Pender Island/ S.G.I.	Mar 18, 1998	197913902	90	0	wet	sweet odour, discharge clear
							Jul 21, 1998	197913903	5	0	dry	no odour, discharge clear
							Apr 07, 2003	197917231		9	wet	no odour, discharge clear
7020	P3		AHWL	rock/gravel	under brick house at Port Browning	N.Pender Island/ S.G.I.	Mar 18, 1998	197913904	40	0	wet	musty odour, discharge clear
							Jul 21, 1998	197913905	0		dry	dry, not sampled
							Apr 20, 2005	200510781	200	0	wet	no odour, discharge clear
							Aug 18, 2005	200511434			dry	wet, not sampled
7020	P3		AHWL	rock/gravel	under brick house at Port Browning	N.Pender Island/ S.G.I.	Mar 17, 1998	197913906	70	70	wet	no odour, discharge clear
							Jul 21, 1998	197913907	0		dry	dry, not sampled
							Mar 17, 2004	200412981	20	0	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jul 23, 2004	200414182	0		dry	dry, not sampled
7021	P3		AHWL	rock	Port Browning, Bracket Cove, past Marina	N.Pender Island/ S.G.I.						
							Mar 17, 1998	197913908	150	20	wet	no odour, discharge clear
							Jul 21, 1998	197913909	0		dry	dry, not sampled
							Apr 07, 2003	197917232	100	6	wet	no odour, discharge clear
							Jul 18, 2003	197917529	0		dry	dry, not sampled
							Apr 20, 2005	200510782	250	113	wet	no odour, discharge clear
							Aug 18, 2005	200511433	0		dry	dry, not sampled
7022	P3		AHWL	mud/cobble	Port Browning, intersection of Razor Point Rd.	N.Pender Island/ S.G.I.						
							Mar 17, 1998	197913910	60	14	wet	no odour, discharge clear
							Jul 18, 2003	197917530	0		dry	dry, not sampled
							Apr 20, 2005	200510786			wet	wet, not sampled
							Aug 18, 2005	200511432	0		dry	dry, not sampled
7023	P3	300	AHWL	mud/cobble	Port Browning, Razor Point Rd.	N.Pender Island/ S.G.I.						
							Mar 17, 1998	197913912	40	4	wet	no odour, discharge clear
							Jul 21, 1998	197913913	0		dry	dry, not sampled
							Apr 07, 2003	197917234	60	16	wet	no odour, discharge clear
							Jul 18, 2003	197917531	0		dry	dry, not sampled
							Apr 20, 2005	200510783	120	108	wet	no odour, discharge clear
							Aug 18, 2005	200511431	0		dry	dry, not sampled
7024	P3		AHWL	sand/cobble beach	Port Browning, 100 m northeast of government wharf under mobile home	N.Pender Island/ S.G.I.						
							Mar 17, 1998	197913914	80	8	wet	no odour, discharge clear
							Jul 21, 1998	197913915	0		dry	dry, not sampled
							Apr 18, 2002	197916913	20	60	wet	no odour, discharge clear
							Jul 31, 2002	197916914	0		dry	dry, not sampled
							Apr 07, 2003	197917235	30	36	wet	no odour, discharge clear
							Jul 18, 2003	197917532	0		dry	dry, not sampled
7025	P3		AHWL	cobble beach	Port Browning, 20 m east of old cedar siding house with stone chimney	N.Pender Island/ S.G.I.						
							Mar 17, 1998	197913916	70	2	wet	no odour, discharge clear
							Jul 21, 1998	197913917	5	140	dry	decaying organic odour, brown silt present in discharge
							Apr 18, 2002	197916915	30	3	wet	no odour, discharge clear
							Jul 31, 2002	197916916	0		dry	dry, not sampled
							Apr 07, 2003	197917236	30	6	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7026	P3	250	AHWL	bedrock/cobble	Port Browning, Pallard Cove under large house	N.Pender Island/ S.G.I.						
							Jul 21, 1998	197913918	0	dry	dry, not sampled	
							Apr 18, 2002	197916917	0	wet	dry, not sampled	
							Jul 31, 2002	197916918	0	dry	dry, not sampled	
							Jul 18, 2003	197917533	0	dry	dry, not sampled	
7050	P3	1100	AHWL	intertidal mud flat	Hope Bay, Hoosen Rd. and Bedwell Harbour Rd.	N.Pender Island/ S.G.I.						
							Jul 06, 1999	197914565	1	56	dry	no odour, discharge clear
							Apr 13, 2000	197910970	45	54	wet	no odour, discharge clear
							Mar 14, 2001	197915703	80	13	wet	no odour, discharge clear
							Aug 21, 2001	197915847	0		dry	dry, not sampled
							Apr 18, 2002	197916919	20	100	wet	no odour, discharge clear
							Jul 31, 2002	197916920		1293	dry	stagnant odour, discharge clear
							Apr 07, 2003	197917238	80	12	wet	no odour, discharge clear
							Mar 17, 2004	200412702	100	9	wet	no odour, discharge clear
							Jul 23, 2004	200414183	0		dry	dry, not sampled
Apr 20, 2005	200510784	400	12	wet	no odour, discharge clear							
Aug 18, 2005	200511430			dry	wet, not sampled							
7050-1	P3	stream	AHWL	intertidal mud flat	Hope Bay, upstream of 7050, below confluence of Standen and Bradley Creek, Hoosen Rd. at Christian C	N.Pender Island/ S.G.I.						
							Jul 06, 1999	197914566	1	15	dry	no odour, discharge clear
							Apr 13, 2000	197910971	45	65	wet	no odour, discharge clear
							Aug 10, 2000	197912538	1	1165000	dry	sewage odour, discharge black
							Mar 14, 2001	197915704	75	6	wet	no odour, discharge clear
							Aug 21, 2001	197915848	0		dry	dry, not sampled
							Apr 18, 2002	197916921	30	97	wet	no odour, discharge clear
							Jul 31, 2002	197916922	0		dry	dry, not sampled
							Mar 17, 2004	200412703	100	9	wet	no odour, discharge clear
Jul 23, 2004	200414184	0		dry	dry, not sampled							
7050-2	P3	stream	AHWL	intertidal mud flat	Hope Bay, upstream of 7050 in Standen Creek, Hoosen Rd. at Christian Camp	N.Pender Island/ S.G.I.						
							Jul 06, 1999	197914567	1	201	dry	no odour, discharge clear
							Apr 13, 2000	197910972	8	6	wet	no odour, discharge clear
							Aug 10, 2000	197912539	0		dry	dry, not sampled
							Mar 14, 2001	197915705	25	13	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Aug 21, 2001	197915849	0		dry	dry, not sampled
7050-3	P3	stream	AHWL	intertidal mud flat	Hope Bay, upstream of 7050 in Bradley Creek near Hoosen Rd. at Christian Camp	N.Pender Island/ S.G.I.						
							Jul 06, 1999	197914568	0		dry	dry, not sampled
							Apr 13, 2000	197910973	35	72	wet	no odour, discharge clear
							Mar 14, 2001	197915706	50	16	wet	no odour, discharge clear
							Aug 21, 2001	197915850	0		dry	dry, not sampled
7050-4	P3	stream		intertidal mud flat	5 m upstream from culvert at Hoosen Rd, 4 m downstream of Standen Creek	N.Pender Island/ S.G.I.						
							Mar 14, 2001	197915707	4	61	wet	no odour, discharge clear
							Aug 21, 2001	197915851	0		dry	dry, not sampled
7051	P3		AHWL	intertidal mud flats	south side of Bedwell Harbour Road, east side of Hoosen Rd.	N.Pender Island/ S.G.I.						
							Apr 13, 2000	197912541	35	40	wet	no odour, discharge clear
							Aug 10, 2000	197912542	0		dry	dry, not sampled
							Apr 18, 2002	197916923	30	25	wet	no odour, discharge clear
							Jul 31, 2002	197916924	0		dry	dry, not sampled
7400	S2		AHWL	sand/cobble	small bay behind Trevor Island, west of Boot Cove. East of reddish/brown building with dark brown tri	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912547	40	18	wet	no odour, discharge clear
							Aug 10, 2000	197912543	1	150	dry	no odour, discharge clear
							Apr 14, 2003	197917239	30	0	wet	no odour, discharge clear
7401	S2		AHWL	bedrock	West side of entrance into Boot Cove. 50 m south of small brown shack	Saturna Island/ S.G.I.						
							Aug 10, 2000	197912545	0		dry	dry, not sampled
							Jul 11, 2003	197917534	0		dry	no flow, not sampled
							Apr 06, 2005	200510688			wet	wet, not sampled
							Aug 06, 2005	200512211	0		dry	dry, not sampled
7402	S3		AHWL	mud/sand	south end of Boot Cove, west side of Saturna Lodge wharf	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912546	40	12	dry	no odour, discharge clear
							Apr 14, 2003	197917241	20	10	wet	no odour, discharge clear
							Jul 11, 2003	197917535	2	13000	dry	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 29, 2004	200413079	30	11	wet	no odour, discharge clear
							Jul 21, 2004	200414185			dry	wet, not sampled
							Apr 06, 2005	200510686	100	0	wet	no odour, discharge clear
							Jul 28, 2005	200510831			dry	wet, not sampled
							Mar 27, 2006	200610733		15	wet	no odour, discharge clear
							Aug 01, 2006	200611692			dry	wet, not sampled
7403	S3		AHWL	mud/sand	east side of Boot Cove at southern end, north of reddish/brown house	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912550	2	360	dry	no odour, discharge clear
							Mar 21, 2001	197915708	5	290	wet	no odour, discharge clear
							Sep 13, 2001	197915852	0		dry	dry, not sampled
							Jul 31, 2002	197916926	0		dry	dry, not sampled
							Jul 11, 2003	197917536	0		dry	dry, not sampled
7404	S3		AHWL	mud/sand	3 m northeast of rock retaining wall at 105 Mill Road	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912552	30	2	wet	no odour, discharge clear
							Aug 10, 2000	197912553	0		dry	dry, not sampled
							Apr 16, 2002	197916927	30	0	wet	no odour, discharge clear
							Apr 06, 2005	200510687	80	0	wet	no odour, discharge clear
							Jul 28, 2005	200510829			dry	wet, not sampled
7405	S3		AHWL	mud/sand/sands tone	east side of wood shingled house with green lower floor and wharf with metal railing	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912554	2	0	dry	no odour, discharge clear
							Aug 10, 2000	197912555	0		dry	dry, not sampled
							Jul 31, 2002	197916930	0		dry	dry, not sampled
7406	S3		AHWL	sand/sandstone	east side of Boot Cove, north side of brown house with wharf	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912556	3	11	wet	no odour, discharge clear
							Aug 10, 2000	197912557	0		dry	dry, not sampled
							Jul 31, 2002	197916932	0		dry	dry, not sampled
7407	S4		AHWL	mud/sand	south side of 120 Boot Cove Road	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912558	60	2	wet	no odour, discharge clear
							Aug 10, 2000	197912559	1	663	dry	no odour, discharge clear
							Mar 21, 2001	197915709	45	19	wet	no odour, discharge clear
							Apr 16, 2002	197916933	10	14	wet	no odour, discharge clear
							Jul 31, 2002	197916934	2	2000	dry	no odour, discharge muddy

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Apr 14, 2003	197917243	50	10	wet	no odour, discharge clear
							Mar 29, 2004	200413081	30	0	wet	no odour, discharge clear
							Jul 21, 2004	200413517	2	1800	dry	no odour, discharge brown
							Apr 06, 2005	200510689	60	53	wet	no odour, discharge clear
							Jul 28, 2005	200510832	5	805	dry	no odour, discharge clear
							Dec 21, 2005	200512129	40	22	wet	no odour, discharge clear
							Mar 27, 2006	200610735	40	0	wet	no odour, discharge clear
							Aug 01, 2006	200611104	5	8878	dry	no odour, discharge murky
							Aug 14, 2006	200611678	5	800	dry	no odour, discharge clear
7408	S4		AHWL	mud/sand	north side of 120 Boot Cove Rd	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912560	85	720	wet	no odour, discharge clear
							Aug 10, 2000	197912561	1	150	dry	no odour, discharge clear
							Mar 21, 2001	197915710	80	42	wet	no odour, discharge clear
							Apr 16, 2002	197916935	25	20	wet	no odour, discharge clear
							Jul 31, 2002	197916936	2	360	dry	no odour, discharge clear
							Apr 14, 2003	197917244	40	279	wet	no odour, discharge clear
							Jul 11, 2003	197917537	5	800	dry	no odour, discharge clear
							Mar 29, 2004	200413082	40	0	wet	no odour, discharge clear
							Jul 21, 2004	200414186	0		dry	dry, not sampled
							Apr 06, 2005	200510690	80	8	wet	no odour, discharge clear
							Jul 28, 2005	200510833			dry	wet, not sampled
							Mar 27, 2006	200610736	35	18	wet	no odour, discharge clear
							Aug 01, 2006	200611693			dry	wet, not sampled
7409	S4		AHWL	bedrock	east side of boot Cove, immediately south of cove entrance	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912562	1	4	wet	no odour, discharge clear
							Aug 10, 2000	197912586	0		dry	dry, not sampled
							Apr 16, 2002	197916937	0		wet	dry, not sampled
							Jul 31, 2002	197916938	0		dry	dry, not sampled
							Apr 06, 2005	200510795	0		wet	dry, not sampled
							Aug 26, 2005	200511493	0		dry	dry, not sampled
							Mar 27, 2006	200611344	0		wet	dry, not sampled
							Aug 01, 2006	200611694	0		dry	dry, not sampled
7410	S6		AHWL	bedrock	south side of Lyall Harbour, immediately west of log storage	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912564	75	11	wet	no odour, discharge clear
							Aug 10, 2000	197912565	0		dry	dry, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Mar 14, 2001	197915711	80	200	wet	no odour, discharge clear
							Sep 13, 2001	197915855	0		dry	dry, not sampled
							Apr 16, 2002	197916939	40	165	wet	no odour, discharge clear
							Apr 14, 2003	197917245	80	9	wet	no odour, discharge clear
							Jul 11, 2003	197917538	0		dry	dry, not sampled
							Mar 29, 2004	200413083	80	0	wet	no odour, discharge clear
							Jul 21, 2004	200414187	0		dry	dry, not sampled
							Apr 20, 2005	200510790	80	2	wet	
							Jul 28, 2005	200510834	0		dry	dry, not sampled
							Aug 26, 2005	200512212	0		dry	dry, not sampled
							Mar 27, 2006	200610737	65	0	wet	no odour, discharge clear
							Aug 01, 2006	200611695	0		dry	dry, not sampled
7410-1	S6		AHWL		Harris Road downstream of Money Lake	Saturna Island/ S.G.I.						
							Apr 13, 2000	197912566	65	2	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915712	80	2	wet	no odour, discharge clear
							Sep 13, 2001	197915869	1	126	dry	no odour, discharge clear
							Apr 16, 2002	197916941	40	0	wet	no odour, discharge clear
							Jul 31, 2002	197916942	2	10	dry	no odour, discharge clear
							Apr 14, 2003	197917246	80	18	wet	no odour, discharge clear
							Jul 11, 2003	197917539	5	18	dry	no odour, discharge clear
							Mar 29, 2004	200413084	80	0	wet	no odour, discharge clear
							Jul 21, 2004	200413516	1	0	dry	organic odour, discharge clear
							Apr 20, 2005	200510789	80	0	wet	no odour, discharge clear
							Aug 26, 2005	200511488	2	379	dry	no odour, discharge clear
							Mar 27, 2006	200610746		0	wet	
							Aug 01, 2006	200611679	10	10	dry	no odour, discharge clear
7410-2	S7		AHWL		west side of Money Lake	Saturna Island/ S.G.I.						
							Oct 05, 2000	197910974	0		dry	dry, not sampled
							Mar 14, 2001	197915713	0		wet	dry, not sampled
							Sep 13, 2001	197915856	0		dry	dry, not sampled
							Jul 31, 2002	197916944	0		dry	dry, not sampled
							Jul 11, 2003	197917540	0		dry	dry, not sampled
							Mar 29, 2004	200414164			wet	wet, not sampled
							Jul 21, 2004	200414188	0		dry	dry, not sampled
							Apr 20, 2005	200510787	0		wet	dry, not sampled
							Aug 26, 2005	200511487	0		dry	dry, not sampled
							Mar 27, 2006	200611345	0		wet	dry, not sampled
							Aug 01, 2006	200611696	0		dry	dry, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7410-2A	S7		AHWL	stream	Harris Road - Money Lake (south end)	Saturna Island/ S.G.I.						
							Mar 14, 2001	197915718	4	39	wet	no odour, discharge clear
							Sep 13, 2001	197915857	0		dry	dry, not sampled
							Jul 11, 2003	197917890	0		dry	dry, not sampled
							Mar 29, 2004	200414165			wet	wet, not sampled
							Jul 21, 2004	200414189	0		dry	dry, not sampled
							Apr 20, 2005	200510785	30	0	wet	no odour, discharge clear
							Aug 26, 2005	200511467	1	120	dry	no odour, discharge clear
							Mar 27, 2006	200611347	0		wet	dry, not sampled
Aug 01, 2006	200611697			dry	wet, not sampled							
74102AB					approximately halfway along western side of Money Lake							
							Apr 20, 2005	200511711	0		wet	dry, not sampled
							Aug 26, 2005	200512213	0			dry, not sampled
							Mar 27, 2006	200611346	0		wet	dry, not sampled
							Aug 01, 2006	200611698	0		dry	dry, not sampled
7410-3	S7		AHWL		south end of Money Lake	Saturna Island/ S.G.I.						
							Oct 05, 2000	197912548		28	dry	no odour, discharge clear
							Mar 14, 2001	197915714	3	7	wet	no odour, discharge clear
							Sep 13, 2001	197915858	0		dry	dry, not sampled
							Jul 11, 2003	197917541	0		dry	dry, not sampled
							Mar 29, 2004	200414166	0		wet	dry, not sampled
							Jul 21, 2004	200414190	0		dry	dry, not sampled
							Apr 20, 2005	200512175			wet	wet, not sampled
							Aug 26, 2005	200511470	0		dry	dry, not sampled
							Mar 27, 2006	200610747		20	wet	
Aug 01, 2006	200611699	0		dry	dry, not sampled							
7410-4	S7		AHWL		east side of Money Lake	Saturna Island/ S.G.I.						
							Oct 05, 2000	197915045	0		dry	dry, not sampled
							Mar 14, 2001	197915715	0		wet	dry, not sampled
							Sep 13, 2001	197915993	0		dry	dry, not sampled
							Apr 20, 2005	200510788	0		wet	dry, not sampled
							Aug 26, 2005	200511485	0		dry	dry, not sampled
							Mar 27, 2006	200611348	0		wet	dry, not sampled
							Aug 01, 2006	200611700	0		dry	dry, not sampled
7411	S8		AHWL	sand/cobble	in ditch on south side of Sunset Blvd.	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912567	25	294	wet	no odour, discharge clear
							Aug 10, 2000	197912568	0		dry	dry, not sampled
							Mar 14, 2001	197915716	25	2	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 13, 2001	197915859	0		dry	dry, not sampled
							Apr 16, 2002	197916945	5	46	wet	no odour, discharge clear
							Jul 31, 2002	197916946	0		dry	dry, not sampled
							Apr 20, 2005	200510791	20	39	wet	no odour, discharge clear
							May 11, 2005	200510798	5	13	wet	no odour, discharge clear
							Jul 28, 2005	200510835	0		dry	dry, not sampled
							Dec 21, 2005	200512092	8	600	wet	no odour, discharge clear
							Mar 27, 2006	200610749	1	113	wet	no odour, discharge clear
							Aug 01, 2006	200611701	0		dry	dry, not sampled
7412	S8		AHWL	sand/cobble	ditch on north side of Sunset Blvd.	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912569	6	470	wet	no odour, discharge clear
							Aug 10, 2000	197912570	0		dry	dry, not sampled
							Mar 14, 2001	197915717	2	11	wet	no odour, discharge clear
							Sep 13, 2001	197915860	0		dry	dry, not sampled
							Apr 16, 2002	197916947	1	108	wet	no odour, discharge clear
							Jul 31, 2002	197916948	0		dry	dry, not sampled
							Apr 20, 2005	200510792	12	1600	wet	no odour, discharge clear
							May 11, 2005	200510801	3	2	wet	no odour, discharge clear
							Jul 28, 2005	200510836	0		dry	dry, not sampled
							Dec 21, 2005	200512119	10	727	wet	no odour, discharge clear
							Mar 27, 2006	200610748	3	34	wet	no odour, discharge clear
							Aug 01, 2006	200611702	0		dry	dry, not sampled
7413	S8	stream	AHWL	mud/sand	Lyll Creek, 150 m west of East Point Road	Saturna Island/ S.G.I.						
							Apr 13, 2000	197912571	120	18	wet	no odour, discharge clear
							Aug 10, 2000	197912572	30	370	dry	no odour, discharge clear
							Mar 14, 2001	197915719	250	1	wet	no odour, discharge clear
							Sep 13, 2001	197915870	2	20	dry	no odour, discharge clear
							Apr 16, 2002	197916949	140	131	wet	no odour, discharge clear
							Jul 31, 2002	197916950	15	50	dry	no odour, discharge clear
							Apr 14, 2003	197917250	100	8	wet	no odour, discharge clear
							Jul 11, 2003	197917543	20	600	dry	no odour, discharge clear
							Mar 29, 2004	200413088	100	11	wet	no odour, discharge clear
							Jul 21, 2004	200413514	20	1453	dry	no odour, discharge clear
							May 11, 2005	200510802	100	13	wet	no odour, discharge clear
							Jul 28, 2005	200510828	20	74	dry	no odour, discharge clear
							Aug 26, 2005	200511490	50	14	dry	no odour, discharge clear
							Dec 21, 2005	200512127		19	wet	no odour, discharge clear
							Mar 27, 2006	200610739	65	4	wet	no odour, discharge clear
							Aug 01, 2006	200611675	10	188	dry	no odour, discharge clear
							Aug 14, 2006	200611034	10	118	dry	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7413-1	S8	2200	AHWL	mud/sand	Lyllall Creek, immediately downstream of pipe on East Point Rd.	Saturna Island/ S.G.I.	Apr 13, 2000	197912573	120	4	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915720	250	2	wet	no odour, discharge clear
							Sep 13, 2001	197915871		24	dry	no odour, discharge clear
							Mar 29, 2004	200413087	100	9	wet	no odour, discharge clear
							Jul 21, 2004	200413515	20	1160	dry	no odour, discharge clear
							May 11, 2005	200510803	100	48	wet	no odour, discharge clear
							Aug 26, 2005	200511489	50	63	dry	no odour, discharge clear
							Mar 27, 2006	200610742	80	2	wet	no odour, discharge clear
							Aug 01, 2006	200611676	10	52	dry	no odour, discharge clear
							Aug 14, 2006	200611768	8	190	dry	no odour, discharge clear
7413-2	S9	900	AHWL	mud/sand	Lyllall Creek upstream tributary, immediately north of Saturna Bakery on Naevaez Rd.	Saturna Island/ S.G.I.	Apr 13, 2000	197912574	30	71	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915721	40	1	wet	no odour, discharge clear
							Sep 13, 2001	197915872		800	dry	no odour, discharge clear
							Mar 29, 2004	200413085	60	46	wet	no odour, discharge clear
							Jul 21, 2004	200414191	0		dry	dry, not sampled
							May 11, 2005	200510805	8	380	wet	no odour, discharge clear
							Aug 26, 2005	200512214	0		dry	dry, not sampled
							Dec 21, 2005	200512125	15	46	wet	no odour, discharge clear
							Mar 27, 2006	200610744	75	326	wet	no odour, discharge clear
							Aug 01, 2006	200611677	1	92000	dry	no odour, discharge clear
Aug 14, 2006	200611772		437200	dry	no odour, discharge clear							
7413-3	S9	stream	AHWL	mud/sand	Lyllall Creek, upstream, north of Saturna Bakery on Narvaez Rd., in meadow	Saturna Island/ S.G.I.	Apr 13, 2000	197912575	90	6	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915722	210	1	wet	no odour, discharge clear
							Sep 13, 2001	197915873	2	0	dry	no odour, discharge clear
							Mar 29, 2004	200413086	100	2	wet	no odour, discharge clear
							Jul 21, 2004	200414192			dry	wet, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7413-4	S9	stream	AHWL	mud/sand	Lyllal Creek, upstream, northern tributary, upstream of Saturna Bakery on Narvaez Rd.	Saturna Island/ S.G.I.	Apr 13, 2000	197912576	4	0	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915723	20	1	wet	no odour, discharge clear
7413-5	S9	stream	AHWL	mud/sand	Lyllal Creek, upstream of Saturna Bakery on Narvaez Rd. and northern tributary	Saturna Island/ S.G.I.	Apr 13, 2000	197912577	120	2	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915724	200	2	wet	no odour, discharge clear
							Sep 13, 2001	197915874	2	6	dry	no odour, discharge clear
7413-6	S9	2200	AHWL	mud/sand	Lyllal Creek upstream tributary, across road from rust and yellow coloured house at beginning of park	Saturna Island/ S.G.I.	Apr 13, 2000	197912578	50	0	wet	no odour, discharge clear. Sample collected for upstream investigation
							Mar 14, 2001	197915725	120	1	wet	no odour, discharge clear
							Sep 13, 2001	197915862	0	0	dry	dry, not sampled
7413-7	S9	stream	AHWL	mud/sand	Lyllal Creek, upstream, Narvaez Road, immediately downstream of marsh area	Saturna Island/ S.G.I.	Apr 13, 2000	197912579	70	0	wet	no odour, discharge clear. Sample collected for upstream investigation
							Aug 10, 2000	197917949	0		dry	dry, not sampled
							Mar 14, 2001	197915726	30	6	wet	no odour, discharge clear
							Sep 13, 2001	197915863	0		dry	dry, not sampled
7414	S8		AHWL	mud/sand	Bonnybank Road, on west side of rust coloured house with wood retaining wall	Saturna Island/ S.G.I.	Apr 14, 2000	197912580	1	2	wet	no odour, discharge clear
							Aug 10, 2000	197912581	0		dry	dry, not sampled
							Mar 29, 2004	200414167			wet	wet, not sampled
							Jul 21, 2004	200414193	0		dry	dry, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7415	S10	150	AHWL	sand/cobble	Bonnybank Road, under natural wood-coloured house with green railings	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912582	0		wet	dry, not sampled
							Aug 10, 2000	197912583	0		dry	dry, not sampled
							Mar 29, 2004	200414168	0		wet	dry, not sampled
							Jul 21, 2004	200414194	0		dry	dry, not sampled
							May 11, 2005	200510807	0		wet	dry, not sampled
							Jul 28, 2005	200510839	0		dry	dry, not sampled
7416	S10		AHWL	sand/cobble	directly north of log storage, in small cove, west side of brown house partially hidden in trees	Saturna Island/ S.G.I.						
							Apr 14, 2000	197912584	60	5	wet	no odour, discharge clear
							Aug 10, 2000	197912585	3	148	dry	no odour, discharge clear
							Mar 29, 2004	200414169			wet	wet, not sampled
							Jul 21, 2004	200414195	0		dry	dry, not sampled
							May 11, 2005	200510806	40	8		no odour, discharge clear
							Jul 08, 2005	200510838			dry	wet, not sampled
7600	M1	stream	AHWL	sand	Deacon Creek, southeast side of Village Bay	Mayne Island/ S.G.I.						
							Sep 01, 2000	197916123	3	26	dry	
							Jun 20, 2001	197916122	25	1400	dry	
							Sep 13, 2001	197916120	1	1200	dry	
							Apr 16, 2002	197916957	100	89	wet	no odour, discharge clear
							Sep 19, 2002	197916966	6	170	dry	no odour, discharge clear
							Apr 01, 2004	200413106	100	338	wet	no odour, discharge clear
							Jul 21, 2004	200414196			dry	wet, not sampled
							Apr 06, 2005	200510669	1000	10	wet	no odour, discharge clear
							Sep 01, 2005	200511594	2	1200	dry	no odour, discharge clear
							Dec 05, 2005	200512071	150	14	wet	no odour, discharge clear
							Mar 28, 2006	200610757	85	37	wet	no odour, discharge clear
							Jul 18, 2006	200611407		600	dry	no odour, discharge clear
7610	M3	350	AHWL		Georgia Pt Rd	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917910	0		wet	dry, not sampled
							Jul 23, 2003	197917911	0		dry	dry, not sampled
							Apr 01, 2004	200414170	0		wet	dry, not sampled
							Jul 21, 2004	200414197	0		dry	dry, not sampled
							Apr 06, 2005	200510671	0		wet	dry, not sampled
							Sep 01, 2005	200511556	0		dry	dry, not sampled
7611	M3	750	I		south side of Sunset Pl.	Mayne Island/ S.G.I.						

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Apr 17, 2003	197917912	80	147	wet	no odour, discharge clear
							Jul 23, 2003	197917913	0		dry	dry, not sampled
							Apr 01, 2004	200413095	20	39	wet	no odour, discharge clear
							Jul 21, 2004	200414198	0		dry	dry, not sampled
							Apr 06, 2005	200510667	120	49	wet	no odour, discharge clear
							Sep 01, 2005	200511557	0		dry	dry, not sampled
7612	M3	350	I		approximately half way between Sunset Pl. and Fernhill Rd.	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917914	30	2	wet	no odour, discharge clear
							Jul 23, 2003	197917915	0		dry	dry, not sampled
							Apr 01, 2004	200413096	20	0	wet	no odour, discharge clear
							Jul 21, 2004	200414199	0		dry	dry, not sampled
							Apr 06, 2005	200510668	12	42	wet	no odour, discharge clear
							Sep 01, 2005	200511558	0		dry	dry, not sampled
7613	M3		I		north side of Fernhill Rd.	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917916	70	7	wet	no odour, discharge clear
							Apr 01, 2004	200413097	20	36	wet	no odour, discharge clear
							Jul 21, 2004	200414200	0		dry	dry, not sampled
							Apr 06, 2005	200510661	120	2200	wet	no odour, discharge clear
							Sep 01, 2005	200511560	2	400	dry	no odour, discharge clear
							Dec 05, 2005	200512067	40	32	wet	no odour, discharge clear
							Mar 28, 2006	200610751	50	5200	wet	no odour, discharge clear
							May 23, 2006	200611064	40	465	wet	no odour, discharge clear
							Jul 18, 2006	200611396	15	1600	dry	no odour, discharge clear
7614	M3	150	I		below southern deck of Springwater Lodge	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917919	25	11800	wet	sewage odour, discharge clear
							Jul 23, 2003	197917920	10	35200	dry	sewage odour, discharge clear
							Apr 01, 2004	200413098	20	116800	wet	slight sewage odour, discharge clear
							Jul 21, 2004	200413520	5	2400	dry	no odour, discharge clear
							Apr 06, 2005	200510662	40	7200	wet	no odour, discharge clear
							Sep 01, 2005	200511559	0		dry	dry, not sampled
							Dec 05, 2005	200512066	40	94	wet	no odour, discharge clear
							Mar 28, 2006	200610755		5600	wet	no odour, discharge clear
							May 23, 2006	200611065	35	118400	wet	no odour, discharge clear
							Jul 18, 2006	200611397	30	4400	dry	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7615	M3		AHWL		from concrete retaining wall below 1st cabin at Springwater Lodge	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917921	4	2180	wet	no odour, discharge clear
							Jul 23, 2003	197917922	0		dry	dry, not sampled
							Apr 01, 2004	200413099	1	17	wet	no odour, discharge clear
							Jul 21, 2004	200414201	0		dry	dry, not sampled
							Apr 06, 2005	200510663	40	640	wet	no odour, discharge clear
							Sep 01, 2005	200511561	0		dry	dry, not sampled
							Mar 28, 2006	200610756		780	wet	no odour, discharge clear
Jul 18, 2006	200611409	0		dry	dry, not sampled							
7616	M3	350	AHWL		below 1st brown cabin at Springwater Lodge	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917923	0		wet	dry, not sampled
							Jul 23, 2003	197917924	0		dry	dry, not sampled
							Apr 01, 2004	200414171	0		wet	dry, not sampled
							Jul 21, 2004	200414202	0		dry	dry, not sampled
							Apr 06, 2005	200510664	0		wet	dry, not sampled
							Sep 01, 2005	200511562	0		dry	dry, not sampled
7617	M3	100	AHWL		below cabin #3 and #4 at Springwater Lodge	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917925	30	135	wet	no odour, discharge clear
							Jul 23, 2003	197917926	0		dry	dry, not sampled
							Apr 01, 2004	200413100	10	9	wet	no odour, discharge clear
							Jul 21, 2004	200414203	0		dry	dry, not sampled
							Apr 06, 2005	200510665	8	20	wet	no odour, discharge clear
							Sep 01, 2005	200511563	0		dry	dry, not sampled
7618	M3	100	AHWL		in lower concrete retaining wall below yellow cabins beside Springwater Lodge	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917927	100	10	wet	no odour, discharge clear
							Jul 23, 2003	197917928	0		dry	dry, not sampled
							Apr 01, 2004	200413101	60	2	wet	no odour, discharge clear
							Jul 21, 2004	200414204	0		dry	dry, not sampled
7619	M3	creek	AHWL		approximately 150m west of beach access at Naylor Rd, Miner's Bay	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917929	80	8	wet	no odour, discharge clear
							Jul 23, 2003	197917930	0		dry	dry, not sampled
							Apr 01, 2004	200413102	60	0	wet	no odour, discharge clear
							Jul 21, 2004	200414205	0		dry	dry, not sampled
							Apr 06, 2005	200510670		6	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Sep 01, 2005	200511564	0		dry	dry, not sampled
7620	M3	creek	AHWL		40m east of Victor Rd, Miner's Bay	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917931	5	230	wet	no odour, discharge clear
							Jul 23, 2003	197917932	0		dry	dry, not sampled
							Apr 01, 2004	200413103	5	0	wet	no odour, discharge clear
							Jul 21, 2004	200414206	0		dry	dry, not sampled
							Apr 06, 2005	200510599	450	11	wet	no odour, discharge clear
							Sep 01, 2005	200511565	0		dry	dry, not sampled
7621	M3	creek	AHWL		5m east of Victor Rd, Miner's Bay	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917933	50	14	wet	no odour, discharge clear
							Jul 23, 2003	197917934	0		dry	dry, not sampled
							Apr 01, 2004	200413104	40	0	wet	no odour, discharge clear
							Jul 21, 2004	200414207	0		dry	dry, not sampled
7622	M3	creek	AHWL		363 Maple Drive, Miner's Bay	Mayne Island/ S.G.I.						
							Apr 17, 2003	197917935	25	2	wet	no odour, discharge clear
							Jul 23, 2003	197917936	0		dry	dry, not sampled
							Apr 01, 2004	200413105	20	0	wet	no odour, discharge clear
							Jul 21, 2004	200414208	0		dry	dry, not sampled
7625					north side of Bennett Bay beach access of Wilkes Rd							
							Apr 06, 2005	200510674	1	31	wet	no odour, discharge clear
							Sep 01, 2005	200511551	0		dry	dry, not sampled
							Mar 28, 2006	200611350	0		wet	dry, not sampled
							Jul 18, 2006	200611399	0		dry	dry, not sampled
7626					south side of 787 Wilkes Rd, Bennett Bay							
							Apr 06, 2005	200510675	80	47	wet	no odour, discharge clear
							Sep 01, 2005	200511552	0		dry	dry, not sampled
							Mar 28, 2006	200610769	60	14	wet	no odour, discharge clear
							Jul 18, 2006	200611402	0		dry	dry, not sampled
7627					500 Arbutus Drv, Bennett Bay							
							Apr 06, 2005	200510676	350	2200	wet	no odour, discharge clear
							Sep 01, 2005	200511553	0		dry	dry, not sampled
							Dec 05, 2005	200512215	0		wet	dry, not sampled
							Mar 28, 2006	200610764		130	wet	no odour, discharge clear
							Jul 18, 2006	200611412	0		dry	dry, not sampled

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
7628					south side of 506 Arbutus Drv, Bennett Bay		Apr 06, 2005	200510678	2	165	wet	no odour, discharge clear
							Sep 01, 2005	200511554	0		dry	dry, not sampled
							Mar 28, 2006	200610763	1	282	wet	no odour, discharge clear
							Jul 18, 2006	200611398	1	210	dry	no odour, discharge clear
7630	M4				foot of Curlew View Rd.	Mayne Island/ S.G.I.	Jul 23, 2003	197917938	0		dry	dry, not sampled
							Apr 01, 2004	200414172	0		wet	dry, not sampled
							Jul 21, 2004	200414209	0		dry	dry, not sampled
7631	M4	stream	AHWL		Steward Rd	Mayne Island/ S.G.I.	Apr 17, 2003	197917939	15	2	wet	no odour, discharge clear
							Jul 23, 2003	197917940	0		dry	dry, not sampled
							Apr 01, 2004	200413089	20	6	wet	no odour, discharge clear
							Jul 21, 2004	200414210	0		dry	dry, not sampled
7632	M4	stream	AHWL		Horton Bay Rd.	Mayne Island/ S.G.I.	Apr 17, 2003	197917941	80	8	wet	no odour, discharge clear
							Jul 23, 2003	197917942	0		dry	dry, not sampled
							Apr 01, 2004	200413093	100	37	wet	no odour, discharge brown
							Jul 21, 2004	200414211			dry	wet, not sampled
7633	M4		AHWL		east end of Horton Bay Rd	Mayne Island/ S.G.I.	Apr 17, 2003	197917943	5	6	wet	no odour, discharge clear
							Apr 01, 2004	200413091	10	0	wet	no odour, discharge clear
							Jul 21, 2004	200414212	0		dry	dry, not sampled
7634	M4	350	AHWL		east end of Horton Bay Rd	Mayne Island/ S.G.I.	Apr 17, 2003	197917945	10	4	wet	no odour, discharge clear
							Apr 01, 2004	200413090	20	0	wet	no odour, discharge clear
							Jul 21, 2004	200414213	0		dry	dry, not sampled
7635	M4		AHWL		east end of Horton Bay Rd	Mayne Island/ S.G.I.	Apr 17, 2003	197917947	10	3	wet	no odour, discharge clear
							Apr 01, 2004	200413092	30	0	wet	no odour, discharge clear
							Jul 21, 2004	200414214	0		dry	dry, not sampled
7800	G4	stream	AHWL		Georgeson Creek	Galiano Island/ S.G.I.	Apr 16, 2002	197916964		325	wet	no odour, discharge clear
							Jul 30, 2002	197916965	0		dry	dry, not sampled
							Apr 10, 2003	197917252		57	wet	no odour, discharge clear
							Jul 14, 2003	197917544	5	2200	dry	no odour, discharge clear
							Mar 22, 2004	200412983	90	14	wet	no odour, discharge clear

* BLWL denotes at or below water level, I denotes intertidal and AHWL denotes above water level.

Stormwater Quality Report

Fecal Coliform and Flow Data (for the period of Jan 01, 1998 to Dec 31, 2006)

CRD Outlet No.	Figure No.	Outlet Diameter (mm)	*Point of Disch	Nature of Shoreline	Location	Contributors	Date Visited	Sample No	Flow Rate L/min	Fecal Coliform Per/100mL	Season	Comments
							Jul 15, 2004	200414215	0		dry	dry, not sampled
							Apr 06, 2005	200510672	600	2000	wet	no odour, discharge clear
							Aug 31, 2005	200511555			dry	wet, not sampled
							Dec 15, 2005	200512089	80	5	wet	no odour, discharge clear
							Mar 28, 2006	200610607	80	107	wet	no odour, discharge clear
							Sep 29, 2006	200612223	0		dry	dry, not sampled
7810	G4	stream	AHWL		Taylor Cove	Galiano Island/ S.G.I.						
							Mar 22, 2004	200414173	0		wet	dry, not sampled
							Jul 15, 2004	200414216	0		dry	dry, not sampled
							Mar 28, 2006	200610617	50	20	wet	no odour, discharge clear
							Sep 29, 2006	200612222	0		dry	dry, not sampled
7820	G3	stream	AHWL		end of Highview Rd in Whaler Bay	Galiano Island/ S.G.I.						
							Apr 10, 2003	197917254	100	14	wet	no odour, discharge clear
							Mar 22, 2004	200414174			wet	could not access, not sampled
							Jul 15, 2004	200414217	0		dry	dry, not sampled
							Apr 06, 2005	200510598		56	wet	
							Aug 31, 2005	200511715	0		dry	dry, not sampled
							Mar 28, 2006	200610753	75	15	wet	no odour, discharge clear
							Sep 29, 2006	200612224	0		dry	dry, not sampled